

International Aero Engines

INFORMATION BULLETIN

STANDARD PRACTICES - ENGINE - INFORMATION - TO ANNOUNCE THE AVAILABILITY OF PARTS TO PERMIT THE REPAIR OF FUEL TUBE ASSEMBLIES - NOT APPLICABLE - MOD.ENG-70-0018

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1

B. Reason

To announce the availability of newly released Repair Parts.

C. <u>Compliance</u>

For information only.

D. Approval

The part number transactions shown under the MATERIAL INFORMATION portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. <u>References</u>

(1) Internal Reference No.

EC89VR884

EC89VE885

F. General Information

New Repair Scheme being introduced into the V2500 Engine Manual which requires Special Repair Parts for its accomplishment.

ATA Ref No.	Repair Scheme	Title
73-11-49	VRS6223	Fuel tubes - Engine - Replace damaged tube lengths
73-11-49	VRS6224	Fuel tubes - Engine - Replace damaged tube lengths

(For Special Repair Parts required, see 'Material Information'.)

V2500-ENG-70-0018

International Aero Engines

INFORMATION BULLETIN

G. <u>Material Information</u>

New		Est'd		Old	
Part No.		Unit		Part No.	Instructions
(ATA No.)	Qty	Price (\$)	Keyword	(IPC No.)	Disposition

(1) The following Special Repair Parts are required to accomplish Repair VRS6223:

LK46450	1	-	Sleeve	-	(A)
LK46451	1	-	Sleeve	_	(A)
LK46452	1	_	Sleeve	_	(A)

(2) The following Special Repair Parts are required to accomplish Repair VRS6224:

LK64923	1	-	Tube	-	(A)
LK64924	1	-	Tube	_	(A)
LK64926	1	-	Tube	-	(A)
LK17171	1	-	Tee-Piece	-	(A)
LK17173	1	-	Ring	-	(A)
LK17175	1	-	Tee-Piece	-	(A)

H. Supply Status Code Statements

(A) New part number is currently available.

NOTE: The estimated 1991 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.