



STANDARD PRACTICES - ENGINE - INFORMATION - AIR - TO ANNOUNCE THE AVAILABILITY OF A  
 REPAIR PART FOR THE HPC STAGE 7 BLEED VALVE DUCT AND SEAL ASSEMBLY - NOT APPLICABLE -  
 MOD.ENG-70-0093

1. Planning Information

A. Effectivity

- (1) Aircraft: Airbus A320
- (2) Engine: V2500-A1

B. Reason

To announce the availability of a newly released Repair Part.

C. Compliance

For information only.

D. Approval

The part number transaction shown under the MATERIAL INFORMATION portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and is FAA-APPROVED for the Engine Model listed.

E. References

- (1) Internal Reference No.  
 EC87VR775

F. General Information

New Repair Scheme being introduced into the V2500 Engine Manual which requires Special Repair Parts for its accomplishment:

ATA No.	Repair Scheme	Title
-----		
72-32-52	VRS6046	H.P. compressor stage 7 RH lower air seal assembly - Replace the seal

(For Special Repair Part required, see 'Material Information')



International Aero Engines  
INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
------------------------------	-----	-----------------------------	---------	------------------------------	------------------

---

The following Special Repair Part is required to accomplish Repair VRS6046:

AS16532	16	-	Rivet, solid, csk.	-	(A)
---------	----	---	--------------------	---	-----

H. Supply Status Code Statements

(A) New part number is currently available.

NOTE: The estimated 1991 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult the IAE Price Catalogue or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain

V2500-ENG-70-0093