



STANDARD PRACTICES - ENGINE - INFORMATION - TO ANNOUNCE THE AVAILABILITY OF PARTS TO  
PERMIT THE REPAIR OF TE HP COMPRESSOR SEAL RING CARRIER ASSEMBLIES - NOT APPLICABLE -  
MOD.ENG-70-0221

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine : V2500-A1

B. Reason

To announce the availability of newly released Repair Parts.

C. Compliance

For information only.

D. Approval

The part number transactions shown under the MATERIAL INFORMATION portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

(1) Internal Reference No.

EC90VR755

F. General Information

New Repair Scheme being introduced into the V2500 Engine Manual which requires Special Repair Parts for its accomplishment.

ATA Ref No. -----	Repair Scheme -----	Title -----
72-32-23	VRS6113	HP Compressor - Seal Ring Carrier Assembly - Replace The Seal Ring

(For Special Repair Parts required, see 'Material Information'.)

V2500-ENG-70-0221

Aug.27/93

Page 1 of 2



International Aero Engines  
INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
------------------------------	-----	-----------------------------	---------	------------------------------	------------------

---

The following Special Repair Parts are required to accomplish Repair Scheme VRS6113.

6A1450 (72-32-23)	1	255	Retainer, Ring Seal	- (01-724)	(A)
UP10892 (72-32-23)	1	405	Ring, Seal	- (01-726)	(A)

H. Supply Status Code Statements

(A) New part number is currently available.

NOTE: The estimated 1993 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain

V2500-ENG-70-0221