

# International Aero Engines

# **INFORMATION BULLETIN**

<u>STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - INLET CONE ASSEMBLY - TO ANNOUNCE</u>
<u>THE AVAILABILITY OF INLET CONE REPAIR PARTS - NOT APPLICABLE - MOD.ENG-70-0263</u>

#### 1. Planning Information

#### A. Effectivity

(1) Aircraft: (a) Airbus A320/A321

(2) Engine: (a) V2500-A1

#### B. Reason

To announce the availability of a newly released repair part.

# C. <u>Compliance</u>

For information only.

# D. Approval

(1) The part number transaction shown under the Material Information portion in paragraph G, has been shown to comply with the applicable Federal Aviation Regulation and are FAA-APPROVED for the Engine Model listed.

#### E. <u>References</u>

(1) Internal Reference No.

ECM86VJ037-04

ECM86VJ037-05

#### F. General Information

(1) The Repair Scheme has been introduced into the V2500-A1 Engine Manual which requires Special Repair Parts for its accomplishment:

ATA No.	Repair Scheme	Title
72–38–11	VRS1462	Replace the inlet cone tip of the inlet cone assembly, Repair 002.

(For Special Repair Part required, See 'Material Information')

(2) Other publications affected

V2500-ENG-70-0263



# International Aero Engines

# **INFORMATION BULLETIN**

(a) The V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-38-11, Figure 01.

# G. Material Information

New		Est'd	Old	
Part No.		Unit	Part No.	Supply
(ATA No.)	Qty	Price (\$) Keyword	(IPC No.)	Status

(1) The following Repair Part is required to accomplish Repair No. VRS1462

5A0005	1	39.70	Holder, Tip		(A)
(72 - 38 - 11)			Nose Cone	(01-230)	

# H. Supply Status Code Statement:

(A) New part is currently available.

NOTE: The estimated 1995 unit prices shown is provided for planning purposes only and does not constitute a firm quotation. Contact IAE's Spare Parts Sales Department for information concerning firm prices.

V2500-ENG-70-0263