



International Aero Engines INFORMATION BULLETIN

INFORMATION - LP TURBINE - TO ANNOUNCE AVAILABILITY OF
AN ADDITIONAL ADJUSTMENT RING WITH DIFFERENT THICKNESS

MODEL APPLICATION

V2500-A1
V2522-A5
V2524-A5
V2527-A5
V2527E-A5
V2530-A5
V2533-A5
V2525-D5
V2528-D5

BULLETIN INDEX LOCATOR

72-00-00

Compliance Category Code

Not applicable

Internal Reference No.

EC98VJ019

Mar.31/00

V2500-ENG-70-0719

Page 1 of 4



International Aero Engines INFORMATION BULLETIN

INFORMATION - LP TURBINE - TO ANNOUNCE AVAILABILITY OF
AN ADDITIONAL ADJUSTMENT RING WITH DIFFERENT THICKNESS

A. Effectivity

(1) Aircraft:

- (a) Airbus A319
- (b) Airbus A320
- (c) Airbus A321
- (d) Boeing-Douglas Product Division MD-90

(2) Engine:

- (a) V2500-A1 Engines
- (b) V2522-A5 Engines
- (c) V2524-A5 Engines
- (d) V2527-A5 Engines
- (e) V2527E-A5 Engines
- (f) V2530-A5 Engines
- (g) V2533-A5 Engines
- (h) V2525-D5 Engines
- (i) V2528-D5 Engines

B. Reason


To announce availability of the additional adjustment ring with different thickness. Recent statistical assessment indicates that about 4 % of engines used the thickest adjusting washer with a machining process. An additional adjusting ring with a fixed thickness can almost eliminate the utilization of this thickest adjusting ring and the resultant machining process.

C. Compliance

This Bulletin is introduced for record purpose only.

D. Approval

The part number transaction are given in the Material Information section of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine models listed.



International Aero Engines INFORMATION BULLETIN

E. Reference

IAE Engineering Change No.98VJ019

F. General Information

- (1) The Material Information section of this Service Bulletin gives the latest information about the availability of the affected parts.
- (2) The adjustment ring have thickness of 0.5118 inch (13,00 mm).
- (3) V2500 Engine Illustrated Parts Catalogs, Chapter/Section 72-00-50, will be revised to incorporate the new part number.
- (4) V2500 Engine Manual (E-V2500-1IA), Chapter/Section 72-00-50, Installation-03 will be revised to incorporate the new Fig/Item number.
- (5) V2500 Engine Manual (E-V2500-3IA), Chapter/Section 72-00-50, Installation-02 will be revised to incorporate the new Fig/Item number.
- (6) V2500 Engine Manual (E-V2500-1IA and 3IA), Chapter/Section 72-00-50, Cleaning-04, Config-01 will be revised to incorporate the new part number.
- (7) V2500 Engine Manual (E-V2500-1IA and 3IA), Chapter/Section 72-00-50, Inspection/Check-03, Config-01 will be revised to incorporate the new part number.
- (8) V2500 Engine Manual (E-V2500-1IA and 3IA), Chapter/Section 72-00-50, Repair 004, VRS1121 will be revised to incorporate the new part number.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price(\$)	Keyword	Old Part No. (IPC No.)	Instruction/ Disposition
5A1839 (72-00-50)	1		.Ring, Adjust	- (01-309)	(A)

NOTE: The unit prices, if shown, are an estimate and they are given for the purposes of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's Spare parts Sales Department.



International Aero Engines INFORMATION BULLETIN

H. Instruction/Disposition Code Statements:

(A) New part is currently available.