

SERVICE BULLETIN

ENGINE - H.P. COMPRESSOR STAGE 7 AND 8 ROTOR PATHS WITH REDUCED SPRAYED THICKNESS ABRADABLE LININGS - CATEGORY CODE 6 - MOD.ENG-72-0030

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500 A1 Engines prior to Serial No.V0071, excluding V0061,

V0060, V0038 and V0042 as delivered.

B. Reason

(1) Condition

The abradable lining on the stage 8 rotor has become detached from the parent ring.

(2) Background

Boroscope examination of the rotor paths and subsequent strip of engine V0021 showed that the abradable lining on the stage 8 rotor path has become detached from the parent ring over an arc of 270 degrees.

Laboratory investigation concluded that excessive sprayed thickness of lining material was the cause of this separation, and recommended a reduction in the sprayed thickness. Although there has been no evidence of lining separation occurring in the stage 7 rotor path, this modification is applied to the stage 7 as it has the same sprayed lining material as the stage 8 rotor path.


(3) Objective

The changes in configuration recommended in this Service Bulletin are designed to maintain the reliability of the stage 7 and stage 8 rotor paths of the HP compressor.

(4) Substantiation

Engineering assessment has concluded that the changes introduced by this modification will reduce the level of internal stress at the lining material to parent metal bond joint, which has resulted in tensile stress at the bond interface and subsequent failure of the bond.

(5) Effects of Bulletin on:



SERVICE BULLETIN

Removal/Installation Disassembly/Assembly Cleaning Inspection/Check Repair Testing Not affected Not affected Not affected Affected (See Supplemental Information) Not affected Not affected

- (6) Supplemental Information
 - (a) The assembly and disassembly of the Post-Service Bulletin configuration does not change.

C. <u>Description</u>

- (1) New rotor paths are introduced at stage 7 and 8 of the HP compressor.
- (2) The changes introduced by this Service Bulletin are as follows:
 - (a) Stage 7 has a total lining thickness, as sprayed and including the bonding coat of 0.048 to 0.058in. (1,21 to 1,47 mm).
 - (b) Stage 8 has a total lining thickness, as sprayed and including the bonding coat of 0.055 to 0.065in. (1,39 to 1,65 mm).
- (3) Existing HP compressor cases can be reworked, see Figure 1 to 4.

D. <u>Approval</u>

The part number changes and/or part modifications described in Sections 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA - APPROVED for the Engine Model listed.

E. Compliance

Category Code 6

Accomplish when the sub-assembly (ie modules, accessories, components, build groups) is disassembled sufficiently to afford access to the affected part and all affected spare parts.

F. Manpower

Estimated manhours to incorporate the full intent of this bulletin:

Venue Estimated Manhours

- (1) In service Not applicable
- (2) At overhaul 9 hours



SERVICE BULLETIN

To accomplish rework and re-ident of the Stage 7 and 8 Rotor path ring.

- G. Material Price and Availability
 - (1) Modification kit not required.
 - (2) See Material Information section for prices and availability of future spares.
- H. Tooling Price and Availability

The following tools are required to accomplish Sub-division 2 of this Service Bulletin:

Tool No.	Qty	Description	Function	Avail.
3R18570	1	Turning fixture	Location of workpiece	(1)
3R18232	1	Lifting tool	Location of turning fixture	(1)

(1) Indicates that tool aperture cards are currently available from I.A.E.

- I. Weight and Balance
 - (1) Weight change None
 - (2) Moment arm No effect
 - (3) Datum Engine front mount centreline (Power Plant Station (PPS) 100)
- J. Electrical Load Data

This Service Bulletin has no effect on the aircraft electrical loads.


- K. <u>References</u>
 - (1) Internal Reference No.

EC89VR005

(2) Other References

V2500 Engine Manual 72-41-00 and 72-41-20, Assembly.

- L. Other Publications Affected
 - (1) V2500 Illustrated Parts Catalog, 72-41-21.
 - (2) V2500 Engine Manual, 72-41-00, Assembly and Disassembly, 72-41-20, Assembly and 72-41-21, Cleaning and Inspection/Check.



2. Accomplishment Instructions

A. Rework Instructions

(1) Rework 6A3651 and 6A6352 stage 7 and 8 rotor paths with reduced sprayed thickness abradable linings. Refer to 72-41-21, Fig/Item No's 03-450 and 03-600) as follows:

Consumable Materials

CoMat 02-001 CoMat 02-006 CoMat 05-001 CoMat 05-003 CoMat 03-038 CoMat 03-089 CoMat 03-090 CoMat 03-036	Masking tape Masking tape Abrasive Abrasive Metco 450 NS) Amdry 956) Metco 450 NS) Alternative Metco 405 NS)
CoMat 03-235 CoMat 02-236	Amdry 357) Metco 54 NS) Alternative
CoMat 07-035 Type A CoMat 07-036 Type A	Corrosion Resistant Coating) Alternative Aluminium High Heat Res.) Paint)
CoMat 07-037 CoMat 07-038	Touch Up Coating) Alternative Touch Up Coating)

Procedure

Supplementary Information

and lifting tool 3R18232.

Use lathe, turning fixture 3R18570

- (a) Assemble fixture on machine.
- Set to machine correctly. (b) Assemble rotor path ring onto turning
- fixture and machine to remove abradable lining.
- (c) Remove remaining lining material.
- (d) Chemically remove remaining lining material. Alternative to (c).
- (e) Abrasive blast. Alternative to (c).

Machine to remove lining. Figure 2 or 4 You must not remove material from the

Hand dress.

ring.

Use air operated grinder with rotary burr or suitable alternative. You must not remove material from ring. Refer to Standard Practices Manual, TASK 70-33-63.

Refer to SPM, TASK 70-12-02. Use CoMat 05-003.



SERVICE BULLETIN

(f) Visually/dimensionally Refer to SPM, TASK 70-34-01. Figure 2 or 4.

(g) Do a penetrant crack test. Refer to SPM, TASK 70-23-01 or 03.

(h) Remove grease. Refer to SPM, TASK 70-11-01.

(i) Put covers over areas not Use CoMat O2-001 or locally to be sprayed. manufactured fixture.

(j) Abrasive blast. Refer to SPM, TASK 70-12-02.

Use CoMat 05-001.

Remove masks when blasting is completed. Do not touch area

which has been blasted.

(k) Put covers over areas Use CoMat 02-006 or locally not to be sprayed. manufactured fixture.

(l) Apply bond coat. Refer to SPM, TASK 70-34-01. For powder feed plasma spray gun

use CoMat 03-038 or CoMat 03-089

or CoMat 03-090.

Alternatively for wire feed

combustion spray use CoMat 03-036. Preheat seal ring to 105 deg C to 125 deg C. Use spray gun with

powder feed off.

Bond Coat

(m) Apply abradable lining. Refer to SPM, TASK 70-34-01.

Figure 3 or 5. Use CoMat 03-235 or CoMat 03-236. Remove covers when

Abradable Coat

spraying is completed.

Spray Data

Parameters for Metco 3MB powder feed plasma spray gun

Gun	Metco 3MB	Metco 3MB
Cathode	3M11A	3M11A
Nozzle	3M7AGH	3M7AGH
Distribution ring	3A275A	3A275A
Powder port	No 2	No 1
Primary gas flow tube	2M164	2M164
Secondary gas flow tube	2M166	2M166

Gases:



SERVICE BULLETIN

Arc primaryArgonArgonPressure100 p.s.i.100 p.s.i.Arc secondaryHydrogenHydrogenPressure50 p.s.i.50 p.s.i.

Power Supply:

Operating Conditions:

Gas flow Metco flow meter setting:

Primary 80 150 Secondary 15 5

Power settings:

Current 500 amps 500 amps Voltage 61-75 volts 55-70 volts

Powder control:

Spray distance

Carrier gas flow meter 37 37

setting

Powder feed rate 67-69 gms/min 49-50 gms/min Spray distance 4-7 ins. 4-6 ins.

Spray thickness 0.004-0.007ins. See illustrations

Bond Coat

Parameters for Plasma Technik plasma burner

Plasma Technik Plasma Technik Gun F4 F4 Nozzle dia 6,0 mm. 6,0 mm. Powder injector dia 1,8 mm. 1,8 mm. Injector angle 90 degrees +15 degrees Powder gauge 6,0 mm. 6,0 mm. Argon Argon Arc primary gas Flow rate litres/min 55 38 Arc secondary gas Hydrogen Hydrogen Flow rate litres/min 9.5 12 Power supply 600 amps 500 amps Carrier gas litres/min 3.5 5.0 Powder spreader type L L Powder feed rate grams/min 50 35

Spray thickness 0.004-0.007 ins. See illustrations


5.5 ins.

Parameters for Metco 10E or 12E wire feed combustion spray gun

V2500-ENG-72-0030

6.7 ins.

Abradable Coat



SERVICE BULLETIN

Bond Coat

Gun Metco 10E or 12E*

Nozzle diameter 3,0 mm.

Air cap C

Gas pressures

Acetylene 10 p.s.i. 0xygen 30 p.s.i.

Air 65 p.s.i. or 75 p.s.i.*

Gas flows Metco flow meter setting

Acetylene 33 Oxygen 46

Air 49 or 65*
Spray distance 5-7 ins.
Wire diameter 0.125 ins.
Deposition per pass 0.001 ins.

Spray thickness 0.004-0.007 ins.

Procedure Supplementary Information

(n) Visually inspect sprayed Refer to SPM, TASK 70-34-01.

coating on ring.

(o) Make a dimensional Figure 3 or 5.

inspection.

(p) Hardness test sprayed Refer to SPM, TASK 70-34-01. coating. Average hardness must be 70-80

R15Y outer limits 65 min. 85 max.

(q) Apply high heat resisting Refer to SPM, TASK 70-38-21

enamel as necessary. Figure 3 or 5.

Use CoMat 07-035 Type A or CoMat 07-036 Type A, CoMat 07-037 or

CoMat 07-038.


(r) Re-identify with new Old Part Number New Part Number

part number vibro-

engrave adjacent to 6A3651 6A4101 existing part number 6A3652 6A4102


2) Rework 6A3652, HP compressor stage 8 rotor path ring in accordance with Repair Scheme VRS6O2O and re-identify 6A41O2.

B. Assembly Instructions





- (1) New 6A4101 and 6A4102 HP compressor with reworked stage 7 and 8 rotor paths are interchangeable with in use HP compressor cases.
- (2) Assemble new 6A4101 and 6A4102 HP compressor case with reworked stage 7 and 8 rotor path linings in accordance with approved procedures. Engine Manual, 72-41-00 and 72-41-20, Assembly.






Location of H.P. compressor stages 7 and 8 rotor paths Fig.1 $\,$







THE REMOVAL OF THE SEAL MATERIAL FROM THE STAGE 7 COMPRESSOR ROTOR PATH

MACHINE WHERE SHOWN

✓


REMOVE THE SHARP EDGES 0.012 ± 0.008 in $(0.30 \pm 0.20$ mm)

MACHINED SURFACE FINISH TO BE 250 MICROINCHES (6,30 MICROMETRES)

GEOMETRIC SYMBOLS CONFORM TO ISO R1101-1969.

Modification of HP Compressor Stage 7 Rotor Path Fig.2





THE REPLACEMENT OF THE SEAL MATERIAL IN THE STAGE 7 COMPRESSOR ROTOR PATH

MAKE GOOD ALL DAMAGE TO ENAMEL AS GIVEN IN TEXT. DO NOT LET THE ENAMEL TOUCH THE AREAS SPECIFIED AB OR GO INTO THE HOLES.


APPLY THE SEAL MATERIAL AS GIVEN IN THE TEXT ON THE AREA SPECIFIED AC. NOTE AD:-

IT IS PERMITTED TO MAKE SURFACE NOT SMOOTH.

Modification of HP Compressor Stage 7 Rotor Path Abradable Lining Fig.3


V2500-ENG-72-0030

ded0000498



THE REMOVAL OF THE SEAL MATERIAL FROM THE STAGE8 COMPRESSOR ROTOR PATH.





THE REPLACEMENT OF THE SEAL MATERIAL IN THE STAGE 8 COMPRESSOR ROTOR PATH.


MAKE GOOD ALL DAMAGE TO ENAMEL AS GIVEN IN TEXT.

DO NOT LET THE ENAMEL TOUCH THE AREAS SPECIFIED AB OR GO INTO THE HOLES.

APPLY THE SEAL MATERIAL AS GIVEN IN THE TEXT ON THE AREA SPECIFIED AC. NOTE AD:-

IT IS PERMITTED TO MAKE THE SURFACE NOT SMOOTH.

Modification of HP Compressor Stage 8 Rotor Path Abradable Lining Fig.5



SERVICE BULLETIN

3. Material Information

NEW EST'D OLD

PART NO. UNIT PART NO. INSTRUCTIONS (ATA NO.) QTY PRICE (\$) KEYWORD (IPC NO.) DISPOSITION

Applicability: For each V2500 Engine to incorporate Sub-division 1 of this

Bulletin.

A. Kits associated with the Bulletin:

None

B. Parts affected by this Bulletin:

6A4101 (72-41-21)	1	1913,00	Ring Stag	e 7	Rotor	Path	6A3651 (03-450)	
6A4102	1	1913,00	Ring Stag	e 8	Rotor	Path	6A3652 (03-600)	

C. Instruction/Disposition Code Statements:

- (2D) Old part can be reworked and re-identified to the new part number
- (S1) Old and new parts may be freely interchanged
- (A) New part currently available
- (B) Old part no longer available for sale

NOTE: The estimated 1989 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Contact IAE Spare Parts Sales Department for information concerning firm prices.