

International Aero Engines

SERVICE BULLETIN

ENGINE - H.P. COMPRESSOR DISCS - COMPRESSOR STAGE 3 TO 8 ROTOR DRUM ASSEMBLY WITH SPACERS IN TRIPLE MELT TITANIUM - CATEGORY CODE 7 - MOD.ENG-72-0130

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1 Engines prior to Serial No.V0246*

* The serial number data shown is of a preliminary nature and is provided for advance planning only. A future revision to this service bulletin will confirm final serial number effectivity.

B. Reason

(1) Condition

The H.P. compressor stage 3 to 8 rotor drum assembly is currently supplied with spacers in double melt titanium.

(2) Background

As part of a general process of product improvement the new HP compressor stage 3 to 8 rotor drum assembly is supplied with spacers in triple metal titanium.

(3) Objective

Incorporation of this Service Bulletin is designed to maintain engine reliability.

(4) Substantiation


Investigation by the Stress Department has shown that the cleared life of the rotor drum assembly is unaffected by the change.

(5) Effect of Bulletin on Workshop Procedures

Removal/Installation Not affected Disassembly/Assembly Not affected Cleaning Not affected Inspection/Check Not affected Repair Not affected Testing Not affected

(6) Supplemental Information

V2500-ENG-72-0130



SERVICE BULLETIN

None

C. <u>Description</u>

(1) The changes introduced by this Service Bulletin are as follows:

Spacers between HP compressor rotor discs stages 3 to 4, 4 to 5 and 5 to 6 which are presently manufactured in double melt titanium will now be manufactured in triple melt titanium.

D. Approval

The part number changes and/or part modifications decribed in Section 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation regulations and are FAA-APPROVED for the Engine Model listed.

E. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

F. Manpower

Estimated manhours to incorporate the full intent of this Bulletin:

Venue Estimated Manhours

(1) In Service Not applicable

(2) At Overhaul Not affected

G. Material - Price and Availability

- (1) Modification kit not required
- (2) See "Material Information" section for prices and availability of future spares.

H. Tooling - Price and Availability

Special tools are not required.

I. Weight and Balance

- (1) Weight change None
- (2) Moment arm No effect

V2500-ENG-72-0130



International Aero Engines

SERVICE BULLETIN

(3) Datum Engine front mount centreline (Power Plant Station - PPS 100)

J. Electrical Load Data

This Service Bulletin has no effect on the aircraft electrical load.

K. References

(1) Internal Reference No.

EC91VR004

(2) Other References

V2500 Engine Manual, 72-41-10 Assembly

L. Other Publications Affected

- (1) Repair schemes VRS 6006, 6007, 6047, 6048, 6122, 6129, 6130, 6132, 6149, 6154, 6220 and 6487 are also applicable to the new part number being introduced by this Service Bulletin.
- (2) V2500 Engine Manual, 72-41-11 Cleaning -00, Cleaning -01 (Config 2), Inspection/Check -00 and Inspection/Check -01 (Config 2).




SERVICE BULLETIN

2. Accomplishment Instructions

A. Rework Instructions

Not applicable

- B. Assembly Instructions
 - (1) New 6A4189 HP compressor disc assembly is interchangeable with in use HP compressor disc assemblies.
 - (2) Assemble new 6A4189 HP compressor disc assembly by use of approved procedures, Engine Manual, 72-41-10 Assembly.
- C. Recording Instructions
 - (1) A record of accomplishment is necessary.



SERVICE BULLETIN

3. Material Information

Applicability: For each V2500 Engine to incorporate this Bulletin.

A. <u>Kits associated with this Bulletin:</u>

None

B. Parts affected by this Bulletin:

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword		Instructions Disposition
6A4189 (72-41-11)	1		Disc assembly, stages 3 to 8 - H.P. compressor		(S1)(A)(B)
				or 6A3934 (01-200)	

C. <u>Instruction/Disposition Code Statements:</u>

- (S1) Old and new parts are freely and fully interchangeable
- (A) New part is currently available for sale.
- (B) Old part is no longer available.

NOTE: The estimated 1992 unit prices are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

