

SERVICE BULLETIN

<u>ENGINE - LP COMPRESSOR - INTRODUCE A REWORK PROCEDURE ON THE FAN FRAME ASSEMBLY - CATEGORY CODE 8 - MOD.ENG-72-0286</u>

1. Planning Information

A. Effectivity

(1) Aircraft: (a) Airbus A320

(2) Engine: (a) V2500-A1 Engines prior to serial number V0305.

B. Concurrent Requirements

None

C. Reason

(1) Condition

The existing IAE service bulletin No. V2500-ENG-72-0150 does not have rework procedure of the fan frame assembly. The rework is required to change secured method of mount tube stopper from rivet type to bolt type on the fan frame assembly.

(2) Background

The existing mounting tube stopper has shown damage at some locations. The operators wish to accomplish the partial application of the IAE service bulletin No. V2500-ENG-72-0150, although the operators can not accomplish the above bulletin completely.


(3) Objective

To introduce rework procedure of the fan frame assembly for the strength improvement of mount tube stopper.

(4) Substantiation

Analytically substantiated.

(5) Effects of Bulletin on Workshop Procedures:



SERVICE BULLETIN

Removal/Installation
Disassembly/Assembly
Cleaning
Inspection/Check
Repair
Testing

Not affected Affected (See Supplemental Information) Not affected Not affected Not affected Not affected

- (6) Supplemental Information
 - (a) The Disassembly/Assembly of the post-service bulletin configuration requires instructions for mount tube stopper.

D. <u>Description</u>

(1) The new mount tube stopper which is secured by the bolts and nuts are introduced (See Figure 2).

These parts are exactly same as the parts introduced by IAE Service Bulletin No. V2500-ENG-72-0150.

- (2) Rework procedure of fan frame is introduced to enlarge the current two rivet holes to bolt holes (See Figure 1).
- (3) For relationship with other Service Bulletins, See Figure 3 "Family Tree Chart".

E. Approval

The part number changes and part modifications described in sections 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

F. Compliance

Category Code 8

Accomplish based upon experience with the prior configuration.

G. Manpower

Estimated Manhours to incorporate the full intent of this Bulletin:

Venue Estimated Manhours

- (1) In service Not applicable
- (2) Rework of Fan Frame Assembly



SERVICE BULLETIN

(a)	To replace mount tube stopper	 45 minutes
(b)	Crack Test	 20 minutes
(c)	Vibro etch new part number	
	on fan frame	 03 minutes

Total 1 hour 08 minutes

H. Material - Price and Availability

- (1) Modification kit is not required.
- (2) See "Material Information" section for prices and availability of future spares.

I. Tooling - Price and availability

Special tools are not required to accomplish of this Bulletin.

J. Weight and Balance

(1)	Weight	change		None
-----	--------	--------	--	------

(2) Moment arm No effect

(3) Datum Engine front mount centreline (Power Plant Station (PPS) 100)

K. Electrical Load Data

This SB has no effect on the aircraft electrical load.

L. References

(1) Internal Reference No.

EC97VJ016

(2) Other References

V2500 Engine Illustrated Parts Catalog

V2500 Engine Manual

V2500 Standard Practices/Processes Manual

IAE Service Bulletin No. V2500-ENG-70-0002

IAE Service Bulletin No. V2500-ENG-72-0009

IAE Service Bulletin No. V2500-ENG-72-0077

SERVICE BULLETIN

IAE Service Bulletin No. V2500-ENG-72-0051

IAE Service Bulletin No. V2500-ENG-72-0160

IAE Service Bulletin No. V2500-ENG-72-0132

IAE Service Bulletin No. V2500-ENG-72-0150

IAE Service Bulletin No. V2500-ENG-70-0266

IAE Service Bulletin No. V2500-ENG-72-0211

M. Other publications affected

- (1) V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-32-03
- (2) V2500 Engine Manual, Chapter/Section 72-32-00, Disassembly-02 and Assembly-14, CONFIG-1



2. Accomplishment Instructions

- A. Rework Instructions
 - (1) Rework and reidentify the following Fan Frame Assembly (Ref. 72-32-03, Fig/Item No. 03-100);

(a)	Old Part No.	New Part No.		
	(Before rework)	(After rework)		
	5A6592	5A1763		
	5A0256	5A1764		
	5A6596	5A1765		
	5A0349	5A1766		
	5A0856	5A1767		
	5A1047	5A1768		
	5A0362	5A1769		
	5A0364	5A1770		
	5A0363	5A1771		
	5A0366	5A1772		
	5A0365	5A1773		
	5A0407	5A1774		
	5A0401	5A1775		
	5A0405	5A1776		
	5A0403	5A1777		
	5A0409	5A1778		
	5A1167	5A1779		
	5A1049	5A1780		
	5A1064	5A1781		
	5A1062	5A1782		
	5A1068	5A1783		
	5A1066	5A1784		

WARNING: YOU HAVE TO MAKE SURE THE STANDARD PRACTICES/PROCESSES MANUAL (SPM) TASK 70-03-00-100-501, SPECIAL HANDLING OF MATERIALS AND SOLUTIONS-01 BEFORE YOU DO STEP (h) BECAUSE THE PART MATERIAL IS TITANIUM ALLOY.

Procedure

Supplementary Information

- Remove the existing rivets from the fan frame assembly
- (c) Remove the mount tube stopper
- (d) Make sure the drilling position Refer to Figure 1 on the fan frame assembly



SERVICE BULLETIN

(e) Make the diameter of the rivet
hole larger at two positions
(Outside of existing rivet holes)

Refer to Figure 1, Use a 0.220 to 0.232 in. (5,60 to 5,90 mm.) drill

(f) Examine

Make sure holes are correctly drilled

(g) Remove all sharp edges from the new holes and make a smooth surface Use standard workshop equipment

(h) Clean the affected areas

Refer to SPM TASK 70-11-26-300-503

(i) Do a crack test the affected areas

Refer to SPM TASK 70-23-05, penetrant inspection

(j) Make a mark of the new part No. on the fan frame assembly adjacent to the old part No., make two lines (====) on the old part No. to erase it Use the Vibro-Peen method, Refer to Figure 1 and A.(1), (a)


B. Assembly Instructions

(1) Install the 5A0426, mount tube stopper to the fan frame assembly with the two 4W2326, screws and 4W0001, nuts. Refer to Figure 2.


C. Record Instructions

A record of accomplishment is required.






Rework of the Fan Frame Assembly Fig.1



Install the mount tube stopper on the fan frame assembly Fig.2 $\,$

V2500-ENG-72-0286

ded0002396



3. <u>Material Information</u>


Applicability: For each V2500-A1 Engines to incorporate this Bulletin.

A. Kits associated with this Bulletin:

None.

B. Parts affected by this Bulletin:

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instruction/ Disposition
5A1763 (72-32-03)	1		.Frame, A/O Fan	5A6592 (03-100)	(A) (S1)(1D)
5A1764 (72-32-03)	1		.Frame, A/O Fan	5A0256 (03-100)	(A) (S1)(1D)
5A1765 (72-32-03)	1		.Frame, A/O Fan	5A6596 (03-100)	(A) (S1)(1D)
5A1766 (72-32-03)	1		.Frame, A/O Fan	5A0349 (03-100)	(A) (S1)(1D)
5A1767 (72-32-03)	1		.Frame, A/O Fan	5A0856 (03-100)	(A) (S1)(1D)
5A1768 (72-32-03)	1		.Frame, A/O Fan	5A1047 (03-100)	(A) (S1)(1D)
5A1769 (72-32-03)	1		.Frame, A/O Fan	5A0362 (03-100)	(A) (S1)(1D)
5A1770 (72-32-03)	1		.Frame, A/O Fan	5A0364 (03-100)	(A) (S1)(1D)
5A1771 (72-32-03)	1		.Frame, A/O Fan	5A0363 (03-100)	(A) (S1)(1D)
5A1772 (72-32-03)	1		.Frame, A/O Fan	5A0366 (03-100)	(A) (S1)(1D)
5A1773 (72-32-03)	1		.Frame, A/O Fan	5A0365 (03-100)	(A) (S1)(1D)
5A1774 (72-32-03)	1		.Frame, A/O Fan	5A0407 (03-100)	(A) (S1)(1D)



5A1775	1	.Frame, A/O	5A0401	(A)
(72-32-03)		Fan	(03-100)	(S1)(1D)
5A1776	1	.Frame, A/O	5A0405	(A)
(72-32-03)		Fan	(03-100)	(S1)(1D)
5A1777	1	.Frame, A/O	5A0403	(A)
(72-32-03)		Fan	(03-100)	(S1)(1D)
5A1778	1	.Frame, A/O	5A0409	(A)
(72-32-03)		Fan	(03-100)	(S1)(1D)
5A1779	1	.Frame, A/O	5A1167	(A)
(72-32-03)		Fan	(03-100)	(S1)(1D)
5A1780	1	.Frame, A/O	5A1049	(A)
(72-32-03)		Fan	(03-100)	(S1)(1D)
5A1781	1	.Frame, A/O	5A1064	(A)
(72-32-03)		Fan	(03-100)	(S1)(1D)
5A1782	1	.Frame, A/O	5A1062	(A)
(72-32-03)		Fan	(03-100)	(S1)(1D)
5A1783	1	.Frame, A/O	5A1068	(A)
(72-32-03)		Fan	(03-100)	(S1)(1D)
5A1784	1	.Frame, A/O	5A1066	(A)
(72-32-03)		Fan	(03-100)	(S1)(1D)
 (72-32-03)	1	Stopper, Rubber Mount	5A1300 (03-175)	(B)
 (72-32-03)	1	Rivet, Solid CSK Head	AS16447 (03-179)	(B)
5A0426	1	.Stopper, A/O		(C)
(72-32-03)		Mount Tube	(02-450)	(S1)(2D)
4W0001 (72-32-03)	1	.Nut, Option	 (02-451)	(C) (S1)(2D)
4W2326 (72-32-03)	1	.Screw, Option	 (02-454)	(C) (S1)(2D)


NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's spare parts sales department.




SERVICE BULLETIN

C. <u>Instruction/Disposition Code Statements:</u>


- (A) New part and old part are non-provisioning items.
- (B) Repair parts for Fan Frame Assembly (72-32-03, 03-100).
- (C) New part is currently available.
- (S1) New part coded (S1) must replace old part coded (S1) as a COMPLETE SET per engine.
- (1D) Old part can be reworked and reidentify to a new configuration.
- (2D) Additional part, same as IAE Service Bulletin No.V2500-ENG-72-0150.





Family Tree - Fan Frame Assembly Ref. Catalog Sequence No. 72-32-03, Fig.03, Item 100 Fig.3 (Sheet 1 of 6)






ded0002398

Family Tree - Fan Frame Assembly Ref. Catalog Sequence No. 72-32-03, Fig.03, Item 100 Fig.3 (Sheet 2 of 6)






ded0002399

Family Tree - Fan Frame Assembly Ref. Catalog Sequence No. 72-32-03, Fig.03, Item 100 Fig.3 (Sheet 3 of 6)






ed0002400

Family Tree - Fan Frame Assembly Ref. Catalog Sequence No. 72-32-03, Fig.03, Item 100 Fig.3 (Sheet 4 of 6)






ed0002401

Family Tree - Fan Frame Assembly Ref. Catalog Sequence No. 72-32-03, Fig.03, Item 100 Fig.3 (Sheet 5 of 6)





ded0002402

Family Tree - Fan Frame Assembly Ref. Catalog Sequence No. 72-32-03, Fig.03, Item 100 Fig.3 (Sheet 6 of 6)

