

Date: Apr.24/00

Subject: Transmittal of Revision 1 To Service Bulletin Number

V25000-ENG-72-0298.

Service Bulletin Revision History:

 Event
 Date

 Basic Issue
 Jan.5/98

 Revision 1
 Apr.24/00

Reason For Issuance Of Revision:

- (1) In paragraph 1.K.(2) change Chapter/Section 71-21-02 to 73-21-02 or 73-21-34.
- (2) Editorial correction page 2.
- (3) In paragraph 2.F. change Part Number 2P16242 to 2P16369.
- (4) In paragraph 2.J. add Chapter/Section 73-21-34.

Effect on Prior Compliance:

None.

List of Effective Pages:

Bulletin Page No.	Rev. No.	Effective <u>Date</u>
1 and 2	1	Apr.24/00
3	Basic	Jan.5/98
4	1	Apr.24/00
5	Basic	Jan.5/98
6 and 7	1	Apr.24/00
8 to 16	Basic	Jan.5/98

V2500-ENG-72-0298

Transmittal Page 1 of 1

ENGINE - CONVERSION - PROVIDE INSTRUCTIONS TO CHANGE THE V2500-D5 ENGINE RATING BY MODIFYING THE DATA ENTRY PLUG

MODEL APPLICATION

V2525-D5 V2528-D5

BULLETIN INDEX LOCATOR

72-00-00

Compliance Category Code

Internal Reference No.


8

97VI001B

Jan.5/98 Revision 1 Apr.24/00

V2500-ENG-72-0298

Page 1 of 16



1. Planning Information

Effectivity

(1) Aircraft: MCDONNELL DOUGLAS MD-90

Engine: V2525-D5 and V2528-D5 Engines (Any Engine as Applicable, subject to the restrictions listed in step (3)).

NOTE: Conversion of V2500-D5 engines to a different model rating as described in this Service Bulletin can only be accomplished as per prior contractual agreement with International Aero Engines.

Restrictions: See Table 1 to determine which (if any additional) Service Bulletins must be incorporated into the subject engine before performing an engine model change.

Conversion of V2500-D5 engines to a different model rating as described in this Service Bulletin can only be accomplished as per prior contractual agreement with International Aero Engines.

Engines that have been operated at a higher Rating must NOTE: maintain the life limited parts lives currently assigned to that higher Rating even if the engine is downrated to a lower Rating.

Reason

(1) Condition:

> Operators of multiple V2500-D5 engine models desire more flexibility with engine rating interchangeability.

Background:

Spare engines of a needed engine model may not always be available to operators of multiple V2500-D5 engine models.

(3) Objective:

To provide instructions for converting a V2500-D5 engine to a different engine model rating.

(4) Substantiation

All of the listed V2500-D5 engine model configurations have been previously flight tested and certified.

(5) Effects of Bulletin on Workshop Procedures:

Not affected Removal/Installation Not affected Disassembly/Assembly Not affected Cleaning Inspection/Check Not affected Not affected Repair

Jan.5/98 Revision 1 Apr.24/00

Testing Not affected

(6) Supplemental Information

None.

C. Description

- Determine if any Service Bulletin engine hardware and/or EEC software modifications are required prior to engine model conversion, from Table 1.
- (2) Determine the Data Entry Plug jumper connections for the desired V2500-D5 engine model rating, from Table 2.
- (3) Wire the current EEC Data Entry Plug to the appropriate engine model rating.
- (4) Mark the Data Entry Plug with the new Variant No.
- (5) Install a NEW Engine Identification Plate with the new Variant No. and Engine Rating already marked.

D. Approval

The Part Number Changes and/or part modifications described in Section 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

The 'compliance' statement and the procedures described in paragraph F of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-Approved for the Engine Model listed.

E. Compliance


Category 8

Accomplish based upon experience with the prior configuration.

NOTE: Conversion of V2500-D5 engines to a different model rating as described in this Service Bulletin can only be accomplished as per prior contractual agreement with International Aero Engines.

NOTE: Conversion is optional and is to be accomplished only if the required engine model is not available.

Jan.5/98



F. Manpower

Estimated Manhours to incorporate the full intent of this Bulletin:

Venue

Estimated Manhours

(1) In service

21 minutes

(2) At overhaul

21 minutes

NOTE: The parts affected by this Service Bulletin are accessible at overhaul.

- (a) To do a modification of the 13 minutes
 Data Entry Plug Assembly
- (b) To identify Data Entry Plug 3 minutes Assembly
- (c) To mark and install the 5 minutes
 Engine Identification Plate

TOTAL 21 minutes

- G. Material Price and Availability
 - (1) Modification kit is not required. Parts are supplied as single line items.
 - (2) See "Material Information" section for prices and availability of future spares.
- H. Tooling Price and Availability

1

IAE2P16242

Tester

Electrical test (1)

- (1) Indicates that tool design aperture card is currently available from IAE.
- I. Weight and Balance

(1) Weight change

None

(2) Moment arm

No effect

(3) Datum

Engine Front mount Centerline (Power Plant station (PPS) 100)

J. Electrical Load Data

This Service Bulletin has no effect on the aircraft electrical load.

- K. References
 - (1) V2500-D5 Engine Illustrated Parts Catalog (S-V2500-3IA, S-V2500-3IB), Chapter/Section 73-22-35, (Figure Item No. 01-100), and Chapter/Section 72-32-85, (Figure Item No. 03-120).
 - (2) Aircraft Maintenance Manual, Chapter/Section 73-21-35, Approved Repairs, Replace the Jumpers, Contacts or Connector VRS 3500; and Chapter/Section, 73-21-02 or 73-21-34 Adjustment/Test and Chapter/Section, 73-21-03, EEC Static Test Adjustment/Test.

Jan.5/98 Revision 1 Apr.24/00



- (3) V2500 Standard Practices/Processes Manual(SSP-V2500-1IA), 70-09-00, Marking of Parts.
- (4) IAE Service Bulletin:
 None.
- L. Other Publications Affected None.

Jan.5/98



2. Accomplishment Instructions


See Table 1 to determine which (if any) Service Bulletins must be incorporated into the subject engine before performing an engine model rating change.

- A. Remove the Data Entry Plug by the procedure given in Reference (2), Chapter/Section 73-21-35, Repairs, VRS3500.
- B. Disassemble the Data Entry Plug Assembly, PN 2A3106, Reference (1), Chapter/Section 73-22-35, Figure/Item No. 01-100) by the procedure specified in Reference (2), Chapter/Section 73-21-35, Repairs, VRS3500 and Figure 2.

The Data Entry Plug Assembly can be disassembled as necessary to permit the installation of the necessary jumper wires.

- C. Make two copies of Figure 5, Contact Hole Locations.
 - Mark the existing jumper connections from the Data Entry Plug Connector on one copy of the figure.
 - Find the jumper pin connections, from Table 2, for the current engine model rating, and highlight these on the copy made in C. (1).
 - Find the jumper pin connections, from Table 2, for the variant for (3) the target engine model rating, and highlight these on the second copy of the figure.
 - Determine the jumper pin changes required from these two copies, for the target engine model rating, and any new jumpers needed, (Reference (1), Chapter/Section 73-22-35, Figure/Item No. 01-100), and Figure 2.
- D. Modify the Data Entry Plug Connector by the procedure specified in Reference (2), Chapter/Section 73-21-35, Repairs, VRS3500.
- E. Assemble the Data Entry Plug Assembly by the procedure specified in Reference (2), Chapter/Section 73-21-35, Repairs, VRS3500 and Figure 2.
- Do a check of the wiring, using electrical tester IAE 2P16369, by the procedure specified in Reference (2), Chapter/Section 73-21-35, Repairs VRS3500.
- G. Mark the Data Entry Plug Backshell with the new Variant No. by the procedure given in Reference (3), Chapter/Section 70-09-00, Marking of Parts Parts and Figure 3. Use the vibration peen method.
- Install the Data Entry Plug by the procedure given in Reference (2), Chapter/Section 73-21-35, Repairs, VRS3500.
- Install a new Engine Identification Plate, PN 5A9036, Reference (1), Chapter/Section 72-32-85, Figure Item No. 03-120, and Figure 4 as follows:
 - The new Engine Identification Plate MUST be obtained from your NOTE: International Aero Engines Representative, and the old Engine Identification Plate MUST be returned to this same representative.
 - Remove the four bolts (4W0102), that hold the Engine Identification Plate to the bracket.

Jan.5/98 Revision 1 Apr.24/00



- Give the old Engine Identification Plate to your IAE Representative.
- Get the new Engine Identification Plate from your IAE Representative.
- Install the new Engine Identification Plate with the 4W0102 bolts (4 off).
- Torque the bolts between 32 to 36 lbfin (3,61 to 4,07 Nm).
- NOTE: If a two-sided (reversible) Engine Identification Plate is installed, that already has the required information and the new variant No. on the back-side of the plate, the plate may simply be removed, flipped over, and installed again. You MUST inform your IAE representative of this action.
- J. Check the data entry plug wiring by viewing the Engine Rating indicated on the Engine Display Panel comparing this to the Data Plate information, when the EEC and the DEP are installed on the aircraft. Use the procedure specified in Reference (2), Chapter/Section 73-21-02 or 73-21-34, EEC Adjustment/Test. Aircraft 28V dc Power/Engine Display Panel Adjustment /Test, to view the EDP, and Figure 6.

If this does not agree, the Data Entry Plug must be corrected or replaced; until then the aircraft can not be dispatched.

Do a Static Test of the EEC by the procedure given in Reference (2), Chapter/Section 73-21-03, Static Test, Adjustment/Test

Jan.5/98 Revision 1 Apr.24/00

NO SERVICE BULLETIN REQUIREMENTS AT THIS TIME

E7871

Service Bulletin Incorporation Requirements for Engine Model Conversion Table ${\bf l}$

Jan.5/98

V2500-ENG-72-0298



$\sqrt{2500}$ International Aero Engines **SERVICE BULLETIN**


FOR DEP 2A3106 (CL02), 2A2309 (CL04)							
VARIANT <u>No</u> .	ENG. <u>RATING</u> .	THRUST LEVEL	BUMP <u>No.</u>	CHANNEL A	CHANNEL B	JUMPER <u>TYPE</u>	No. <u>REQ.</u>
10	4	28K	00	b* TO F Y TO C Z* TO D	h* TO S N TO q g* TO f	2 PIN 2 PIN 2 PIN	2 PIN :6
15	5	25K	00	b* TO F Y TO C , X Z* TO D, E	h* TO S, N TO q, M g* TO f, R	2 PIN 3 PIN 3 PIN	2 PIN :2 3 PIN :4
20	6	25K/28K	00	b* TO F Y TO B, X	h* TO S N TO e, M	2 PIN 3 PIN	2 PIN :2 3 PIN :2
NOTE: In some cases, connectors holes b and h are used in the engine serial number wiring and connector holes g and Z are used in the EPR modifier wiring. Determine which holes are to be connected for engine serial number, EPR modifier and variant number wiring before you select the required jumpers.							
						E787	2

Data Entry Plug Pin Selection Procedure For Engine Rating - Bump No. Table 2

Jan.5/98

Printed in Great Britian

2500 International Aero Engines **SERVICE BULLETIN**




E7873

Location of the Electronic Engine Control Figure 1

Jan.5/98

V2500-ENG-72-0298




Data Entry Plug Assembly Figure 2

E7874

Jan.5/98

V2500-ENG-72-0298




E7875

Identification Of The Data Entry Plug Assembly To the New Part Number Figure 3

Jan.5/98

V2500-ENG-72-0298




E7876

Location of the Engine Identification Plate Figure 4

Jan.5/98

V2500-ENG-72-0298





?fi;E7564

NOTE: Upper case I, O, and Q are not used. Lower case I and o are not used.


ENGINE NO.	
RATING - BUMP	
VARIANT	
EPR MOD.	
P/N	2A3106- CL02

E7877

Contact Hole Locations Figure 5

Jan.5/98

V2500-ENG-72-0298



E7878

Engine Display Panel Electronic Engine Control Adjustment/Test Figure 6

Jan.5/98

V2500-ENG-72-0298



$\mathbf{V2500}$ International Aero Engines **SERVICE BULLETIN**

Material Information

Kit associated with this bulletin.

None

B. Parts affected by this bulletin.

New		Est'd		01d	
Part No.		Unit		Part No.	Instructions
(ATA No.)	Oty	Price(\$)	Keyword	(IPC No.)	Disposition
5A9036	1		Engine	5A9036	(A)
(72 - 32 - 85)				ion (03-120)	\ ,
			Plate		

C. Consumable Materials

None.

D. Instructions/Disposition Code Statements:

(A) The new Engine Identification Plate can be obtained through your International Aero Engines Representative.

Jan.5/98