

International Aero Engines

## SERVICE BULLETIN

Jan.12 /00

Subject: Transmittal of Revision 1 to Service Bulletin V2500-ENG-72-0347.

Service Bulletin Revision History:

Event	Date
Basic Issue	Aug 12/99.
Revision 1	Jan.12/00

Reason for Revision:

- (1) To revise 1. A. (2) Engine Incorporation and add Group A Part Life information for Stage 9-12 Disk Assembly (72-41-12,01-600) (INTREF TS-EM-036-99 refers)

Effect on Past Compliance:


None.

List of Effective Pages:

Page No.	Revision No.	Effective Date
1 and 2	Revision 1	Jan.12/00
3	Initial Issue	Aug.12/99
4	Revision 1	Jan.12/00
4A and 4B	Revision 1	Jan.12/00
5 to 28	Initial Issue	Aug. 12/99

# V2500-ENG-72-0347

Transmittal  
Page 1 of 1



## International Aero Engines SERVICE BULLETIN

ENGINE - HP COMPRESSOR DISKS (STAGES 9-12) - INTRODUCTION OF REVISED HP  
COMPRESSOR STAGE 9-12 DISK ASSEMBLY WITH INCREASED ABRASIVE LINING BOND  
COAT THICKNESS

### MODEL APPLICATION

V2500-A1  
V2522-A5  
V2524-A5  
V2527-A5  
V2527E-A5  
V2527M-A5  
V2530-A5  
V2533-A5  
V2525-D5  
V2528-D5

### BULLETIN INDEX INDICATOR

72-41-12

Compliance Category Code

7


Internal Reference No.

98VR036

Aug.12/99  
Revision 1 Jan.12/00

**V2500-ENG-72-0347**

Page 1 of 28



## International Aero Engines SERVICE BULLETIN

### ENGINE - HP COMPRESSOR DISKS (STAGES 9-12) - INTRODUCTION OF REVISED HP COMPRESSOR STAGE 9-12 DISK- ASSEMBLY WITH INCREASED ABRASIVE LINING BOND COAT THICKNESS

#### 1. Planning Information

##### A. Effectivity

##### (1) Aircraft


- (a) Airbus A319
- (b) Airbus A319CJ
- (c) Airbus A320
- (d) Airbus A321
- (e) Boeing - Douglas Product Division MD-90

##### (2) Engine:

- R (a) V2500-A1 Engines prior to serial number V0362
- R (b) V2522-A5 Engines prior to serial number V10653 onwards but excluding  
R V10647 to V10650 and V10652.
- R (c) V2524-A5 Engines prior to serial number V10653 onwards but excluding  
R V10647 to V10650 and V10652.
- R (d) V2527-A5 Engines prior to serial number V10653 onwards but excluding  
R V10647 to V10650 and V10652.
- R (e) V2527E-A5 Engines prior to serial number V10653 onwards but excluding  
R V10647 to V10650 and V10652.
- R (f) V2527M-A5 Engines prior to serial number V10653 onwards but excluding  
R V10647 to V10650 and V10652.
- R (g) V2530-A5 Engines prior to serial number V10653 onwards but excluding  
R V10647 to V10650 and V10652.
- R (h) V2533-A5 Engines prior to serial number V10653 onwards but excluding  
R V10647 to V10650 and V10652.
- (i) V2525-D5 Engines prior to serial number V20286
- (j) V2528-D5 Engines prior to serial number V20286

Aug.12/99  
Revision 1 Jan.12/00

**V2500-ENG-72-0347**



## International Aero Engines SERVICE BULLETIN

### B. Concurrent Requirements

None

### C. Reason

#### (1) Problem

De-bonding of the abrasive ceramic coating on the HP Compressor stage 9 to 12 disc assemblies can occur.

The problem is attributed to the insufficient thickness of the bond coat combined with a thick top layer.

#### (2) Background

The problem has been seen on engines in-service at strip on overhaul.

#### (3) Objective

Incorporation of this Service Bulletin is designed to keep maintenance reliability.

#### (4) Substantiation

The changes introduced by this Service Bulletin have been the subject of extensive engineering assessment together with successful completion of a 337-hour endurance test and 5000 short cycles of a representative disc assembly on V2500 development engine 804/18.

#### (5) Effect of Bulletin on:

##### (a) Operation

Not affected.

##### (b) Maintenance


Not affected.

##### (c) Overhaul

Not affected.

Aug.12/99

**V2500-ENG-72-0347**



## International Aero Engines SERVICE BULLETIN

(d) Repair Scheme

Affected.

(e) Interchangeability

Not affected.

(f) Fits and Clearances

Not affected.

### D. Description

- (1) The HP Compressor stage 9 to 12 disc assembly has been revised, the changes are as follows:


- (a) The bond coat thickness is increased from 0,1015mm plus or minus 0,0255mm to 0,225mm plus or minus 0,025mm, however the overall thickness of the bond coat and abradable lining is maintained at 0,45mm plus or minus 0,10mm.
- (b) An alternative bond coat '95/5 nickel/aluminium' is introduced to the existing '80/20 nickel/aluminium' material.

- (2) Existing HP Compressor stage 9 to 12 disc assemblies can be reworked – refer to figures 1 to 10.

- R (3) For the effect on declared life, the Time Limits Manual, 05-10-01, Group A Parts Lives will be updated to include the following :

R A1 Model only

R	PART NUMBER	6A7545
R	Approved life (Flight Cycles)	15,000
R	Bump usage (up to 5 percent)	0 to 750
R	Certified life up to 5 percent Bump usage	15,000
R	Bump usage cycles (up to 15 percent)	751 to 2250
R	Certified life up 15 percent Bump usage	15,000
R	Bump usage cycles (up to 30 percent)	2251 to 4500
R	Certified life up to 30 percent Bump usage	15,000
R	Bump usage cycles (up to 100 percent)	4501 to 15,000
R	Certified life up to 100 percent Bump usage	15,000



## International Aero Engines SERVICE BULLETIN

R	<u>A5 Model (V2527E and V2530) not incorporating SB72-0273</u>	
R	Stage 9 to 12 Disk	6A7547
R	(72-41-12,01-600)	
R	Approved life (Flight Cycles)	12,000
R	<u>A5 Model (V2522, V2524 and V2527) not incorporating SB72-0273</u>	
R	Stage 9 to 12 Disk	6A7547
R	(72-41-12,01-600)	
R	Approved life (Flight Cycles)	14,300
R	<u>A5 Model (V2533) not incorporating SB72-0273</u>	
R	Stage 9 to 12 Disk	6A7547
R	(72-41-12,01-600)	
R	Approved life (Flight Cycles)	8,000
R	<u>A5 Model (All Marks) SB72-0273</u>	
R	Stage 9 to 12 Disk	6A7546
R	(72-41-12,01-600)	
R	Approved life (Flight Cycles)	20,000
R	<u>D5 Model (V2525) not incorporating SB72-0273</u>	
R	Stage 9 to 12 Disk	6A7547
R	(72-41-12,01-600)	
R	Approved life (Flight Cycles)	15,700
R	<u>D5 Model (V2528) not incorporating SB72-0273</u>	
R	Stage 9 to 12 Disk	6A7547
R	(72-41-12,01-600)	
R	Approved life (Flight Cycles)	13,200
R	<u>D5 Model (All Marks) SB72-0273</u>	
R	Stage 9 to 12 Disk	6A7546
R	(72-41-12,01-600)	
R	Approved life (Flight Cycles)	20,000
R	<u>NOTE</u> : The Time Limits Manual 05-10-01 is scheduled to incorporate the Part Service Life	
R	Limits related to this Service Bulletin and will take precedence over the Service	
R	Bulletin.	

### E. Approval

The part number changes and/or part modification described in Section 2 and 3 of this Modification Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Models listed.

Aug. 12/99  
Revision 1 Jan. 12/00

## V2500-ENG-72-0347



## International Aero Engines SERVICE BULLETIN

### F. Compliance


#### Category Code 7

Accomplish when the supply of superseded parts has been depleted

Aug.12/99  
Revision 1 Jan.12/00

**V2500-ENG-72-0347**

Page 4B



## International Aero Engines SERVICE BULLETIN

### G. Manpower

Estimated Man-hours to incorporate the full intent of this bulletin.

(1) In Service

Not applicable

(2) At overhaul

No more time is necessary to do this Service Bulletin

NOTE: The parts affected by this Service Bulletin are accessible at overhaul.

### H. Material Price and Availability

(1) Modification kit is not required.

(2) See "Material Information" section for prices and availability of future spares.

### I. Tooling Price and Availability

Special tools are not required.

### J. Industry Support Information

Not applicable.

### K. Weight and Balance

(1) Weight Change

Plus 0.11b (0,05kg).

(2) Moment Arm

24.7in (627mm) rearwards.


(3) Datum

Engine Front Mount Centreline (Power Plant Station - PPS 100)

Aug.12/99

**V2500-ENG-72-0347**





## International Aero Engines SERVICE BULLETIN

### L. Electrical Load Data

This service Bulletin has no effect on the aircraft electrical load.

### M. Software Accomplishment Summary

Not applicable.

### N. References

- (1) Service Bulletin V2500-ENG-72-0273 (Engine – H.P. compressor discs (stages 9-12)  
Introduction of a revised H.P. compressor stage 9-12 disc assembly

### O. Other Publications Affected

- (1) V2500 Engine Illustrated Parts Catalogue (IPC) Chapter/Section 72-41-12.
- (2) V2500 Engine Manual, Chapter/Section 72-41-12, Cleaning-02, Inspection/Check-02  
and Repair
- (3) V2500 Engine Manual, Chapter/Section 72-41-10, Disassembly and Assembly-02

### P. Interchangeability of Parts

Not affected.

## 2. Accomplishment Instructions

### A. Rework Instructions

This Service Bulletin, is Source Demonstrated, refer to VRS6008, for more information.


Authorized Repair Vendors that can accomplish this SB 72-0347, are listed below:

GENERAL PLASMA INC.  
12 THOMPSON ROAD  
EAST WINDSOR CT 06088

ATTN. DIRECTOR, QUALITY ASSURANCE

Aug.12/99

# V2500-ENG-72-0347



## International Aero Engines SERVICE BULLETIN

MTU MAINTENANCE GMBH  
FLUGHAFEN HANNOVER  
MUNCHNER STRASSE 31  
POSTFACH 1720  
D3012 LANGENHAGEN  
GERMANY

ATTN. MANAGER. QUALITY ASSURANCE


ROLLS-ROYCE  
AERO-ENGINE SERVICES LTD.  
COMPONENT REFURBISHMENT  
MAVOR AVENUE  
NERSTON  
EAST KILBRIDE  
GLASGOW G74 4PY  
SCOTLAND

ATTN. BUSINESS MANAGER. COMPONENT REFURBISHMENT

ISHIKAWAJIMA - HARIMA HEAVY INDUSTRIES CO. LTD.,  
AERO-ENGINE & SPACE OPERATIONS,  
MIZUHO AERO - AERO WORKS,  
229, TONOGAYA,  
MIZUHO - MACHI,  
NISHITAMA - GUN,  
TOKYO, 190-12,  
JAPAN

ATTN. MANAGER, ENGINE COMPONENT REPAIR DEVELOPMENT.

- B. The designation by IAE of an Authorized Repair Vendor indicates that the Repair Vendor has demonstrated the necessary capability to enable it to carry out the listed repair work. However IAE make no warranties or representations concerning the qualification of quality standards of the Repair Vendors to carry out the repair work and accept no responsibility whatsoever for any work that may be carried out by a Repair Vendor other than when IAE is listed as the Repair Vendor. Authorized Repair Vendors do not act as agents or representatives of IAE.



## International Aero Engines SERVICE BULLETIN

### (1) Consumable Materials

CoMat 01-025	Nitric acid HNO <sub>3</sub>
CoMat 02-001	Masking tape
CoMat 03-037	Metal spraying powder metco 404NS
CoMat 03-043	Metal spraying powder metco 105NS
CoMat 03-416	Metal spraying powder Ni, Al (95/5)
CoMat 05-001	Abrasive

### (2) Standard Equipment

Chemical cleaning equipment  
Abrasive blast equipment  
Penetrant crack test equipment  
Standard workshop tools  
Metal spraying equipment  
NC Lathe  
Dial test indicator  
Vibro-engraving equipment

### (3) Rework the parts that follow, (A1 Engines only).

6A4131, HP. Compressor Stage 9 to 12 Disks Shaft Assembly, (Refer to 72-41-12, Fig/Item 01-600).

#### PROCEDURE


#### SUPPLEMENTARY INFORMATION

**CAUTION:** YOU MUST DO THIS MODIFICATION SB. 72-0347, IN FULL IF ONLY THE STAGE 11 RUBSTRIP IS TO BE REPLACED, IN ACCORDANCE WITH VRS6513, TASK 72-41-12-300-024.

- (a) Chemically clean                      Refer to TASK 72-41-12-100-000.  
   Use chemical cleaning equipment

- (b) Loosen the Top Coat Lining at Each Stage

**CAUTION:** REMOVE THE TOP COAT ONLY. THE BLAST OPERATION MUST STOP WHEN THE WHITE TOP COAT IS REMOVED. FAILURE TO STOP THE BLAST OPERATION AS SPECIFIED MAY RESULT IN SUBSEQUENT ENGINE FAILURE.



## International Aero Engines SERVICE BULLETIN

**NOTE:** It is permitted to loosen the top coat lining in part, to allow the Nitric Acid by capillary action, to release both top and bond coats at each stage.

### PROCEDURE

- (i) Seal all surfaces not to be blasted

- (ii) Lightly dry blast to loosen top coat lining at each stage

- (iii) Remove the masks

### (c) Chemically Remove the Linings at Each Stage

- (i) Remove the lining at each stage

### (d) Visually Examine Surfaces for Repair

- (i) Visually examine

### (e) Do a Crack Test

- (i) Do a penetrant crack test

### SUPPLEMENTARY INFORMATION


See Figure 1  
Use CoMat 02-001 masking tape  
or Refer to operation 3. A.  
for approved vendor tools

See Figure 1.  
Refer to SPM  
TASK 70-12-02-120-501  
Use CoMat 05-001 abrasive  
with abrasive blast equipment

See Figure 1 and Figure 3  
Refer to SPM TASK 70-33-59-300-503  
Use CoMat 01-025 nitric acid HNO<sub>3</sub>  
with chemical cleaning equipment.  
Put the assembly into nitric acid  
solution and keep below surface  
until bubbles stop

See Figure 3 and Figure 4  
Make sure all the lining material  
has been removed. If not do operation (b)  
and operation (c) again as necessary

Refer to SPM TASK 70-23-04-230-501.  
Use penetrant crack test equipment  
Discard the assembly if cracked



## International Aero Engines SERVICE BULLETIN

### PROCEDURE

### SUPPLEMENTARY INFORMATION

- (f) Dimensionally Examine Surfaces  
for Repair

**CAUTION:** ASSEMBLIES WHICH ARE NOT ACCEPTED AND CANNOT BE  
REPAIRED ARE TO BE DISCARDED.

- (i) Dimensionally examine  
the radial depth of the  
groove for the lining  
at each stage

See Figure 3 and Figure 4  
Use standard workshop tools.  
The depth of the groove must not be  
more than 0.016in. (0,40mm.)

- (g) Seal all Surfaces not to be Repaired

- (i) Seal applicable surfaces

See Figure 1  
Use CoMat 02-001 masking tape.  
Alternatively refer to operation 3. A.  
for approved vendor tools


- (h) Prepare Surfaces for Repair

**CAUTION:** 1. DO NOT TOUCH AREAS TO BE REPAIRED AFTER THEY ARE  
CLEANED.

2. TOO MUCH ABRASIVE BLAST CAN CAUSE DETERIORATION  
OF THE PREPARED SURFACE CONDITION AND MUST BE  
PREVENTED.

- (i) Lightly dry blast to  
prepare surfaces for  
the lining

Refer to SPM TASK 70-12-02-120-501  
Use CoMat 05-001 abrasive with  
abrasive blast equipment



## International Aero Engines SERVICE BULLETIN

### PROCEDURE

### SUPPLEMENTARY INFORMATION

#### (I) Apply the New Linings

- (i) Apply the bond coat at each stage

See Figure 1, 5, 6 and 9  
Refer to SPM TASK 70-34-01-340-501  
SUBTASK 70-34-01-340-007  
Use CoMat 03-037 metal spray powder or  
CoMat 03-416 metal spray powder  
with metal spraying equipment.  
Apply a thickness of 0.008 to 0.010in.(0,203 to  
0,254mm.)

- (ii) Apply the top coat at each stage

See Figure 1, 5, 6 and 9  
Refer to SPM  
TASK 70-34-01-340-501  
SUBTASK 70-34-01-340-013  
Use CoMat 03-043 metal spray powder  
with metal spraying equipment  
Apply a layer of sufficient  
thickness to get the correct  
dimensions after assembly is  
machined

- (iii) Remove the masks

#### (j) Visually Examine

- (i) Visually examine the new linings

Refer to SPM TASK 70-34-01-340-501  
SUBTASK 70-34-01-340-002

#### (k) Machine the Linings, Assembly

- (i) Set up the disk assembly to be machined


See Figure 1, 5, 6, and 9  
Use NC lathe and dial test indicator  
Refer to operation 3. A. for approved vendor tools

- (ii) Machine the linings

See Figure 1, 5, 6, and 9  
Machine at 200 feet/min  
(60 metres per min.)

Aug.12/99

**V2500-ENG-72-0347**



## International Aero Engines SERVICE BULLETIN

### PROCEDURE

### SUPPLEMENTARY INFORMATION

#### (L) Visually and Dimensionally Examine the Repair

- (i) Visually examine  
repaired area

See Figure 1, 5, 6 and 9  
Refer to SPM TASK 70-34-01-340-501  
SUBTASK 70-34-01-340-002

- (ii) Dimensionally examine  
the repaired linings  
at each stage

See Figure 1, 5, 6 and 9  
Use standard workshop tools

#### (m) Clean the Assembly

- (i) Chemically clean

Refer to TASK 72-41-12-100-000.  
Use Chemical cleaning equipment

- (n) Cancel the existing part number and  
identify with the new part number.

See Figure 10  
Use vibro engraving equipment  
Refer to the Standard Practices  
Manual (SPM)  
TASK 70-09-00-400-501  
SUBTASK 70-09-00-400-001

Existing Part No.

New Part No.


6A4131

6A7545

- (1) Rework the parts that follow (A5/D5 Engines only)

#### Consumable Materials

CoMat 01-025	Nitric acid HNO <sub>3</sub>
CoMat 02-001	Masking tape
CoMat 03-037	Metal spraying powder metco 404NS
CoMat 03-043	Metal spraying powder metco 105NS
CoMat 03-416	Metal spraying powder Ni Al (95/5)
CoMat 05-001	Abrasive



## International Aero Engines SERVICE BULLETIN

### PROCEDURE

### SUPPLEMENTARY INFORMATION

(2) Standard Equipment

Chemical cleaning equipment  
Abrasive blast equipment  
Penetrant crack test equipment  
Standard workshop tools  
Metal spraying equipment  
NC Lathe  
Dial test indicator  
Vibro-engraving equipment

(3) Rework the parts that follow, (A5/D5 Engines only).

6A6546 and 6A4156, HP. Compressor Stage 9 to 12 Disks Shaft Assembly,  
(Refer to 72-41-12, Fig/Item 01-600).

**CAUTION:** YOU MUST DO THIS MODIFICATION SB. 72-0347, IN FULL IF ONLY THE STAGE 11 RUBSTRIP IS TO BE REPLACED, IN ACCORDANCE WITH VRS6513, TASK 72-41-12-300-024.

(a) Chemically clean

Refer to TASK 72-41-12-100-000.  
Use chemical cleaning equipment

(b) Loosen the Top Coat Lining at Each Stage


**CAUTION:** REMOVE THE TOP COAT ONLY. THE BLAST OPERATION MUST STOP WHEN THE WHITE TOP COAT IS REMOVED. FAILURE TO STOP THE BLAST OPERATION AS SPECIFIED MAY RESULT IN SUBSEQUENT ENGINE FAILURE.

**NOTE:** It is permitted to loosen the top coat lining in part, to allow the Nitric Acid by capillary action, to release both top and bond coats at each stage.

(i) Seal all surfaces not  
to be blasted

See Figure 2  
Use CoMat 02-001 masking tape  
or Refer to operation 3. A.  
for approved vendor tools





## International Aero Engines SERVICE BULLETIN

### PROCEDURE

- (ii) Lightly dry blast to loosen top coat lining at each stage

- (iii) Remove the masks

### (c) Chemically Remove the Linings at Each Stage

- (i) Remove the lining at each stage

### (d) Visually Examine Surfaces for Repair

- (i) Visually examine

### (e) Do a Crack Test

- (i) Do a penetrant crack test

### (f) Dimensionally Examine Surfaces for Repair

**CAUTION:** ASSEMBLIES WHICH ARE NOT ACCEPTED AND CANNOT BE REPAIRED ARE TO BE DISCARDED.

- (i) Dimensionally examine the radial depth of the groove for the lining at each stage

### SUPPLEMENTARY INFORMATION

See Figure 2  
Refer to SPM TASK 70-12-02-120-501  
Use CoMat 05-001 abrasive with abrasive blast equipment

See Figure 2 and Figure 3.  
Refer to SPM TASK 70-33-59-300-503  
Use CoMat 01-025 nitric acid HNO<sub>3</sub> with chemical cleaning equipment.  
Put the assembly into nitric acid solution and keep below surface until bubbles stop

See Figure 3 and Figure 4  
Make sure all the lining material has been removed. If not do operation (b) and operation (c) again as necessary

Refer to SPM TASK 70-23-04-230-501.  
Use penetrant crack test equipment  
Discard the assembly if cracked

See Figure 3 and Figure 4  
Use standard workshop tools  
The depth of the groove must not be more than 0.016in. (0,40mm.)



## International Aero Engines SERVICE BULLETIN

### PROCEDURE

### SUPPLEMENTARY INFORMATION

(g) Seal all Surfaces not to be Repaired

(i) Seal applicable surfaces

See Figure 2

Use CoMat 02-001 masking tape

Alternatively refer to operation 3. A.  
for approved vendor tools

(h) Prepare Surfaces for Repair

**CAUTION:** 1. DO NOT TOUCH AREAS TO BE REPAIRED AFTER THEY ARE  
CLEANED.

2. TOO MUCH ABRASIVE BLAST CAN CAUSE DETERIORATION  
OF THE PREPARED SURFACE CONDITION AND MUST BE  
PREVENTED.

(i) Lightly dry blast to  
prepare surfaces for  
the lining

Refer to SPM TASK 70-12-02-120-501

Use CoMat 05-001 abrasive with  
abrasive blast equipment

(I) Apply the New Linings

(i) Apply the bond coat at  
each stage

See Figure 2, 7, 8 and 9

Refer to SPM TASK 70-34-01-340-501

SUBTASK 70-34-01-340-007

Use CoMat 03-037 metal spray powder or  
CoMat 03-416 metal spray powder  
with metal spraying equipment

Apply a thickness of 0.008 to 0.010in.(0,203 to  
0,254mm)

(ii) Apply the top coat  
at each stage

See Figure 2, 7, 8 and 9

Refer to SPM TASK 70-34-01-340-501

SUBTASK 70-34-01-340-013


Use CoMat 03-043 metal spray powder  
with metal spraying equipment

Apply a layer of sufficient  
thickness to get the correct  
dimensions after assembly is  
machined

(iii) Remove the masks

Aug.12/99

**V2500-ENG-72-0347**



## International Aero Engines SERVICE BULLETIN

### PROCEDURE

### SUPPLEMENTARY INFORMATION


- (j) Visually Examine
- (i) Visually examine the new linings
- Refer to SPM TASK 70-34-01-340-501  
SUBTASK 70-34-01-340-002
- (k) Machine the Linings, Assembly
- (i) Set up the disk assembly to be machined
- See Figure 2, 7, 8 and 9  
Use NC lathe and dial test indicator  
Refer to operation 3 A, for approved vendor tools
- (ii) Machine the linings
- See Figure 2, 7, 8 and 9  
Machine at 200 feet/min  
(60 metres per min.)
- (l) Visually and Dimensionally Examine the Repair
- (i) Visually examine repaired area
- See Figure 2, 7, 8 and 9  
Refer to SPM TASK 70-34-01-340-501  
SUBTASK 70-34-01-340-002
- (ii) Dimensionally examine the repaired linings at each stage
- See Figure 2, 7, 8 and 9  
Use standard workshop tools
- (m) Clean the Assembly
- (i) Chemically clean
- Refer to TASK 72-41-12-100-000  
Use Chemical cleaning equipment
- (n) Cancel the existing part number and identify with the new part number.
- See Figure 10  
Use vibro engraving equipment  
Refer to the Standard Practices Manual (SPM)  
TASK 70-09-00-400-501  
SUBTASK 70-09-00-400-001

<u>Existing Part No.</u>	<u>New Part No.</u>
--------------------------	---------------------

6A6546	6A7546
6A4156	6A7547

Aug.12/99

# V2500-ENG-72-0347



## International Aero Engines SERVICE BULLETIN

### B. Assembly Instructions

- (1) For the correct removal/installation procedure, refer to Engine Manual Chapter/Section 72-41-10, Disassembly and Assembly-02


### C. Recording Instructions

A record of accomplishment is necessary.


Aug. 12/99

**V2500-ENG-72-0347**

Page 17



# International Aero Engines SERVICE BULLETIN



APPLY THE SPRAY COAT AS GIVEN IN THE  
PROCEDURE ON THE AREAS SPECIFIED **AV**.

THE SURFACES SPECIFIED **AU** TO HAVE A MACHINED SURFACE FINISH  
OF 125 TO 250 MICROINCHES (3,2 TO 6,4 MICROMETRES).

## SECTION THROUGH DISC ASSEMBLY-STAGES 9 TO 12

MACHINE WHERE MARKED


REMOVE THE SHARP EDGES  $0.012 \pm 0.008$  in ( $0,30 \pm 0,20$  mm) UNLESS SPECIFIED DIFFERENTLY.  
THE MACHINED SURFACE FINISH TO BE 63 MICROINCHES (1,6 MICROMETRES).  
THE GEOMETRIC SYMBOLS ARE GIVEN IN THE I.S.O. MANUAL (1101).

Repair details and dimensions - (A1 Engine only)


Figure 1

Aug.12/99

**V2500-ENG-72-0347**



# International Aero Engines SERVICE BULLETIN



APPLY THE SPRAY COAT AS GIVEN IN THE  
PROCEDURE ON THE AREAS SPECIFIED **AV**.

THE SURFACES SPECIFIED **AU** TO HAVE A MACHINED SURFACE FINISH  
OF 125 MICROINCHES (3,2 MICROMETRES).

SECTION THROUGH DISC ASSEMBLY-STAGES 9 TO 12

MACHINE WHERE MARKED  $\nabla$ .

REMOVE THE SHARP EDGES  $0.012 \pm 0.008$  in ( $0,30 \pm 0,20$  mm) UNLESS SPECIFIED DIFFERENTLY.  
THE MACHINED SURFACE FINISH TO BE 63 MICROINCHES (1,6 MICROMETRES).  
THE GEOMETRIC SYMBOLS ARE GIVEN IN THE I.S.O. MANUAL (1101).


dem0000081

Repair details and dimensions - (A5/D5 Engines only)


Figure 2

Aug.12/99

**V2500-ENG-72-0347**



# International Aero Engines SERVICE BULLETIN




POSITION	DIMENSION AR	DIMENSION AP
AA	0.110 ± 0.010 in (2,79 ± 0,25mm)	1.216 ± 0.010 in (30,89 ± 0,25mm)
AB	2.171 ± 0.010 in (55,14 ± 0,25mm)	3.004 ± 0.010 in (76,30 ± 0,25mm)
AC	3.950 ± 0.010 in (100,33 ± 0,25mm)	4.899 ± 0.010 in (124,43 ± 0,25mm)
AD	5.815 ± 0.010 in (147,70 ± 0,25mm)	6.618 ± 0.010 in (168,10 ± 0,25mm)

dem0000082


Repair details and dimensions - (All Marks)  
Figure 3

Aug.12/99

**V2500-ENG-72-0347**



# International Aero Engines SERVICE BULLETIN



POSITION	DIMENSION AT	DIMENSION AS
AA	$0.110 \pm 0.010 \text{ in } (2,79 \pm 0,25 \text{ mm})$	$1.216 \pm 0.010 \text{ in } (30,89 \pm 0,25 \text{ mm})$
AB	$2.171 \pm 0.010 \text{ in } (55,14 \pm 0,25 \text{ mm})$	$3.008 \pm 0.010 \text{ in } (76,40 \pm 0,25 \text{ mm})$
AC	$3.954 \pm 0.010 \text{ in } (100,43 \pm 0,25 \text{ mm})$	$4.908 \pm 0.010 \text{ in } (124,66 \pm 0,25 \text{ mm})$
AD	$5.823 \pm 0.010 \text{ in } (147,90 \pm 0,25 \text{ mm})$	$6.635 \pm 0.010 \text{ in } (168,53 \pm 0,25 \text{ mm})$

dem0000083


Repair details and dimensions - (All Marks)

Figure 4


Aug.12/99

**V2500-ENG-72-0347**





# International Aero Engines SERVICE BULLETIN



DETAIL AT AA AND AB.

Repair details and dimensions - (A1 Engine only)

Figure 5

Aug.12/99

**V2500-ENG-72-0347**



Figure 6

**V2500-ENG-72-0347**





Figure 7

**V2500-ENG-72-0347**




Figure 8

**V2500-ENG-72-0347**



# International Aero Engines SERVICE BULLETIN




dem0000088


Repair details and dimensions - (All Marks)  
Figure 9

Aug.12/99

**V2500-ENG-72-0347**



# International Aero Engines SERVICE BULLETIN




dem00000089

Repair details and dimensions - (All Marks)  
Figure 10

Aug.12/99

**V2500-ENG-72-0347**



## International Aero Engines SERVICE BULLETIN

### 3. Material Information

NEW PART No. (ATA No.)	QTY	EST'D UNIT PRICE (\$)	PART TITLE	OLD PART No. (IPC No.)	INSTR DISP
------------------------------	-----	-----------------------------	------------	------------------------------	---------------

---

Applicability : For each V2500 engine to incorporate this Bulletin.

#### A. Kits associated with this Bulletin:-

None

#### B. Parts affected by this Bulletin:-

A1 Model Only

6A7545 (72-41-12)	1	.Disc Assy-Stages 9 to 12 HP Compressor	6A4131 (01-600)	(A) (S1) (1D)
----------------------	---	--	--------------------	------------------

For A5 & D5 Models Incorporating SB 72-0273

6A7546 (72-41-12)	1	.Disc Assy - Stages 9 to 12 HP Compressor	6A6546 (01-600)	(A) (S1) (1D)
----------------------	---	--	--------------------	------------------

For A5 & D5 Models not Incorporating SB 72-0273

6A7547 (72-41-12)	1	.Disc Assy - Stages 9 to 12 HP Compressor	6A4156 (01-600)	(S1) (1D)
----------------------	---	--	--------------------	-----------

**NOTE:** The unit prices, if shown, are an estimate and they are given for the purposes of planning only.  
For actual prices, refer to the IAE Price Catalogue or contact IAE's spare parts sales department.

#### C. Instruction Disposition Codes

- (A) New part will be made available from September 1999.
- (S1) Old and new parts are freely and fully interchangeable.
- (1D) Old part may be reworked and re-identified to the new part number.

Aug.12/99

## V2500-ENG-72-0347