



400 MAIN STREET, MAIL STOP 121-10  
EAST HARTFORD, CT 06108, USA.  
TELEPHONE:- 860 565 5515

DATE: Mar. 1/11

## V2500-A5/D5 PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits the Revision 2 of Service Bulletin V2500-ENG-72-0403.

### Document History

#### Service Bulletin Revision Status

Initial Issue.	Nov.26/01.
Revision 1.	Jan.10/02.

#### Service Bulletin Revision 2

Remove	Incorporate	Reason for change
All pages of the Service Bulletin.	Pages 1 to 16 of the Service Bulletin.	To add approved repair vendors. Minor editorial changes.

# V2500-ENG-72-0403

Transmittal - Page 1 of 1

**CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED**  
If any have not been received please advise IAE International Aero Engines AG

IAE PROPRIETARY INFORMATION

© IAE International Aero Engines AG (date as above). All rights reserved.  
Not subject to the EAR per 15 C.F.R. Chapter 1, Part 754.3(b)(3).



ENGINE – HP COMPRESSOR SHAFT – INTRODUCTION OF REVISED HP COMPRESSOR REAR SHAFT  
ASSEMBLY WITH NO.4 BEARING LOCATION COATING (A5 & D5 MODELS)

1. Planning Information

A. Effectivity

(1) Airbus A319

R V2522-A5, V2524-A5, V2527M-A5 Engines prior to Serial No. V11181.

(2) Airbus A320

R V2527-A5, V2527E-A5 Engines prior to Serial No. V11181.

(3) Airbus A321

R V2530-A5, V2533-A5 Engines prior to Serial No. V11181.

R (4) Boeing MD-90

V2525-D5, V2528-D5 Engines prior to Serial No. V20286.

(5) ATA Locator 72-41-13

B. Concurrent Requirements

R None.

C. Reason

R (1) Condition

Wear has been observed on the HP Compressor rear shaft and the inner race of the No.4 bearing. In extreme cases this may result in the fit between the components exceeding acceptable limits.

R This is attributed to the variation in thermal expansion of components throughout the flight cycle, causing movement of the bearing inner ring relative to the shaft, resulting in fretting.

(2) Background

R This has been experienced on engines in service and highlighted at overhaul.

(3) Objective

Incorporation of this Service Bulletin (Modification) is designed to maintain reliability.

Nov.26/01

Mar. 1/11 Revision 2

**V2500-ENG-72-0403**

Page 1 of 16

IAE PROPRIETARY INFORMATION

© IAE International Aero Engines AG. All rights reserved.  
Not subject to the E.A.R. per 15 C.F.R. Chapter I, Part 93.3(b)(3).

(4) Substantiation

The changes introduced by this Service Bulletin have been the subject of extensive engineering assessment and successful development engine testing.

(5) Effect of Bulletin on:

(a) Operation

R Not affected.

(b) Maintenance

R Affected (Refer to paragraph 1.0. Other Publications Affected).

(c) Overhaul

R Affected (Refer to paragraph 1.0. Other Publications Affected).

(d) Repair Schemes

Affected.

(e) Interchangeability

Not affected

(f) Fits and Clearances

Not affected.

**D. Description**

- (1) This Service Bulletin introduces an anti-frettage coating to the No.4 bearing location diameter of the HP compressor rear shaft assembly in order to minimise frettage and eliminate loss of fit between these two components.

The changes introduced are:

- (a) A revised HP compressor rear shaft assembly similar to the existing item except for:

- (i) A recess is machined into the diameter of the shaft at the No.4 bearing location to a controlled depth of 0,076mm to 0,152mm, with a width sufficient to ensure the final run-out of applied coating is well beyond the front and rear faces of the bearing.

(b) A tungsten carbide cobalt coating is applied to the recess and machine ground back in order to maintain the current No.4 bearing location diameter.

(2) Existing HP Compressor rear shaft assemblies may only be reworked providing that the No.4 Bearing diameter (identified as ZONE AB) has not been repaired with Chromium Plate in accordance with repair VRS6509 – see Figs 1 and 2.

(3) For effect on declared life see Time Limits Manual 5-10-01.

#### E. Compliance

Category Code 6

Accomplish when the sub assembly (i.e. modules, accessories, components, build groups) is disassembled sufficiently to afford access to the affected part and to all affected spare parts.

#### F. Approval

The part number changes and/or part modifications described in sections 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA approved for the engine models listed.

#### G. Manpower

- R (1) In Service
- R Not applicable.
- R (2) At Overhaul/Shop Visit
- R 14 manhours for the rework.

NOTE: The parts affected by this Service Bulletin are accessible at overhaul.

#### H. Material Price and Availability

Modification kit not required; parts supplied as single line items.

- R For prices and availability of future spares see 2. Material Information.

#### I. Tooling Price and Availability

- R Special tools are not required.

#### J. Industry Support Information

- R None.

Nov.26/01

Mar. 1/11 Revision 2

# V2500-ENG-72-0403

Page 3

IAE PROPRIETARY INFORMATION

© IAE International Aero Engines AG. All rights reserved.  
Not subject to the E.A.R. per 15 C.F.R. Chapter 1, Part 73.1(b)(3).

**K. Weight and Balance****(1) Weight Change**

R           None.

**(2) Moment Arm**

R           No effect.

**(3) Datum**

R           Engine front mount centerline (Power Plant Station (PPS) 100).

**L. Electrical Load Data**

R           The aircraft electrical load is not affected by this Service Bulletin.

**M. Software Accomplishment Summary**

R           Not applicable.

**N. References****(1) IAE V2500 Reference Repair Schemes:**

VRS6509 HPC REAR SHAFT ASSEMBLY – REPAIR THE BEARING, FRONT SEAL, SEAL SPACER AND HPT LOCATION DIAMETERS BY CHROMIUM PLATING.

**(2) Internal reference: EC 01VR004.****(3) Engine Manual 1IA****(a) 72-40-00**

(i)     Disassembly 04

(ii)    Assembly 03

**(b) 72-41-10**

(i)     Disassembly, Config 2

(ii)    Assembly 01, Config 2

(iii)   Assembly 02, Config 2

- (4) Engine Manual, 3IA
  - (a) 72-40-00
    - (i) Disassembly 04
    - (ii) Assembly 03
  - (b) 72-41-10
    - (i) Disassembly
    - (ii) Assembly 01
    - (iii) Assembly 02

0. Other Publications Affected

- (1) Illustrated Parts Catalogue 2IA, 2IB, 3IA, 3IB, 5IA, 5IB, 6IA, 6IB, 7IA, 7IB, 72-41-13 will be revised.
- (2) Engine Manual
  - (a) 1IA, 72-41-13
    - (i) Inspection/Check 01, Config 6
    - (ii) Cleaning 01, Config 2
    - (iii) Repairs
    - (iv) Rework 002
  - (b) 3IA, 72-41-13
    - (i) Inspection/Check 01, Config 2
    - (ii) Cleaning 01, Config 1
    - (iii) Repairs
    - (iv) Rework 001
- (3) Time Limits Manual, 05-10-01
  - (a) 1IA, Config 2, Config 3, Config 4
  - (b) 3IA, Config 1, Config 2

P. Interchangeability of Parts

Not affected.



## 2. Material Information

### A. The kit required consists of the following parts:

None

### B. New production parts:

PART NO.	QTY	UNIT PRICE US DOLLARS
6A7711	1	66230.00
6A7712	1	Not spareable

**NOTE:** The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For actual prices, refer to the IAE Price Catalogue or contact IAE's spare parts sales department.

### C. Parts affected by this bulletin:

All Engines

72-41-13

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
For engines incorporating Mod 72-0202						
01850	6A7711	1	Shaft, assy-rear HP compressor	-	6A5867	(A)(S1) (1D)
01900	6A7712	1	Shaft-rear HP compressor	-	6A5868	(B) (S1) (1D)
For engines not incorporating Mod 72-0202						
01850	6A7713	Ref	Shaft, assy-rear HP compressor	-	6A4157	(A)(S1) (1D)
01900	6A7714	Ref	Shaft-rear HP compressor	-	6A4158	(B) (S1) (1D)

### D. Instructions disposition codes:

(A) New part will be made available from May 2001.

(B) Reference only. Will not be made available as a spare for replenishment purposes.

(S1) New and old parts are freely and fully interchangeable.

Nov.26/01

Mar. 1/11 Revision 2

# V2500-ENG-72-0403

Page 7

IAE PROPRIETARY INFORMATION

© IAE International Aero Engines AG. All rights reserved.  
Not subject to the E.A.R. per 15 C.F.R. Chapter 1, Part 93.3(b)(3).

(1D) Old part may be reworked and re-identified to the new part number.

### 3. Accomplishment Instructions

#### A. Rework Instructions

- (1) This is a Source Demonstrated Service Bulletin which can only be carried out by approved vendors

The source demonstration requirements of this Service Bulletin means that any facility not authorised to accomplish this Service Bulletin, either utilise the authorised repair vendors listed below or contact the IAE Repair Services Group to determine if a qualification program can be initiated at their facility.

IAE – International Aero Engines AG  
C/O Rolls-Royce plc  
PO Box 31  
Derby  
DE24 8BJ  
England  
Attn: Manager Technical Services

Authorised repair vendors for Service Bulletin 72-0403 are listed below:

Rolls-Royce – Aero Repair and Overhaul  
Mavor Avenue  
Nerston  
East Kilbride  
Glasgow G74 4PY  
Scotland

R MTU Maintenance Zhuhai Co. Ltd  
R No. 1 Tianke Road  
R Free Trade Zone  
R Zhuhai, Guangdong  
R PC: 519030 P.R. China  
R Attn. Manager, Parts Repair

R Lufthansa Technik AG  
R Weg Beim Jager 193  
R D-22335 Hamburg  
R Germany  
R Attn. Manager Repair Development



The designation by IAE of an authorised repair vendor indicates that the repair vendor has demonstrated the necessary capability to enable it to carry out the listed Service Bulletin work. However, IAE makes no warranties or representations concerning the qualifications or quality standards of the repair vendor to carry out the Service Bulletin work and accepts no responsibility whatsoever for any work that may be carried out by a repair vendor other than when IAE is listed as the repair vendor. Authorised repair vendors do not act as agents or representatives of IAE.

(2) Rework the parts that follow:

6A4157 HP compressor rear shaft assembly. Refer to Illustrated Parts Catalogue (IPC), 72-41-13, Fig/Item 01-850.

NOTE: 6A4157 (Fig/Item 01-850) is an assembly and contains the part 6A4158 (01-900).

6A5867, HP compressor rear shaft assembly. Refer to Illustrated Parts Catalogue (IPC) 72-41-13 Fig/Item 01-850.

NOTE: 6A5867 (Fig/Item 01-850) is an assembly and contains the part 6A5868 (01-900).

(3) Standard equipment

Locally made grinding fixture  
Cylindrical grinding machine  
Dial test indicator  
Standard workshop equipment  
Standard workshop inspection equipment  
Chemical cleaning equipment  
X10 binoculars  
Penetrant crack test equipment  
Vibro engraving equipment

(4) Consumable materials

CoMat 06-003 Adhesive tape waterproof black  
CoMat 06-022 Fluorescent penetrant

(5) Prepare the HP compressor

- (a) Remove the HP compressor assembly from the engine. Refer to the applicable Engine Manual (EM) 72-00-41, Removal and Installation.
- (b) Disassemble the HP compressor assembly. Refer to the applicable Engine Manual (EM) 72-41-00, Removal and Installation.
- (c) Disassemble the HP compressor rotor. Refer to the applicable Engine Manual (EM) 72-41-10, Removal and Installation.

PROCEDURE	RELATED DATA
(6) Make sure the HP compressor rear shaft assembly can be repaired	You cannot rework the assembly if the assembly is identified 6A7711, 6A7713, VRS6509/1, VRS6509/2, VRS6509/3, VRS6509/4 and/or with a triangle with the letters A, B, C or D inside it.
(7) Grind the HP compressor rear shaft assembly	
(a) Install the fixture into the cylindrical grinding machine	Use a locally made grinding fixture and cylindrical grinding machine
PROCEDURE	RELATED DATA
(b) Install the HP compressor rear shaft assembly on to the fixture and set to turn correctly	Refer to Fig 1 and Fig 2. Use a dial test indicator and standard workshop equipment. Make sure that datums A, B and C are set to turn correctly
(c) Grind the HP compressor rear shaft assembly	Refer to Fig 1 and Fig 2. Refer to approved vendor process
(d) Remove burrs	Use standard workshop equipment
(8) Inspect the HP compressor rear shaft assembly	Refer to approved vendor process. Use standard workshop inspection equipment.
(9) Chemically clean the HP compressor rear shaft assembly	Refer to SPM TASK 70-11-01-300-503. Use chemical cleaning equipment
(10) Cold ferric chloride etch surface AB on the HP compressor rear shaft	Refer to Fig 1 and Fig 2. Refer to SPM TASK 70-11-39-300-503, SUBTASK 70-11-39-300-001. Use chemical cleaning equipment
(11) Visually examine surface AB on the HP compressor rear shaft	Refer to Fig1 and Fig 2. Use X10 binoculars. Indications of defects are not permitted
(12) Do a local penetrant crack test on surface AB of the HP compressor rear shaft	Refer to Fig 1 and Fig 2. Refer to SPM TASK 70-23-05-230-501. Use CoMat 06-022 fluorescent penterant, with penetrant crack test equipment. Cracks are not permitted

(13) Shot peen surface AB on the HP compressor rear shaft

- |  |   |
|--|---|
| (a) Seal the full assembly but for the area which is to be shot peened | Refer to Fig 1 and Fig 2. Use CoMat 06-003 adhesive tape black waterproof or a mechanical seal. Patch mask all identification marks and symbols |
| (b) Shot peen the area which is to be shot peened                      | Refer to Fig 1 and Fig 2. Refer to vendor approved process  |
| (c) Make sure all loose unwanted cast steel shot is removed            |   |

PROCEDURE

RELATED DATA

- |   |  |
|---|--|
| (d) Remove iron contamination after you have shot peened, as necessary                | Refer to Fig 1 and Fig 2. Refer to vendor approved process |
| (e) Remove adhesive tape and/or mechanical seals                                      |  |
| (f) Examine the shot peened area  | Refer to Fig 1 and Fig 2. Refer to vendor approved process |
| (14) Apply the metal spray hard coating to surface AB on the HP compressor rear shaft | Refer to Fig 1 and Fig 2. Refer to vendor approved process |

**NOTE:** Overspray of the metal spray coating is permitted on surfaces AE

(15) Grind the hard coating on the HP compressor rear shaft

- |   |   |
|---|---|
| (a) Install the fixture into the cylindrical grinding machine                                 | Use a locally made grinding fixture   |
| (b) Install the HP compressor rear shaft assembly on to the fixture and set to turn correctly | Refer to Fig 1 and Fig 2. Use a dial test indicator and standard workshop equipment. Make sure that datums A, B and C are set to turn correctly |
| (c) Grind the HP compressor rear shaft assembly   | Refer to Fig 1 and Fig 2. Refer to approved vendor process  |
| (d) Remove burrs  | Use standard workshop equipment   |
| (16) Visually and dimensionally inspect the HP compressor rear shaft assembly                 | Refer to Fig 1 and Fig 2. Use standard workshop inspection equipment  |
| (17) Do a crack test  | Refer to vendor approved process  |

- |  |  |           |
|--|--|-----------|
| (18) Chemically clean the repaired area  | Refer to SPM TASK 70-11-26-300-503,<br>SUBTASK 70-11-26-300-002      |           |
| (19) Cancel the existing part number and re-identify the HP compressor rear shaft assembly with the new part number adjacent to the existing part number | Refer to SPM TASK 70-09-00-400-001.<br>Use vibro-engraving equipment |           |
|  | Existing   | Re-number |
|  | 6A4157   | 6A7713    |
|  | 6A5867   | 6A7711    |


NOTE: Estimated 14 man-hours for rework only

#### B. Assembly Instructions

The revised HP compressor rear shaft assembly introduced by this Service Bulletin is interchangeable with existing. Remove and install in accordance with current overhaul procedures (Engine Manual, 72-40-00, 72-41-10, Disassembly and Assembly (see 1.N. References)).

#### C. Recording Instructions

- (1) A record of accomplishment is required.



BASIC SECTION THROUGH  
HP COMPRESSOR REAR SHAFT

SURFACE TEXTURE VALUES IN MICROINCHES (MICROMETRES)  
GEOMETRIC SYMBOLS CONFORM TO ISO R1101

dem0000607



Rework of HP compressor rear shaft  
Fig 1

Nov.26/01  
Mar. 1/11 Revision 2

**V2500-ENG-72-0403**

Page 14





dem00000609

Rework of HP compressor rear shaft  
 Fig 2




V2500-A5 AND D5 FAMILY TREE

BASELINE

V2500-ENG-72-0202  
Introduction of strengthened HP  
compressor rear shaft and new  
mating rear rotating seal

V2500-ENG-72-0403  
Introduction of revised HP  
compressor rear shaft assembly  
with No 4 bearing location coating



ded0004174a

V2500-A5 and D5 family tree  
Fig 3