



International Aero Engines

RR-DERBY

400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE: 860 565 5515
FAX: 860 565 0600

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE - DERBY 242424

DATE ~~R~~ Aug. 8/02

V2500-A1/A5/D5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

Printed in Great Britain

This document transmits Revision 1 to Service Bulletin EV2500-72-0411

Document History

Service Bulletin Revision Status
Initial Issue Dec.2/01

Supplement Revision Status

Bulletin Revision 1

Remove
Pages 1 to 17 of the
Service Bulletin

Incorporate
Pages 1 to 18 of the
Service Bulletin

Reason for change
To add visual inspection
instead of evacuation check
for Front Bearing
Compartment without the
Leak Check Fixture. To add
scallop type for the oil
drain feature at the side
wall of Hydraulic Seal
groove for new production.

V2500-ENG-72-0411
Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED

If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England

© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin following incorporation of Revision 1 are as follows:

<u>Page</u>		<u>Revision Number</u>	<u>Revision Date</u>
	Bulletin		
R	1	1	Aug.8/02
R	2	1	Aug.8/02
R	3	1	Aug.8/02
R	4	1	Aug.8/02
R	5	1	Aug.8/02
R	6	1	Aug.8/02
R	7	1	Aug.8/02
R	8	1	Aug.8/02
R	9	1	Aug.8/02
R	10	1	Aug.8/02
R	11	1	Aug.8/02
R	12	1	Aug.8/02
R	13	1	Aug.8/02
R	14	1	Aug.8/02
R	15	1	Aug.8/02
R	16	1	Aug.8/02
R	17	1	Aug.8/02
R	18	1	Aug.8/02

Printed in Great Britain



ENGINE – LP COMPRESSOR – INTRODUCTION OF HYDRAULIC SEAL WITH REVISED OIL DRAIN
FEATURE

1. Planning Information

A. Effectivity

Part 1

- (1) Airbus A320

V2500-A1 Engines prior to Serial No.V0214

- (2) ATA Locator 72-32-00

Part 2

- (1) Airbus A319

V2522-A5, V2524-A5, V2527M-A5 Engines prior to Serial No.V11350

- (2) Airbus A320

(a) V2500-A1 Engines prior to Serial No.V0214 to V0361

(b) V2527-A5, V2527E-A5 Engines prior to Serial No.V11350

- (3) Airbus A321

V2530-A5, V2533-A5 Engines prior to Serial No.11350

- (4) Boeing Longbeach Division MD-90

V2525-D5, V2528-D5 Engines prior to Serial No.20286

- (5) ATA Locator

72-32-00

B. Concurrent Requirements

None.

**C. Reason****(1) Problem**

The seal ring at the hydraulic seal is designed to expand and shrink according to the rotor speed. During normal operation, the seal ring expands and attaches into the hydraulic seal groove. When the rotor speed is decreased, the seal ring shrinks, detaches from the hydraulic seal groove and prevents oil leakage to aft portion of the hydraulic seal at engine shutdown. In several field engines, it was revealed that the seal ring adhered on the hydraulic seal groove and was stuck open at engine shutdown.

(2) Background

The sticking open of the seal ring must be prevented because the oil leakage at engine shutdown due to the sticking open is one cause of cabin odour at the next flight. The tear down inspection revealed that the cause of the adhesion and sticking open of the seal ring is the degraded oil and carbon build up observed in the seal ring groove. To prevent the degraded oil and carbon build up, improvement of the drain capability of the hydraulic seal is required.

(3) Objective

To introduce improved oil drain feature by scalloping the side wall of the hydraulic seal groove.

(4) Substantiation

Analytically substantiated.

(5) Effect of Bulletin on workshop procedures:**(a) Removal/Installation**

Not affected

(b) Disassembly/Assembly

Affected (See Supplemental Information)

(c) Cleaning

Not affected

(d) Inspection/Check

Not affected

R



(e) Repair

Not affected

(f) Testing

Not affected

(6) Supplemental Information

R The assembly of the Pre and Post-Service Bulletin configuration requires
R instructions for the visual inspection instead of evacuation check for
R Front Bearing Compartment without the Leak Check Fixture in the Stub Shaft
R and Hydraulic Ring.

D. Description

(1) The changes introduced are as follows:

Part 1

R (a) The oil drain feature at the side wall of hydraulic seal groove is
changed from holes to slots or scallops. Refer to Fig.1.

(b) The numbers of the oil drain feature are not changed. Refer to Fig.1.

Part 2

R (c) The oil drain feature at the side wall of hydraulic seal groove is
changed from holes to slots or scallops. Refer to Fig.1.

(d) The numbers of the oil drain feature are changed from three to six.
Refer to Fig.1.

(2) Existing hydraulic seal can be reworked. Refer to Fig. 4.

(3) For relationship with other Service Bulletins, see 1.K. references and
Fig.2 Family Tree.

(4) This Service Bulletin comprises the two parts that follow:

Part 1 – Rework of hydraulic seal of engines not incorporating SB
V2500-ENG-70-0172

Part 2 – Rework of hydraulic seal of engines incorporating SB
V2500-ENG-70-0172

E. Compliance

Category Code 6



Accomplish when the sub-assembly (i.e. modules, accessories, components, build groups) is disassembled sufficiently to afford access to the affected part and to all affected spare parts.

F. Approval

The part number changes and/or part modifications described in sections 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA approved for the engine models listed.

G. Manpower

Part 1 and Part 2

Estimated Man-hours to incorporate the full intent of this Service Bulletin

(1) In service

Not applicable.

(2) At overhaul

(a) To embody modification (setup, machine, deburr and visually inspect)

1 hour 15 minutes

(b) Re-identify part

20 minutes

(c) Total

1 hour 35 minutes

NOTE: The parts affected by this Service Bulletin are accessible at overhaul.

H. Weight and Balance

(1) Weight Change

None

(2) Moment Arm

No effect

(3) Datum

Engine front mount centreline (Power Plant Station (PPS100)).

**I. Electrical Load Data**

The aircraft electrical load is not affected by this Service Bulletin.

J. Software Accomplishment Summary

Not applicable.

K. References

- R (1) Engineering Change No. 01VJ015 and 02VJ627
- (2) V2500 Engine Illustrated Parts Catalog (A1/A5/D5), Chapter/Section 72-32-19
- (3) V2500 Engine Manual (EM)(E-V2500-1IA and E-V2500-3IA), Chapter/Section 72-32-19, Cleaning-01, Config-01
- (4) V2500 Engine Manual (EM)(E-V2500-1IA and E-V2500-3IA), Chapter/Section 72-32-19, Inspection/Check-01, Config-01
- (5) V2500 Engine Manual (EM)(E-V2500-1IA and E-V2500-3IA), Chapter/Section 72-32-19, Repair 003 (VRS1228), Repair 004 (VRS1229) and Repair 006 (VRS1233)
- (6) V2500 Standard Practices/Processes Manual (SPM) (SPP-V2500-1IA), Chapter/Section 70-09-00 Marking of Parts
- (7) IAE V2500 Service Bulletin
- V2500-ENG-70-0172 - Standard Practices - Engine - Information - Engine LP compressor - New hydraulic seal assembly - Category code 7

L. Other Publications Affected

- (1) V2500 Engine Illustrated Parts Catalog (A1/A5/D5), Chapter/Section 72-32-19 will be revised to add the new part.
- R (2) V2500 Engine Manual (EM)(E-V2500-1IA and E-V2500-3IA), Chapter/Section 72-32-19, Inspection/Check-01, Config-01 will be revised to add the new part.
- R (3) V2500 Engine Manual (EM)(E-V2500-1IA and E-V2500-3IA), Chapter/Section 72-32-19, Cleaning-01, Config-01 will be revised to add the new part.
- R (4) V2500 Engine Manual (EM)(E-V2500-1IA and E-V2500-3IA), Chapter/Section 72-32-19, Repair 003 (VRS1228), Repair 004 (VRS1229) and Repair 006 (VRS1233)



(5) V2500 Engine Manual (EM)(E-V2500-1IA), Chapter/Section 72-32-00, Assembly-11, Config-01 and Config-02 will be revised to delete evacuation check for Front Bearing Compartment without the Leak Check Fixture in the Stub Shaft and Hydraulic Ring.

(6) V2500 Engine Manual (EM)(E-V2500-1IA), Chapter/Section 72-32-00, Assembly-06, will be revised to add the visual inspection instead of evacuation check for Front Bearing Compartment without the Leak Check Fixture in the Stub Shaft and Hydraulic Ring.

(7) V2500 Engine Manual (EM)(E-V2500-3IA), Chapter/Section 72-32-00, Assembly-11, will be revised to delete evacuation check for Front Bearing Compartment without the Leak Check Fixture in the Stub Shaft and Hydraulic Ring.

(8) V2500 Engine Manual (EM)(E-V2500-3IA), Chapter/Section 72-32-00, Assembly-06, will be revised to add the visual inspection instead of evacuation check for Front Bearing Compartment without the Leak Check Fixture in the Stub Shaft and Hydraulic Ring.

M. Interchangeability of Parts

Not affected.



2. Material Information

A. Material – Price and Availability

(1) Modification Kit

Modification Kit is not required, existing parts can be reworked

(2) New production

PART NO.	QTY	UNIT PRICE US DOLLARS
5A1865	1	

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For actual prices, refer to the IAE Price Catalogue or contact IAE's spare parts sales department.

B. Industry Support Information

None

C. Kits necessary for this Service Bulletin

None

D. Parts affected by this bulletin:

V2500-A1/A5/D5 Engines

72-32-19

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
Part 1						
01100	5A1865	1	Seal, A/O Hydraulic	–	5A0698	(A)(B) (S1)(1D)
Part 2						
01100	5A1865	1	Seal, A/O Hydraulic	–	5A1085	(A)(C) (S1)(1D)

**E. Instruction disposition codes:**

- (A) New part will be made available from June 2002.
- (B) Old part is no longer available.
- (C) Old part will continue to be supplied until the new part will be available.
- (S1) New and old parts are freely and fully interchangeable, both physically and functionally.
- (1D) New part can be obtained by rework and re-identification of old part.

F. Tooling – Price and Availability

The tool that follows is required to accomplish this Service Bulletin when reworking the existing hydraulic seal:

Tool Number	Qty	Description	Function	Availability
IAE3J12858	1	Fixture, machining, hydraulic	Fixture at rework of hydraulic seal	(1)

- (1) Indicates that tool design aperture card is currently available from IAE for use in the local manufacture of the fixture.



3. Accomplishment Instructions

A. Rework Instructions

- (1) Do a modification of 5A0689 (Part 1) or 5A1085 (Part 2) hydraulic seal and identify as follows:

- (a) Set up hydraulic seal with the special tool on the machine tool

PROCEDURE

RELATED DATA

- (i) Put the hydraulic seal (Part A and Part B) on the special tool
- (ii) Adjust position of clamps B to seat clamps B to the hydraulic seal (Part B) and safety the hydraulic seal (Part B) with the four screws C, washers B, clamps B and screws B

NOTE: Screws C, washers B, clamps B and screws B are part of the IAE3J12858 fixture, machining hydraulic seal



- (iii) Safety the hydraulic seal Refer to Fig.4.
(Part A) with the screw A,
washer A and clamp A

NOTE: Screw A, washer A and
clamp A are part of
the IAE3J12858
fixture, machining
hydraulic seal

- (b) Cut out the side wall of Refer to Fig.5. Use standard workshop
groove at six equally spaced equipment
positions on circumference of
hydraulic seal

NOTE: All existing drain holes
have to be removed
completely by new cut
off areas.

NOTE: Machining operation is
mandatory at area A.

NOTE: Machining operation is not
mandatory at area B.

- (c) Remove all burrs and sharp Refer to Fig.5
edges from areas cut out

- (d) Examine dimensions Refer to Fig.5

- (e) Cancel existing part number Use vibro-peen method. Refer to Fig.5
and identify with new part and SPM 70-09-00, Marking of Parts,
number adjacent to existing TASK 70-09-00-400-501.
part number

Existing	Re-number
Part 1	
5A0698	5A1865
Part 2	
5A1085	5A1865






B. Assembly Instructions

- (1) Install the new 5A1865 hydraulic seal, existing seal ring and hydraulic ring onto the No.3 bearing rotor centre and support assembly. Refer to Engine Manual (EM), 72-32-10, Assembly, Config-01 (A1), 72-32-10, Assembly, Config-02 (A5), or 72-32-10, Assembly (D5).
- R Evacuation check for front bearing compartment without the Leak check
R fixture in the Stub Shaft Assembly and the Hydraulic Seal is not required.
- (2) Visually inspect the Stub Shaft Assembly, Hydraulic Seal and Hydraulic Ring. Refer to following procedure and Figure 6.
- R (a) Make sure the clearance between the Stub Shaft Assembly and the
R Hydraulic Seal is no more than 0.131 in. (3,35 mm.). If the clearance
R is over 0.131 in. (3,35 mm.), reject the module.
- R (b) Make sure the Hydraulic Seal is fully seated against Hydraulic Ring.
R If Hydraulic Seal is not seated, adjust position of Hydraulic Ring.
R Refer to EM, 72-32-00, Assembly-06
- R (c) Make sure Seal Ring is installed in Hydraulic Seal. If Seal Ring is
R not installed, reject the module.

C. Recording Instructions

A record of accomplishment is required.



NOTE: THERE ARE TWO TYPE, SLOT TYPE OR SCALLOP TYPE
FOR OIL DRAIN FEATURE OF AFTER ALTERATION

ALL DIMENSIONS ARE IN IN.(MM)

Before and after alteration of hydraulic seal
Fig.1

V2500-ENG-72-0411


MODIFICATIONPART NUMBER CHANGE

For V2500-A1

BASE LINE

V2500-ENG-70-0172
ENGINE - LP COMPRESSOR -
NEW HYDRAULIC SEAL ASSEMBLY
-CATEGORY 7

V2500-ENG-72-0411 Part 1 and 2
ENGINE - LP COMPRESSOR -
INTRODUCTION OF HYDRAULIC
SEAL WITH REVISED OIL DRAIN FEATURE
-CATEGORY 6



jax0800053

Family tree - Seal, A/O hydraulic (72-32-19, Fig 01 Item 100)
Fig.2 (Sheet 1 of 2)




MODIFICATION

PART NUMBER CHANGE

For V2522-A5, V2524-A5, V2527-A5
V2527E-A5, V2527M-A5, V2530-A5,
V2533-A5, V2525-D5 and V2528-D5

BASE LINE

V2500-ENG-72-0411 Part 1 and 2
ENGINE - LP COMPRESSOR -
INTRODUCTION OF HYDRAULIC
SEAL WITH REVISED OIL DRAIN FEATURE
-CATEGORY 6



jax0800021


Family tree - Seal, A/O hydraulic (72-32-19, Fig 01 Item 100)
Fig.2 (Sheet 2 of 2)

V2500-ENG-72-0411


Dec 2/01
R Aug. 8/02

© Rolls-Royce plc

Page 14





Location of seal, A/O hydraulic
Fig.3



* Part of the 3J12858 Fixture, Machining-Hdraulic Seal

† Standard Equipment



Installation of hydraulic seal to tool IAE3J12858 fixture, machining hydraulic seal
Fig.4



ALL DIMENSIONS ARE IN IN.(MM)
ALL EXISTING DRAIN HOLES HAVE TO BE REMOVED
COMPLETELY BY NEW CUT OFF AREAS.
MACHINING OPERATION IS MANDATORY AT AREA A.
MACHINING OPERATION IS NOT MANDATORY AT AREA B.
SURFACE ROUGHNESS WHERE MARKED ✓
TO BE 250 MICROINCHES (6,3 MICROMETER).

fax0800023

Rework and re-identification of seal, A/O hydraulic
Fig.5



Requirements of Visual Inspection
Fig.6

V2500-ENG-72-0411