400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE:- 860 565 5515 FAX:- 860 565 0600 P.O. BOX 31, DERBY TELEGRAMS – 'ROYCAR' DERBY TELEX – 37645 TELEPHONE:– 44 (0) 1332 242424 FAX:– 44 (0) 1332 249936

DATE: Oct. 13/05

V2500-A1/A5/D5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits Revision 2 to Service Bulletin EV2500-72-0470 and Revision 2 to the Supplement

Document History

Service Bulletin Revision Status
Initial Issue Jul.28/04 Initial Issue Jul.28/04
Revision 1 Jul.6/05 Revision 1 Jul.6/05

Bulletin Revision 2

Remove Incorporate Reason for change

All pages of the Page 1 and 2 of the To revise Family Tree titles

Summary Summary

All pages of the Pages 1 to 11 of the To revise Family Tree titles

Service Bulletin Service Bulletin

Supplement Revision 2

Remove Incorporate Reason for change

All pages Page 1 To revise Family Tree titles

V2500-ENG-72-0470
Transmittal - Page 1 of 2

Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin following incorporation of Revision 2 to the Bulletin and Revision 2 to the Supplement are as follows:

<u>Page</u>		<u>Revision Number</u>	Revision Date
	Summary		
R	1	2	0ct.13/05
	=		
R	2	2	0ct.13/05
	Bulletin		
R	1	2	Oct.13/05
R	2	2	0ct.13/05
R	3	2	0ct.13/05
R	4	2	0ct.13/05
R	5	2	0ct.13/05 0ct.13/05
R	6	2	0ct.13/05
R	7	2	Oct.13/05
R	8	2	0ct.13/05
R	9	2	Oct.13/05
R	10	2	Oct.13/05
R	11	2	Oct.13/05
	Supplement		
_	Jupprement	2	0-+ 17/05
R	1	2	0ct.13/05



ENGINE - HP COMPRESSOR DISCS (STAGES 3-8) - INTRODUCTION OF REVISED DISC ASSEMBLY WITH REDUCED STAGE 7 REAR DAMPER WIRE RETAINING WALL DIAMETER

SUMMARY

1. PLANNING

A. EFFECTIVITY

Engine Serial No.

V2500-A1 V0001 to V0361

V2500-A5 V10001 to V11783 and Engine Serial Nos. V11785,

V11787, V11789, V11791, V11793, V11795, V11797 and

V11799

V2500-D5 V20001 to V20285

B. CONCURRENT REQUIREMENTS

None.

C. REASON/PROBLEM

Problem

Difficulty may be experienced when fitting HP Compressor Stage 7 blades to the HPC 3-8 disc assembly.

The problem has been attributed to insufficient clearance between the stage 7 rear damper wire retaining tower and the underside of the blade platform.

Evidence

The problem has been experienced on engine build.

Substantiation

The changes introduced by this Service Bulletin (Modification) have been the subject of extensive engineering analysis.

Objective

Incorporation of this Service Bulletin is designed to ease engine assembly.

D. DESCRIPTION

A revised HP Compressor Stage 3-8 disc assembly is introduced similar to the existing item except for a reduction in the stage 7 rear damper wire retaining wall diameter. This introduces a minimum clearance of 0,03 mm. between the retaining wall and the underside of the blade platform.

Jul.28/04 R Oct.13/05 SUMMARY V2500-ENG-72-0470

E. COMPLIANCE

Category Code 7

Accomplish when the supply of superseded parts has been depleted.

F. MANPOWER

In service - Not applicable.

At overhaul - Not affected.

G. INTERCHANGEABILITY OF PARTS

Not affected.

2. MATERIAL INFORMATION

A. PARTS PRICES

Part No.	Description	US Dollars
6A8318	Disc	143,040.00
6A8316	Disc	143,040.00

SUMMARY V2500-ENG-72-047



<u>ENGINE - HP COMPRESSOR DISCS (STAGES 3-8) - INTRODUCTION OF REVISED DISC ASSEMBLY</u> WITH REDUCED STAGE 7 REAR DAMPER WIRE RETAINING WALL DIAMETER

1. Planning Information

A. Effectivity

(1) Airbus A319

V2522-A5, V2524-A5, V2527M-A5 Engines prior to Serial No.V11784 and Engine Serial Nos. V11785, V11787, V11789, V11791, V11793, V11795, V11797 and V11799

(2) Airbus A320

V2500-A1 Engines prior to Serial No. V0362

V2527-A5, V2527E-A5 Engines prior to Serial No.V11784 and Engine Serial Nos. V11785, V11787, V11789, V11791, V11793, V11795, V11797 and V11799

(3) Airbus A321

V2530-A5, V2533-A5 Engines prior to Serial No.V11784 and Engine Serial Nos. V11785, V11787, V11789, V11791, V11793, V11795, V11797 and V11799

(4) Boeing - Longbeach Division MD-90

V2525-D5, V2528-D5 Engines prior to Serial No. V20286

B. Concurrent Requirements

None.

C. Reason

(1) Problem

Difficulty may be experienced when fitting HP Compressor Stage 7 blades to the HPC 3-8 disc assembly.

The problem has been attributed to insufficient clearance between the stage 7 rear damper wire retaining tower and the underside of the blade platform.

(2) Evidence

The problem has been experienced on engine build.

Jul.28/04 R Oct.13/05



(3) Substantiation

The changes introduced by this Service Bulletin (Modification) have been the subject of extensive engineering analysis.

(4) Objective

Incorporation of this Service Bulletin is designed to ease engine assembly.

- (5) Effect of Bulletin on:
 - (a) Operation

Not affected.

(b) Maintenance

Affected.

(c) Overhaul

Affected.

(d) Repair Schemes

Affected.

(e) Interchangeability

Not affected.

(f) Fits and Clearances

Not affected.

D. <u>Description</u>

- (1) The changes introduced are:
 - (a) A revised HP Compressor Stage 3-8 disc assembly is introduced similar to the existing item except for a reduction in the stage 7 rear damper wire retaining wall diameter. This introduces a minimum clearance of 0,03 mm. between the retaining wall and the underside of the blade platform.
- (2) For effect on declared life see Time limits manual 5-10-01.

E. Compliance

Category Code 7

Jul.28/04 R Oct.13/05



Accomplish when the supply of superseded parts has been depleted.

F. Approval

The part number changes and/or part modifications described in Sections 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-Approved for the engine models listed.

G. Manpower

In service

Not applicable.

At overhaul

Not affected.

NOTE: The parts affected by this Service Bulletin are accessible at overhaul.

H. Material Price and Availability

Modification kit not required; parts supplied as single line items.

For prices and availability of future spares see Supplement to this Bulletin.

I. Tooling Price and Availability

Special tools are not required.

J. <u>Industry Support Information</u>

None.

K. Weight and Balance

(1) Weight Change

None.

(2) Moment Arm

No Effect.

(3) Datum

Engine Front Mount Centreline (Power Plant Station PPS100).

L. <u>Electrical Load Data</u>

The aircraft electrical load is not affected by this Service Bulletin.

Jul.28/04 R Oct.13/05



M. <u>Software Accomplishment Summary</u>

Not applicable.

N. References

- (1) Engine Manual, Chapter/Section 72-41-10, Assembly.
- (2) Engineering Change No. 03VR012.
- (3) ATA Locator 72-41-11.

0. Other Publications Affected

- (1) Illustrated Parts Catalogue (IPC), Chapter/Section 72-41-11 will be revised.
- (2) Engine Manual, Chapter/Section 72-41-10, Assembly.
- (3) Engine Manual, Chapter/Section 72-41-11, Cleaning and Inspection/Check.

P. Interchangeability of Parts

Not Affected.



2. Material Information

A. The kit required consists of the following parts:

None.

B. Parts to be reworked:

None.

C. New production parts:

A1 Engines

72-41-11

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
01200	6A8318	1	.Disc, assy of Stage 3-8 HP Compressor	-	6A8236	(A)(S1)
01245	6A8317	Ref	Disc, assy of Stage 3-8 HP Compressor	-	6A7706	(B)
A5 and D5 Engines						
FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
01200	6A8316	1	.Disc, assy of Stage 3-8 HP Compressor	-	6A7705	(A)(S1)
01245	6A8317	Ref	Disc, assy of Stage 3-8 HP Compressor	-	6A7706	(C)

D. <u>Instruction Disposition Codes:</u>

- (A) New part will be available from July 2004.
- (B) Part of Disc Assy, 6A8318. Will not be made available as a spare for replenishment purposes.
- (C) Part of Disc Assy, 6A8316. Will not be made available as a spare for replenishment purposes.
- (S1) Old and new parts are freely and fully interchangeable.

Jul.28/04 V250 R Oct.13/05



3. Accomplishment Instructions

A. Rework Instructions

None.

B. Assembly Instructions

For the correct Assembly Instructions refer to Engine Manual, Chapter/Section 72-41-10, Assembly.

C. Recording Instructions


A record of accomplishment is necessary.



Baseline 6A3648 6A3508 V2500-ENG-72-0035 HP Compressor Discs and 6A3936 6A3934 Blades-Stages 3 to 5 -Anti-Frettage Treatment Α V2500-ENG-72-0130 6A4189 **HP Compressor Discs** Deleted Stage 3 to 8 Rotor Drum Assembly with Spacers in Triple Melt Titanium В V2500-ENG-72-0161 6A5594 HP Compressor Discs and Blades-Stage 7 & 8 Damper Wires and Stage 6, 7 & 8 Blades with **Anti-Frettage Coating** V2500-ENG-72-0178 **HP Compressor Discs** 6A5467 Stage 3 to 8 Rotor Drum Thicker Stage 6 Disk Hub and Damping Wire Locating Lip V2500-ENG-72-0254 **HP Compressor Discs** 6A6473 Stage 3 to 8-Introduction of HPC Drum with Revised Disc Profiles V2500-ENG-72-0304 **HP Compressor Discs** 6A7385 6A7384 6A7379 Stage 3 to 8-Intro of Reworked Stage 3 to 8 Disc Assy with Revised 'L' Shaped Sealing Wires V2500-ENG-72-0300 6A7401 **HP Compressor Discs** Stages 3 to 8-Intro of HP Comp Disc Assy with Revised Location Of Damper Wire Grooves ded0005993

A1 Engines Only - HP Compressor Stage 3-8 Disc Assembly Family Tree Sheet 1 of 3

Jul.28/04 R Oct.13/05



A1 Engines Only - HP Compressor Stage 3-8 Disc Assembly Family Tree Sheet 2 of 3

Jul.28/04 R Oct.13/05


| ded0005994

V2500-ENG-72-0450

HP Compressor Discs Stages 3–8 – Intro of a Revised Stage 3–8 Disc Assy

V2500-ENG-72-0470

HP Compressor Discs Stages 3-8 - Intro of a Revised Disc Assy with Reduced Stage 7 Rear Damper Wire Retaining Wall Diameter



ded0005995a

A1 Engines Only - HP Compressor Stage 3-8 Disc Assembly Family Tree Sheet 3 of 3

Jul.28/04 R Oct.13/05

Baseline

V2500-ENG-72-0178

Engine - HP Compressor Discs - Stage 3 to 8 Drum with Thicker Stage 6 Disk Hub and Damping Wire Location Lips

V2500-ENG-72-0254

Engine - HP Compressor Discs (Stage 3 to 8) Introduction of HPCompressor Drum with Revised Disc Profiles

V2500-ENG-72-0304

Engine - HP Compressor Discs - Introduction of a reworked Stage 3 to 8 disc with revised L shaped sealing wires

V2500-ENG-72-0300


Engine - Stage 3 to 8 - HP Compressor Discs - Introduction of revised stage 3 to 8 disc assembly and revised stage 7 and 8 sealing wires

V2500-ENG-72-0376

Engine - HP Compressor Discs (Stages 3-8) - Introduction of a Revised Stage 3-8 Disc Assembly With Increased Life.

V2500-ENG-72-0470

Engine - HP Compressor Discs (Stages 3-8) - Introduction of a Revised Disc Assembly With Reduced Stage 7 Rear Damper Wire Retaining Wall Diameter



ded0005996

R

A5 and D5 Engines (not including A533) - HP Compressor Stage 3-8 Disc Assembly Family Tree
Sheet 1 of 1

Jul.28/04 R Oct.13/05

Baseline

V2500-ENG-72-0304

Engine - HP Compressor Discs Introduction of a reworked Stage 3 to 8 disc assembly with revised L shaped sealing wires

V2500-ENG-72-0300


Engine - Stage 3 to 8 - HP Compressor Discs - Introduction of revised stage 3 to 8 disc assembly and revised stage 7 and 8 sealing wires

V2500-ENG-72-0376

Engine - HP Compressor Discs (Stages 3-8) - Introduction of a Revised Stage 3-8 Disc Assembly With Increased Life.

V2500-ENG-72-0470

Engine - HP Compressor Discs (Stages 3-8) - Introduction of a Revised Disc Assembly With Reduced Stage 7 Rear Damper Wire Retaining Wall Diameter



led0005997

R

R

A533 Only - HP Compressor Stage 3-8 Disc Assembly Family Tree Sheet 1 of 1

Jul.28/04 R Oct.13/05



<u>ENGINE - HP COMPRESSOR DISCS (STAGES 3-8) - INTRODUCTION OF REVISED DISC ASSEMBLY</u> WITH REDUCED STAGE 7 REAR DAMPER WIRE RETAINING WALL DIAMETER

SUPPLEMENT - PRICES AND AVAILABILITY

The prices (if shown) are for estimating purposes only and as such are given in good faith, without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current price catalogue for current prices.

1. Modification Kit:

Not applicable.

2. Parts required:

Part No.	Description	Unit Price US Dollars
6A8318	Disc	143,040.00
6A8316	Disc	143,040.00

V2500-ENG-72-0470
Supplement Page 1 of 1