P.O. BOX 31, DERBY

400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE:- 860 565 5515 FAX:- 860 565 0600 TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE: - 44 (0) 1332 242424
DATR: Jun.20/05
FAX: - 44 (0) 1332 249936

V2500-A5/D5 SERIES PROPULSION SYSTEM SERVICE BULLETIN

This document transmits Revision 1 to Service Bulletin EV2500-72-0486 and Revision 1 to the Supplement

Document History

Service Bulletin Revision Status Supplement Revision Status
Initial Issue Apr.22/05 Initial Issue Apr.22/05

Bulletin Revision 1

Remove Incorporate Reason for change
All pages of the Page 1 and 2 of the To revise engine
Summary incorporation information.

All pages of the Pages 1 to 15 of the To revise engine Service Bulletin Service Bulletin incorporation information.

<u>Supplement Revision 1</u>

Remove Incorporate Reason for change
All pages Page 1 To revise engine incorporation information.

V2500-ENG-72-0486

Printed in Great Britain

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England © Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin following incorporation of Revision 1 to the Bulletin and Revision 1 to the Supplement are as follows:

<u>Pa</u>	<u>ige</u>	<u>Revision Number</u>	<u>Revision Date</u>	
	Summary			
R	1	1	Jun.20/05	
R	2	1	Jun.20/05	
	Bulletin			
R	1	1	Jun.20/05	
R	2	1	Jun.20/05	
R	3	1	Jun.20/05	
R	4	1	Jun.20/05	
R	5	1	Jun.20/05	
R	6	1	Jun.20/05	
R	7	1	Jun.20/05	
R	8	1	Jun.20/05	
R	9	1	Jun.20/05	
R	10	1	Jun.20/05	
R	11	1	Jun.20/05	
R	12	1	Jun.20/05	
R	13	1	Jun.20/05	
R	14	1	Jun.20/05	
R	15	1	Jun.20/05	
	Supplement			
R	1	1	Jun.20/05	



ENGINE - HP COMPRESSOR VARIABLE VANES - INTRODUCTION OF A REVISED VIGV WITH AN OPTIMISED SPINDLE - MOD 72-0486

SUMMARY

1. PLANNING

A. EFFECTIVITY

Engine Serial No.

V2500-A5 Prior to V11870 and Engine Serial No.s V11871, V11873.

V11874, V11887 and V11941.

V2500-D5 Prior to V20286

B. CONCURRENT REQUIREMENTS

None.

C. REASON/PROBLEM

Problem

The design review of the HP Compressor has indicated that manufacture of the Variable Inlet Guide Vanes (VIGV) may be optimised.

Evidence

See problem.

Substantiation

The changes introduced by this modification have been subject of extensive engineering analysis.

Objective

Incorporation of this modification is designed to simplify manufacture.

D. DESCRIPTION

This modification introduces revised arrangement for attaching the lever arms to the top of the VIGV spindles from the existing stud and nut to a bolt and helicoil configuration.

E. COMPLIANCE

Category Code 7

Accomplish when the supply of superseded parts has been depleted.

Apr 22/05 R Jun.20/05 SUMMARY V2500-ENG-72-0486

© Rolls-Royce plc

Printed in Great Britain

R R

F. MANPOWER

In service - Not applicable.

At overhaul - Not affected.

G. INTERCHANGEABILITY OF PARTS

Not affected.

2. MATERIAL INFORMATION

A. PARTS PRICES

Part No.	Description	Unit Price US Dollars
6A8405	Vane, assy - VIGV Long Spindle	854.00
6A8407	Vane, assy - VIGV Short Spindle	854.00
4W0409	Bolt	10.50



ENGINE - HP COMPRESSOR VARIABLE VANES - INTRODUCTION OF A REVISED VIGV WITH AN OPTIMISED SPINDLE - MOD 72-0486

1. Planning Information

A. <u>Effectivity</u>

Printed in Great Britain

R

- (1) Airbus A319
 - (a) V2522-A5, V2524-A5, V2527M-A5, Engines prior to Serial No. V11870 and Engine Serial No.s V11871, V11873. V11874, V11887 and V11941.
- (2) Airbus A320
- R (a) V2527-A5, V2527E-A5, Engines prior to Serial No. V11870 and Engine R Serial No.s V11871, V11873. V11874, V11887 and V11941.
 - (3) Airbus A321
- R (a) V2530-A5, V2533-A5, Engines prior to Serial No. V11870 and Engine R Serial No.s V11871, V11873. V11874, V11887 and V11941.
 - (4) Boeing Longbeach Division MD-90
 - (a) V2525-D5, V2528-D5, Engines prior to V20286.

B. Concurrent Requirements

None.

C. Reason

(1) Problem

A design review of the HP Compressor has indicated that manufacture of the Variable Inlet Guide Vanes (VIGV) may be optimised.

(2) Evidence

See problem.

Substantiation

The changes introduced by this modification have been the subject of extensive engineering analysis.

(3) Objective

Incorporation of this modification is designed to simplify manufacture.

Apr 22/05 R Jun.20/05

- (4) Effect of Bulletin on:
 - (a) Operation

Not affected.

(b) Maintenance

Not affected.

(c) Overhaul

Affected.

(d) Repair Schemes

Affected.

(e) Interchangeability

Not affected.

(f) Fits and Clearances

Not affected.

D. <u>Description</u>

- (1) This modification introduces revised arrangement for attaching the lever arms to the top of the VIGV spindles from the existing stud and nut to a bolt and helicoil configuration. The changes introduced are:
 - (a) Revised HP Compressor VIGV long and short spindle assemblies are introduced, similar to the existing items except for:
 - (b) The stud in the top of the vane outer spindle is deleted and replaced by a helicoil insert.
 - (i) The existing thread size is reduced from 0.3125 UNJF to 0.2964 UNJF.
 - (ii) The depth of the outer spindle hole has been increased.
 - (iii) The counter bore diameter has been reduced from 8,68mm. to 7,80mm.
 - (iv) The weight relief areas on the long spindle are removed.
 - (c) The nut which was previously used to attach the lever arms to the top of the vane spindles is deleted and replaced by a standard type bolt.



E. Compliance

Category 7.

Accomplish when the supply of superseded parts has been depleted.

F. Approval

The part number changes and/or part modifications specified in the Accomplishment Instructions and Material Information sections of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model(s) given.

G. Manpower

(1) In service

Not applicable

(2) At overhaul

Not affected

<u>NOTE</u>: The parts affected by this Service Bulletin are accessible at overhaul.

H. Material Price and Availability

Modification kit not required; parts supplied as single line items.

For prices and availability of future spares see supplement to this bulletin.

I. Tooling Price and Availability

Special tools are not required

J. <u>Industry Support Information</u>

Not applicable.

K. Weight and Balance

(1) Weight Change

Plus 0.1lb (0,05 kg)

(2) Moment Arm

0.10 in (3,00 mm) rearwards

Apr 22/05 R Jun.20/05



(3) Datum

Engine Front Mount Centreline (Power Plant Station PPS100).

L. Electrical Load Data

The aircraft electrical load is not affected by this Service Bulletin.

M. <u>Software Accomplishment Summary</u>

Not applicable.

N. References

- (1) Engine Manual, Chapter/Section 72-41-30, Assembly.
- (2) Engineering Change No. 04VR010.
- (3) ATA Locator -72-41-30.

O. Other Publications Affected

- (1) Illustrated Parts Catalogue (IPC) will be revised
- (2) Engine Manual Chapter/Section 72-41-30, Assembly/Disassembly.
- (3) Engine Manual Chapter/Section 72-41-32 and 72-41-34, Cleaning, Inspection/Check and Repair.

P. Interchangeability of Parts

It is permissable to interchange a new vane assy and bolt for an old vane and nut on a one for one basis.



2. <u>Material Information</u>

A. The kit required consists of the following parts:

None.

B. Parts to be reworked:

None.

C. New production parts:

72-41-32

	FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
	01-500	6A8405	38	.Vane,assy VIGV Long Spindle	-	6A7723	(A)(B) (S1)
	01-600	6A8407	2	.Vane,assy VIGV Short Spindle	-	6A7725	(A)(B) (S1)
	72-41-3	4					
	FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
	02-102	4W0409	30	.Bolt, (See Appendix 5)	_	-	(A)
	02-122 02-142	4W0409 4W0409	8 2	.Bolt, (See Appendix 5) .Bolt, (See Appendix 5)	_	_	(A) (A)
D.	<u>Redunda</u>	nt Parts:					
	72-41-3	2					
	FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
	01-515 01-615		1AR 1AR	Stud Stud		UP11066 UP11066	(E)
	72-41-3	4					
	FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP

Apr 22/05 R Jun.20/05

02-103 -

30

V2500-ENG-72-0486

4W0002

(C)

.Nut



Ε

SERVICE BULLETIN

	FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP	
	02-123 02-143	<u>-</u>	8 2	.Nut .Nut	<u>-</u>	4W0002 4W0002	(C)	
Ξ.	. Reference Instructions:							
	72-41-00	D						
	FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP	
	99-201	6A8422	Ref	.Instruction, build	-	6A5561		
	72-41-21							
	FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP	
	99-201	6A8422	Ref	.Instruction, build	-	6A5561		
	72-41-32							
	FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP	
	99-201	6A8422	Ref	.Instruction, build	-	6A5561		
72-41-34								
	FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP	
	99-201	6A8422	Ref	.Instruction, build	-	6A5561		

F. <u>Instruction Disposition Codes:</u>

- (A) New part will be available from November 2004.
- (B) Part becomes redundant upon embodiment of this modification.
- (C) Part may be used up on other applications.
- (E) Part introduced by VRS6259 not required following embodiment of this modification.


Apr 22/05 R Jun.20/05



(S1) Old and new parts are not interchangeable.

Apr 22/05 R Jun.20/05


HP Compressor VIGV Vane Assembly Family Tree




led0006070

International Aero Engines...

SERVICE BULLETIN



GENERAL SECTION THROUGH HP COMPRESSOR




DIAGRAMMATIC VIEW - AA

Tdem0001943

Apr 22/05 R Jun.20/05

International Aero Engines...


SERVICE BULLETIN



GENERAL SECTION SECTION THROUGH HP COMPRESSOR BEFORE ALTERATION TYPICAL 38 POSITIONS (LONG SPINDLE)

Apr 22/05 R Jun.20/05






GENERAL SECTION SECTION THROUGH HP COMPRESSOR AFTER ALTERATION TYPICAL 38 POSITIONS (LONG SPINDLE)

Apr 22/05 R Jun.20/05






SECTION AB
BEFORE ALTERATION
TYPICAL 2 POSITIONS DESIGNATED AC
(SHORT SPINDLE)

Apr 22/05 R Jun.20/05





SECTION AB TYPICAL 2 POSITIONS DESIGNATED AC (SHORT SPINDLE)

Apr 22/05 R Jun.20/05



3. Accomplishment Instructions

A. Rework Instructions


Not applicable.

B. Dis-assembly Instructions

For the correct Dis-assembly Instructions refer to Engine Manual, Chapter/Section 72-41-30, Dis-assembly.

- C. Assembly Instructions, Refer to Fig 1.
 - (1) Install the actuating levers (72-41-34, 02-100 and 02-140). Make sure the correct actuating lever goes on the correct guide vane at positions 3 to 18.
 - (2) Install the 16 bolts (72-41-34, 02-102 and 02-142) on to the guide vanes at positions 3 to 18.
 - (3) Install the actuating lever (72-41-34, 02-120). Make sure the correct actuating lever goes on the correct guide vane at positions 1, 2, 19, 20, 21, 22, 39 and 40.
 - (4) Install the 8 bolts (72-41-34, 02-122) on to the guide vanes at positions 1, 2, 19, 20, 21, 22, 39 and 40.
 - (5) Remove the rigging pins and set the guide vanes at the null position.
 - (6) Torque the bolts to 100 lbfin. (11,50 Nm.) plus the run down torque.
- D. Recording Instructions
 - (1) A record of accomplishment is necessary.





Tded0004738

Position for the Variable Inlet Guide Vanes (VIGV) - Fig. 1

Apr 22/05 R Jun.20/05



ENGINE - HP COMPRESSOR VARIABLE VANES - INTRODUCTION OF A REVISED VIGV WITH AN OPTIMISED SPINDLE - MOD 72-0486

SUPPLEMENT - PRICES AND AVAILABILITY

The prices (if shown) are for estimating purposes only and as such are given in good faith, without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current price catalogue for current prices.

1. Modification Kit:

Not applicable.

2. Parts required:

Part No.	Description	Unit Price US Dollars
6A8405	Vane, assy - VIGV Long Spindle	854.00
6A8407	Vane, assy - VIGV Short Spindle	854.00
4W0409	Bolt	10.50

Apr 22/05 R Jun.20/05