P.O. BOX 31, DERBY

400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE:- 860 565 5515 FAX:- 860 565 0600

Printed in Great Britain

TELEGRAMS – 'ROYCAR' DERBY
TELEX – 37645
TELEPHONE: – 44 (0) 1332 242424
DATE: Jan. 6/09
FAX: – 44 (0) 1332 249936

V2500-A1 SERIES PROPULSION SYSTEM SERVICE BULLETIN

This document transmits the Initial Issue of Service Bulletin V2500-ENG-72-0570

Service Bulletin Initial Issue

Remove Incorporate Reason for change

Pages 1 to 9 of the Ir Service Bulletin

Initial Issue.

Page 1 of the Supplement

Initial Issue.

(Prices and Added Data)

V2500-ENG-72-0570
Transmittal - Page 1 of 1

CHECK THAT ALL PREVIOUS TRANSM

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England © Rolls-Royce plc (date as above) Printed in Great Britain





INFORMATION - ENGINE - PROVIDE NEW NO. 5 REAR BEARING HEAT SHIELD PART NUMBERS

1. Planning Information

- A. Effectivity
 - (1) Airbus A320
 - (a) V2500-A1 Engines from Serial No. V0001 thru V0361.
- B. Concurrent Requirements

There are no concurrent requirements.

- C. Reason
 - (1) Problem:

Fiat/Avio part numbering is not compatible with Pratt & Whitney downstream systems.

(2) Background:

Pratt & Whitney is now responsible for the manufacturing and design of several Fiat/Avio heat shields.

(3) Objective:

Replace the Fiat/Avio part numbering with Pratt & Whitney compatible part numbering.

(4) Substantiation:

The new parts are physically identical to the downchange parts with new part numbers to rectify the numbering of assemblies.

- (5) Effects of Bulletin on:
 - (a) Removal/Installation:

Not affected.

(b) Disassembly/Assembly:

Not affected.

(c) Cleaning:

Not affected.

Jan. 6/09

Jan. 6/09 Initial Issue



(d) Inspection/Check:

Not affected.

(e) Repair:

Not affected.

(f) Testing:

Not affected.

(6) Supplemental Information

None.

D. <u>Description</u>

New Pratt & Whitney part numbers are being assigned to existing parts for compatibility.

E. Compliance

Category 7

Accomplish when supply of superseded parts has been depleted.

F. Approval Data

The part number changes and/or part modifications specified in the Accomplishment Instructions and Material Information sections of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model(s) given.

G. Manpower

(1) In Service

Not Applicable.

(2) At Overhaul

Not Applicable.

H. Weight and Balance

(1) Weight Change

None.

Jan. 6/09 Jan. 6/09 Initial Issue



(2) Moment Arm

No Effect.

(3) Datum

Engine Front Mount Centerline (Power Plant Station (PPS) 100)

I. Electrical Load Data

This Service Bulletin has no effect on the aircraft electrical load.

J. Software Accomplishment Summary

Not Applicable.

K. References

- (1) V2500 Engine Illustrated Parts Catalogs (S-V2500-1IA), Chapter/Section 72-50-53 and 72-58-01.
- (2) V2500 Engine Manual (E-V2500-1IA), Chapter/Section 72-58-01.
- (3) V2500 Standard Practices/Processes Manual (E-V2500-1IA).
- (4) Internal Reference No. O5VAO64A.
- (5) ATA Locator 72-50-00.

L. Other Publications Affected

- (1) V2500 Engine Illustrated Parts Catalogs (S-V2500-1IA), Chapter/Section 72-58-01.
- (2) V2500 Engine Manuals (E-V2500-1IA), Chapter/Section 72-58-01 Cleaning, Inspection and Repair, to add the new part.

M. <u>Interchangeability of Parts</u>

Old and new parts are fully interchangeable.

N. Information in the Appendix

Alternate Accomplishment Instructions (No)

Progression Charts (No)

Revision to Table of Limits (No)

Inspection Procedures (No)

Jan. 6/09

Jan. 6/09 Initial Issue



Supplement (Yes)

Added Data (Yes)

Printed in Great Britain



2. Material Information

A. Material - Price and Availability

Modification kit is not required.

For Price and availability of spares refer to the supplement of this Service Bulletin.

B. Industry Support Program

Not Applicable.

C. The material data that follows is for each engine.

For V2500-A1 Engines:

FIG- ITEM NUMBER	NEW PART NUMBER	QTY	PART TITLE	MAT	OLD PN	INSTR - DISP
72-58-01						
01-100	2A4227-01	1	Heat Shield Assy, No. 5 Rear Bearing	. –	4T8030	(2)(A)(C) (I)(S1)
72-50-53						
01-372	2A4226-01	1	Heat Shield, Lower	-	4T8046	(2)(B)(C) (I)(S1)
01-382	2A4228-01	1	Heat Shield, Upper	-	4T8047	(2)(B)(C) (1)(S1)

D. <u>Instructions/Disposition Code Statements:</u>

Parts Modification Conditions

(2) The new part is a replacement part only, and cannot be obtained by modification of the old part.

Spare Parts Availability

- (A) The new part will be available approximately March 2009.
- (B) The new part will be available approximately May 2010.
- (C) The old part will be supplied until stock is exhausted.

Jan. 6/09

Jan. 6/09 Initial Issue



Cleaning, Inspection and Repair Information

(I) The cleaning, inspection and repair requirements are the same for the old and new part. The applicable engine manuals will be revised.

Interchangeability of Parts

(S1) Old and new parts are fully interchangeable.

E. Tooling - Price and Availability

Special tools are not required to accomplish this Service Bulletin.

F. Reidentified Parts

Not Applicable.

Reidentified Parts New PN	Data Keyword	Old PN
2A4226-01	No. 5 Rear Bearing Lower Heat Shield	4T8046
2A4228-01	No. 5 Rear Bearing Upper Heat Shield	4T8047
2A4227-01	No. 5 Rear Bearing Heat Shield Assy	4T8030

G. Other Material Information Data

Not Applicable.

Jan. 6/09


Jan. 6/09 Initial Issue

3. Accomplishment Instructions

None.

Printed in Great Britain

Jan. 6/09 Jan. 6/09 Initial Issue




LOCATION OF NO. 5 REAR BEARING HEAT SHIELD ASSEMBLY FIGURE 1

Jan. 6/09

Jan. 6/09 Initial Issue





pw0b520189

LOCATION OF NO. 5 REAR BEARING HEAT SHIELDS FIGURE 2

Jan. 6/09

Jan. 6/09 Initial Issue





INFORMATION - ENGINE - PROVIDE NEW NO. 5 REAR BEARING HEAT SHIELD PART NUMBERS

<u>Supplement</u>

1. Modification Kit

A. There is no kit provided to do this Service Bulletin.

2. Material Cost

<u>NOTE</u>: The prices shown are for estimating purposes only and as such are given in good faith without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current Price Catalog for current prices.

A. The estimated price of new material to do this Service Bulletin using new replacement parts is USD 8,016.00.

3. New Production Parts

New Production Part Number	Description	Unit Price US Dollars
2A4227-01	No. 5 Rear Bearing Heat Shield Assy	4,012.00
2A4226-01	No. 5 Rear Bearing Lower Heat Shield	2,002.00
2A4228-01	No. 5 Rear Bearing Upper Heat Shield	2,002.00

Added Data

Internal Reference Information

Revision No. Reference Document Origination

Original EC 05VA064A WC/TR

Jan. 6/09

Jan. 6/09 Initial Issue