



SERVICE BULLETIN

ENGINE - FUEL AND CONTROL - INCORPORATE A NEW ELECTRONIC ENGINE CONTROL (EEC)
CONFIGURATION - CATEGORY CODE 4 - MOD.ENG-73-0007

1. Planning Information

A. Effectivity

- (1) Aircraft: Airbus A320
- (2) Engine: All V2500 A1 Engines prior to Engine Serial Numvers V0097 except Engine Serial Number V0007, V0092 and V0095.

B. Reason

(1) Condition

The present software (SNC10B) does not give the necessary Stator Vane Actuator minimum limit protection.

(2) Background

Decrease of the N2 RPM causes the vanes to skew too far cambered.

(3) Objective

To replace the Electronic Engine Control with one that has SCN10D Software.

(4) Substantiation

Intermittent loss of N2 speed caused an engine to stall during engine test, because of vane misscheduling.

(5) Effects of Bulletin on Workshop Procedures:

Removal/Installation	Not affected
Disassembly/Assembly	Not affected
Cleaning	Not affected
Inspection/Check	Not affected
Repair	Not affected
Testing	Not affected

(6) Supplemental Information:

None.

V2500-ENG-73-0007

**C. Description**

(1) The stall problem caused by intermittent loss of N2 speed was corrected as follows:

(a) A new Electronic Engine Control with SCN10D Software is installed.

D. Approval

The Part Number Changes and/or part modifications described in Section 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Compliance

Category Code 4.

Accomplish at the first visit of an engine or a module to a maintenance base capable of compliance with the accomplishment instructions regardless of the planned maintenance action of the reason for engine removal.

F. Manpower

Estimated Manhours to incorporate the full intent of this Bulletin:

Venue	Estimated Manhours
-------	--------------------

(1) In Service

(a) To gain access	14 minutes
--------------------	-------	------------

(b) To embody	46 minutes
---------------	-------	------------

(c) To return engine to flyable status	14 minutes
--	-------	------------

TOTAL		1 hour, 14 minutes
-------	--	--------------------

(2) In Shop	Not applicable
-------------	-------	----------------

G. Material Price and Availability

(1) Modification Kit Not Required.

(2) See Material Information section for prices and availability of future spares.

H. Tooling - Price and Availability

Special tools are not required.

V2500-ENG-73-0007



SERVICE BULLETIN

I. Weight and Balance

- | | | | | | |
|-----|---------------|----|----|----|--|
| (1) | Weight change | .. | .. | .. | None |
| (2) | Moment arm | .. | .. | .. | No effect |
| (3) | Datum | .. | .. | .. | Engine front mount Centerline (Powerplant Station PPS 100) |

J. Electrical Load Data

This Service Bulletin has no effect on the aircraft electrical load.

K. References

- (1) Internal Reference No.
- 89VA119
- (2) Other References
- Hamilton Standard Service Bulletin EEC 150-73-1.
- A320 Aircraft Maintenance Manual.

L. Other Publications Affected

- (1) None.



2. Accomplishment Instructions

A. Prerequisite Instructions

- (1) Remove the PN 2A1988 or 2A1989 RElectronic Engine Control by the approved procedure in Reference (2), Chapter/Section 73-22-34, Removal/Installation. Refer to Figure 1.

B. Rework Instructions


- (1) Do a modification of the PN 2A1988 or 2A1989 Electronic Engine Control and identify as PN 2A2039 by the approved procedure in Reference (1).

C. Fitment Instructions


- (1) Install the PN 2A2039 Electronic Engine Control by the approved procedure in Reference (2), Chapter/Section 73-22-34, Removal/Installation.

D. Recording Instructions

- (1) A record of accomplishment is necessary.



REMOVE PN 2A1988 OR
PN 2A1989 ELECTRONIC
ENGINE CONTROL, DO
A MODIFICATION, IDENTIFY
AND INSTALL AS
PN 2A2039 (1 Off)



14987

Location of Electronic Engine Control
Fig.1

V2500-ENG-73-0007



SERVICE BULLETIN

3. Material Information

NEW PART NO. (ATA NO.)	QTY	EST'D UNIT PRICE (\$)	KEYWORD	OLD PART NO. (IPC NO.)	INSTRUCTIONS DISPOSITION
------------------------------	-----	-----------------------------	---------	------------------------------	-----------------------------

Applicability: For each V2500 Engine to incorporate this Bulletin.

A. Kit associated with this Bulletin:

None.

B. Parts affected by this Bulletin:

2A2039 (73-22-34)	1	Control-Electronic Engine	2A1988 (01-280) or 2A1989 (01-280)	(1D) (1D)
----------------------	---	------------------------------	--	------------------

C. Instruction/Disposition Code Statements:

(1D) A modification can be done to the Old Part and it can then be identified as the New Part Number.

NOTE: The estimated 1989 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Contact IAE's Spare Parts Sales Department for information concerning firm prices.

V2500-ENG-73-0007



**UNITED
TECHNOLOGIES
HAMILTON
STANDARD**

A320/PW

SERVICE BULLETIN

CIRCULATE PROMPTLY

ENGINE FUEL AND CONTROL - EEC150 ELECTRONIC ENGINE CONTROL
INCORPORATE NEW SOFTWARE

1. Planning Information

A. Effectivity

All Hamilton Standard Electronic Engine Controls Model EEC150 Not Incorporating Part Number:

798300-8-027

B. Reason

This product improvement change introduces a new software configuration into revenue service. The new software updates the 2.5 Bleed Logic and the Stator Vane Logic.

C. Description

Processor board assemblies are removed from the unit. New software is incorporated by reprogramming the EPROMs. Following EPROM reprogramming, the unit is assembled and tested.

D. Compliance

Category 4 - Accomplish at the first visit of an Electronic Engine Control to a maintenance shop.

NOTE: The tasks of this service bulletin must be accomplished concurrently with Service Bulletin EEC150-73-2.

E. Approval

The part number changes and part modifications described in Paragraph 2 of this service bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-Approved for the Electronic Engine Controls listed.

Jun 15/89

EEC150-73-1
Page 1 of 4



UNITED
TECHNOLOGIES
HAMILTON
STANDARD

SERVICE BULLETIN

F. Manpower

Approximately 8 man-hours are required to reprogram each unit. This includes disassembly, assembly, and testing.

G. Material - Cost and Availability

None

H. Tooling

None

I. Weight and Balance

Not Affected

J. Electrical Load Data

Not Affected

K. Reference

IAE Service Bulletin No. V2500-ENG-73-007
Hamilton Standard Service Bulletin EEC150-73-2
Component Maintenance Manual 73-22-34 (TR73-1)

EC89VA119
73-0007

L. Other Publications Affected

Component Maintenance Manual 73-22-34
Illustrated Parts Catalog 73-22-34

2. Accomplishment Instructions

- A. Reprogram the EEC using the following instructions or return the EEC, for reprogramming, to:

Pratt & Whitney Overhaul/Repair Center Europe (PWORCE)
Maastricht Airport
P.O. Box 269
6190 AG BEEK
The Netherlands



SERVICE BULLETIN

- B. Determine the requirements for service bulletin incorporation by checking the units and spare assemblies for the following part numbers:

<u>Assembly</u>	<u>HS Part Number</u>
EEC150	798300-8-XXX
Control Assembly	798199-8-XXX
Processor/Input Module-Channel A	793610-14-XXX
Processor/Input Module-Channel B	793612-14-XXX

(XXX) - indicates the software configuration

CAUTION: OBEY THE ESDS PRECAUTIONS IN REPAIR 1 OF CMM 73-22-34. THE EEC150 CONTAINS ESDS COMPONENTS WHICH MAY BE EASILY DAMAGED.

- C. Reprogram the units according to REPAIR 5 (TR73-1) of Component Maintenance Manual 73-22-34. Use the program and version number shown below with the indicated checksums.

Application Program:	Y793610
Application Version Number:	E050
Application Checksum:	B93F
.PAR Checksum:	C78E
Engine Trim Program:	Y793612
Engine Trim Version Number:	E050

NOTE: Perform the inspection described in Service Bulletin EEC150-73-2 after the unit is disassembled but before the boards are reprogrammed.



**UNITED
TECHNOLOGIES**
**HAMILTON
STANDARD**

SERVICE BULLETIN

- D. Reidentify the assemblies as shown below. Refer to REPAIR 4 (TR73-1) of Component Maintenance Manual 73-22-34 for instructions to replace the identification plates.

<u>Assembly</u>	<u>New HS Part Number</u>	<u>New IAE Part Number</u>
EEC150	798300-8-027 L6 798300-8-027 L7	2A2039E 2A2039F
Control Assembly	798199-8-027	N/A
Processor/Input Module-Channel A	793610-14-027	N/A
Processor/Input Module-Channel B	793612-14-027	N/A

3. Material Information

None

Hamilton Standard Internal Reference Number 192745-1
Hamilton Standard Document Identification Number 6323N
Pratt & Whitney Reference GES/PSH 89VA119