



ENGINE - FUEL AND CONTROL - ENGINE FUEL AND CONTROL - FUEL SYSTEM TUBES - FUEL SERVO
TUBE WITH REPOSITIONED CLIPPING LUG - CATEGORY CODE 7 - MOD.ENG-73-0053

1. Planning Information

A. Effectivity

- (1) Aircraft McDonnell Douglas MD-90
- (2) Engine V2500-D5 Engines before Serial No.V20007

B. Concurrent Requirements

None

C. Reason

(1) Condition

Insufficient access to secure clip point 7004.

(2) Background

At build of the first D5 engine it was not possible to tighten the bolt at clip point 7004. The proximity of the LH bifurcation box cross-beam precluded spannering access. The clip point secures together the servo fuel supply and return tubes between the bifurcation box and 4 way adaptor.

This was initially overcome by fitting back-to-back clipping (designated CP7004A). The tube clipping lug was retained but unused.

(3) Objective

To provide positive clip location.

(4) Substantiation

An assembly check established that the new tube with repositioned clipping lug allows spannering access.

(5) Effect of Bulletin on Workshop Procedures:

V2500-ENG-73-0053



SERVICE BULLETIN

Removal/Installation	Not affected
Disassembly/Assembly	Affected
Cleaning	Not affected
Inspection/Check	Not affected
Repair	Not affected
Testing	Not affected

(6) Supplemental Information

None

D. Description

The tube supplying fuel to the B.S.B.V. actuators is replaced by an identical tube on which the clipping lug has been repositioned.

Clip point CP7004A is replaced by CP7004.

E. Approval

The part number changes and/or part modifications described in Section 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

F. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

G. Manpower

Estimated manhours to incorporate the full intent of this Bulletin:

Venue	Estimated Manhours
(1) In Service	Not applicable
(2) At Overhaul	Not affected

H. Material – Price and Availability

(1) Modification Kit not required.

(2) See "Material Information" section for prices and availability of future spares.

I. Tooling – Price and Availability

Special tools are not required.

V2500–ENG–73–0053



SERVICE BULLETIN

J. Weight and Balance

- | | | | | | |
|-----|---------------|----|----|----|--|
| (1) | Weight change | .. | .. | .. | None |
| (2) | Moment arm | .. | .. | .. | No effect |
| (3) | Datum | | | | Engine front mount centreline
(Power Plant Station (PPS) 100) |

K. Electrical Load Data

This modification has no effect on the aircraft load.

L. References

- (1) Internal Reference No.

93VR072

- (2) Other References

The V2500 Engine Manual, Chapter/Section 72-00-32 and 72-00-42,
Removal/Installation.

The MD-90 Aircraft Maintenance Manual, Chapter/Section 73-11-49.

M. Other Publications Affected

- (1) The V2500 Illustrated Parts Catalogue Chapter/Section 73-11-49.
- (2) The V2500 Engine Manual, Chapter/Section 72-00-32 and 72-00-42.

V2500-ENG-73-0053



2. Accomplishment Instructions

A. Rework Instructions

Not applicable


B. Assembly Instructions

- (1) Install the new clipping assembly in accordance with the approved procedures, ref V2500 Engine Manual, Chapter/Section 72-00-32 and 72-00-42, Installation.

C. Recording Instructions

A record of accomplishment is necessary

V2500-ENG-73-0053



REMOVE 6A5289 AND
INSTALL 6A5370

E3383

Location of fuel servo tube
Fig.1

V2500-ENG-73-0053



SERVICE BULLETIN

3. Material Information

Applicability: For each V2500 Engine to incorporate this Bulletin.

A. Kits associated with this Bulletin:

None

B. Parts affected by this Bulletin:

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
6A5370 (73-11-49)	1	2321-00	Tube assy, fuel - LH bifurcation box to 4 way connector	6A5289 (11-100)	(A)(B)
- (73-11-49)	1		Clip CP7004A	AS62408 (11-128)	(C)(D)
4W0111 (73-11-49)	1	4-07	Bolt, bi-hex CP7004	AS21416	(A)(C)
LK53268 (73-11-49)	1	12-10	Spacer CP7004	LK67295	(A)(C)

C. Instructions/Disposition Code Statements

- (A) New part is currently available
- (B) Old part is no longer available
- (C) Old part can be used up in other applications
- (D) Deleted part

Printed in Great Britain

V2500-ENG-73-0053