

# International Aero Engines SERVICE BULLETIN

July 24/98

Subject: Transmittal of Revision 1 to Service Bulletin No. V2500-ENG-73-0084

Service Bulletin Revision History:

Event	Date
Basic Issue	Nov.8/96
Revision 1	July 24/98

Reason for Issuance of Revision:

- (1) To add Airbus comments
- (2) To correct part number at 2.B.(2) and 3.B.
- (3) Editorial changes to bring Service Bulletin up to latest standards

Effect on Past Compliance:


None

List of Effective Pages:

Bulletin Page No.	Rev. No.	Effective Date
1 to 6	1	July 24/98
7	Basic issue	Nov.8/96
8	1	July 24/98

## V2500-ENG-73-0084

Transmittal  
Page 1 of 1



# International Aero Engines SERVICE BULLETIN

ENGINE - FUEL AND CONTROL - FUEL SYSTEM TUBES -  
INTRODUCTION OF RE-ALIGNED LP FUEL TUBE  
ASSEMBLY PRODUCED FROM STAINLESS STEEL MATERIAL

## MODEL APPLICATION

V2500-A1  
V2522-A5  
V2524-A5  
V2527-A5  
V2530-A5

## BULLETIN INDEX LOCATOR

73-00-00

## Compliance Category Code

6

## Internal Reference No.

EC96VR002


Nov.8/96

R Revision 1 July 24/98

Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).

# V2500-ENG-73-0084

Page 1 of 8



# International Aero Engines SERVICE BULLETIN

## ENGINE - FUEL AND CONTROL - FUEL SYSTEM TUBES - INTRODUCTION OF RE-ALIGNED LP FUEL TUBE ASSEMBLY PRODUCED FROM STAINLESS STEEL MATERIAL

### 1. Planning Information

#### A. Effectivity

##### (1) Aircraft:

- (a) Airbus A319
- (b) Airbus A320
- (c) Airbus A321

##### (2) Engine:

- (a) V2500-A1 Engines prior to Serial No.V0362
- (b) V2522-A5 Engines prior to Serial No.V10185
- (c) V2524-A5 Engines prior to Serial No.V10185
- (d) V2527-A5 Engines prior to Serial No.V10185
- (e) V2530-A5 Engines prior to Serial No.V10185

#### B. Concurrent Requirements

Prior to or concurrently with V2500-ENG-73-0061 Service Bulletin.

#### C. Reason

##### (1) Condition


Wear of the Fuel Cooled Oil Cooler (FCOC) to diverter valve tube assembly can occur where the tube engages with the seal housing on the FCOC. In extreme cases this has resulted in fuel leaks.

R The problem is caused by a combination of the mis-alignment of the tube  
R and seal housing and the fretting resistance of the material not being  
R sufficient.

##### (2) Background

R The condition has been found on both A1 and A5 in-service engines.

Printed in Great Britain



# International Aero Engines SERVICE BULLETIN

## (3) Objective

R To prevent fuel leaks from the fuel tube assembly between the FCOC and  
R IDG.

## (4) Substantiation

R A satisfactory trial installation on a production engine has been done  
R on the changes introduced by this Service Bulletin.

## (5) Effect of Bulletin on Workshop Procedures:

Removal/Installation	Not Affected
Disassembly/Assembly	Not Affected
Cleaning	Affected
Inspection/Check	Not Affected
Repair	Not Affected
Testing	Not Affected

## (6) Supplemental Information

None.


## D. Description

R This Service Bulletin introduces a revised LP fuel tube assembly between  
R the FCOC and the diverter valve with the changes that follow:

- (a) The tube material has been changed from titanium to stainless steel.
- R (b) The ferrule has been revised to contain a centralising spigot to  
control alignment to the FCOC mounted seal housing.
- R (c) The length of the tube assembly has been increased so that more of  
R the ferrule goes into the FCOC mounted seal assembly.
- R (d) The tube assembly will be produced with more tightly controlled  
R tolerances at the tube end locations. This will make sure that the  
tube is manufactured correctly and as a result, reduce the  
possibility of misalignment.

## E. Approval

R The part number changes and/or part modification are given in Section 2 and  
R 3 of this Service Bulletin. They comply with the applicable Federal  
Aviation Regulations and are FAA-APPROVED for the engine models listed.



# International Aero Engines SERVICE BULLETIN

Printed in Great Britain

## F. Compliance

Category Code 6

R This Service Bulletin can be accomplished when the sub-assembly (That is  
R modules, accessories, components, build groups) is disassembled  
R sufficiently to get access to all the affected parts.

## G. Manpower

R Estimate of manhours necessary to embody this Service Bulletin in full:

<u>Venue</u>	<u>Estimated Manhours</u>
(1) In service	Not applicable
(2) At Overhaul	
To reduce the FCOC to diverter valve LP Fuel tube assembly	10 minutes
TOTAL	10 minutes

R NOTE: It is possible to get access to the parts affected by this Service  
R Bulletin at overhaul.

## H. Material - Price and Availability

- R (1) A modification kit not necessary.
- R (2) Refer to Section 3 Material Information for the prices and availability  
of future spares.

## I. Tooling - Price and Availability


R Special tools are not necessary.

## J. Weight and Balance

- (1) Weight change .. .. Plus 0,201b. (0.091 Kg)
- (2) Moment arm .. .. 10.0in. (254,0 mm) forward of datum
- (3) Datum .. .. Engine front mount centreline  
(Power Plant Station (PPS) 100)

## K. Electrical Load Data

This Service Bulletin has no effect on the aircraft electrical load.




## International Aero Engines SERVICE BULLETIN

### L. References

- (1) V2500 Engine Manual (E-V2500-1IA)
- (2) V2500 Component Maintenance Manual (CMM-MECH-V2500-1IA)
- (3) Standard Practices/Process Manual (SPP-V2500-1IA)
- (4) V2500-ENG-73-0061 Service Bulletin
- R (5) Aircraft Modification No.27820

### M. Other Publications Affected

- (1) The V2500 Engine Manual, (E-V2500-1IA), Chapter/Section, 72-00-32, to add new part.
- (2) The Aircraft Maintenance Manual, Chapter/Section, 72-11-47, to add new part.



## International Aero Engines SERVICE BULLETIN

### 2. Accomplishment Instructions

#### A. Rework Instructions

- (1) None.

#### B. Assembly Instructions

- R (1) Before the new fuel tube is installed, make sure that the inner diameter  
R of the 5W8201 mating seal housing has been inspected for fretting and  
wear in accordance with the appropriate inspection check. (Refer to the  
Component Maintenance Manual, Chapter/Section 73-11-49,  
Inspection/Check-02.)
- R (2) Install the new 6A6484 fuel tube. For the correct procedures, refer to  
R the A1/A5 Engine Manual (EM), Chapter/Section 72-00-32, Installation-20.


#### C. Recording Instructions

- (1) A record of accomplishment is necessary.

Printed in Great Britain



# International Aero Engines SERVICE BULLETIN



General View  
Fig 1

de0084f010

Nov.8/96


© Rolls-Royce plc

Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).

## V2500-ENG-73-0084

Page 7





# International Aero Engines SERVICE BULLETIN

## 3. Material Information

R Applicability: For each V2500 Engine for which this Service Bulletin is  
R applicable.

### A. Kits necessary for this Service Bulletin:

None

### B. Parts affected by this Service Bulletin:

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
R 6A6484 (73-11-49)	1	1004-00	Tube A/O - LP fuel FCOC to diverter valve	6A5343 (03-500)	(A)(B) (S1)(1D)

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's Spare Parts Sales Department.

### C. Instructions/Disposition Code Statements:

- R (A) New parts are currently available  
(B) Old parts are no longer available  
(S1) New part can replace old part but old part cannot replace new part  
(1D) Old part becomes redundant on incorporation of this modification.

Printed in Great Britain