



ENGINE - FUEL AND CONTROL - ENGINE - INSPECTION OF V2500-A1, A5 FUEL MANIFOLDS FOR TYPE
OF BRAZE USED AT FERRULE/MANIFOLD JOINT - CATEGORY CODE 4 - MOD.ENG-73-0134

Printed in Great Britain

1. Planning Information

A. Effectivity

- (1) Aircraft: Airbus A319, A320, A321
- (2) Engine: V2500-A1 Engines before Serial No. V0362
V2522-A5 Engines before Serial No. V10435
V2524-A5 Engines before Serial No. V10435
V2527-A5 Engines before Serial No. V10435
V2527E-A5 Engines before Serial No. V10435
V2530-A5 Engines before Serial No. V10435
V2533-A5 Engines before Serial No. V10435

B. Reason

To provide traceability of Fuel Nozzles with Gold/Nickel Braze.

C. Compliance

Category 4

Accomplish when the subassembly (i.e. modules, accessories, components, build groups) is disassembled sufficiently to afford access to the affected part and to all affected spare parts.

NOTE: This Inspection and Identification is to be preformed when the engine is in the shop.

D. Approval

The 'compliance' statement and the procedures described in paragraph F of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-Approved for the Engine Model listed.

E. References

- (1) V2500 Standard Practices Manual (SPM) (SPP-V2500-1I-A) Chapter/Section 70-23-05.

F. Action

Use one of the following Inspection procedures to identify manifolds having Gold/Nickel braze.

V2500-ENG-73-0134



SERVICE BULLETIN

NOTE: Applicable part numbers for pre Service Bulletin 73-0088 are 2A0504-01, 2A0508-01, 2A0509-01, 2A0510-01, and 2A0516-01.

NOTE: Applicable part numbers for post Service Bulletin 73-0088 are 2A3229-01, 2A3230-01, 2A3231-01, 2A3232-01, and 2A3236-01.

(1) Procedure for inspection by use of chemical stripping technique. See figure 1.

(a) Clean the braze area on the manifold at the flowdivider valve end.
See figure 2,

1 Degrease per SPM 70-11-03.

2 Clean to remove varnish and carbon per SPM 70-11-13-203.

3 Scrub braze joint area with CoMat 05-126, scotchbrite.

(b) Prepare the following stripping solution in a suitable container:

WARNING: REFER TO THE MANUFACTURES/SUPPLIERS MATERIAL PARTS SHEET FOR INSTRUCTIONS ON HOW TO USE THIS MATERIAL SAFELY.

WARNING: ALWAYS WEAR PROTECTIVE CLOTHING WHEN WORKING WITH CHEMICALS

Gold-Nickel Braze Stripping Solution

Material	Make-Up	Preparation
Tap Water	50% by volume	1. Fill 50% of operating volume of container with tap water.
Nitric Acid CoMat 01-025 or Equivalent	50% by volume	2. Fill the remaining 50% of operating volume of container with nitric acid, slowly and cautiously.
		3. Stir to mix.
Ferric Chloride CoMat 01-1003 or Equivalent	9.0 grams per US Gallon/(3.79 liter)	4. Add required amounts of ferric chloride and copper sulfate.
		5. Stir to mix thoroughly.
Copper Sulfate Powder CoMat 01-362 or Equivalent	16.0 grams per US Gallon/(3.79 liter)	

V2500-ENG-73-0134

**SERVICE BULLETIN**

- (c) Use a cotton swab to wipe the braze, at the flowdivider valve end only, with the Gold/Nickel braze stripping solution. See figure 2.
 - (d) Allow the solution to remain on the surface for approximately 30 seconds, then remove the solution by thoroughly rinsing with clean water.
 - (e) Visually inspect the braze surface. Gold/Nickel braze will distinctively look gold in color, while Nickel braze will continue to have a silver color.
 - (f) Manifolds with Nickel braze must be removed from service.
 - (g) Incorporate Service Bulletin 73-0088 for Manifold Assemblies part number 2A0504-01, 2A0508-01, 2A0509-01, 2A0510-01, and 2A0516-01 having Gold/Nickel braze.
 - (h) Identify manifolds with Gold/Nickel braze by the procedure given in SPM 70-09-00 and Table 1, then return to service.
- (2) Procedure for inspection by use of radiographic technique (x-ray).
- (a) X-ray the braze area of the manifold.
- NOTE: X-ray the Manifold at the flowdivider valve end only. There is no concern at the ends where the manifold connects to the fuel nozzles.
- (b) Inspect the radiograph,
 - 1 A Gold/Nickel braze fitting, which has a higher density than the tube material, will have two rings of braze material (shown as white rings), visible on the radiograph.
 - 2 A Nickel Braze fitting is all the same density and there are no distinguishable rings visible on the radiograph.
 - (c) Manifolds with Nickel braze must be removed from service.
 - (d) Incorporate Service Bulletin 73-0088 for Manifold Assemblies part number 2A0504-01, 2A0508-01, 2A0509-01, 2A0510-01, and 2A0516-01 having Gold/Nickel braze.
 - (e) Identify manifolds with Gold/Nickel braze by the procedure given in SPM 70-09-00 and Table 1, then return to service.


V2500-ENG-73-0134



G. Identify Manifolds that have Gold/Nickel braze and return to service.

Old Part Number	New Part Number
2A3229-01	2A3229-001
2A3230-01	2A3230-001
2A3231-01	2A3231-001
2A3232-01	2A3232-001
2A3236-01	2A3236-001

Manifold Assemblies with Gold/Nickel Braze
Table 1




de000e8024

TYPICAL VIEW OF FUEL NOZZLE SUPPLY MANIFOLD ASSEMBLY
AT FLOWDIVIDER VALVE END

Inspection of the Fuel Nozzle Supply Manifold Assembly
Fig.1

V2500-ENG-73-0134



de000e8025

Printed in Great Britain

Typical Manifold Assembly
Fig.2

V2500-ENG-73-0134



International Aero Engines

SERVICE BULLETIN

Printed in Great Britain

V2500-ENG-73-0134

Mar.26/99

Page 7

