

628 Hebron Avenue, Suite 400 Glastonbury, CT 06033, USA. Tel: +1 (860) 368-3823 Fax: +1 (860) 755-6876

DATE: Nov. 17/11

## V2500-A1 SERIES PROPULSION SYSTEM SERVICE BULLETIN

This document transmits the Revision 4 of Service Bulletin V2500-ENG-75-0001.

# **Document History**

Service Bulletin Revision Status

Initial Issue Apr.13/90. Revision 1 Jan.18/91. Revision 2 Nov.30/05. Revision 3 Jul. 8/11.

## Service Bulletin Revision 4

Remove Incorporate Reason for change

All Pages of the Pages 1 to 12 of the To update the Material

Service Bulletin. Service Bulletin. Information.

All Pages of the Page 1 of the No change.

Supplement. Supplement.

V2500-ENG-75-0001

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED If any have not been received please advise IAE International Aero Engines AG



## AIR - INTRODUCE A REVISED LPT ACC SUPPORT ASSEMBLY CONFIGURATION

	- 1			
Ί.	Plan	nıng	Infor	nation

- A. <u>Effectivity</u>
  - (1) Airbus A320
    - (a) V2500-A1 Engines prior to Serial No.V0073.
- B. Concurrent Requirements

None.

- C. Reason
  - (1) Condition

The current LP Turbine-ACC support assemblies configuration standard leads to long installation times.

(2) Background

This has been identified during engine build.

(3) Objective

The changes in configuration introduced by this bulletin are to ease assembly of the LP Turbine ACC system in order to reduce assembly time.

(4) Substantiation

Testing of the new ACC configuration was not required.

- (5) Effect of Bulletin on:
  - (a) Operation

Not affected.

(b) Maintenance

Not affected.

(c) Overhaul

Affected (Refer to paragraph 1.0. Other Publications Affected).

Apr.13/90 Nov.17/11 Revision 4



(d) Repair Schemes

Affected (Refer to paragraph 1.C.(6) Supplemental Information).

(e) Interchangeability

Not affected.

(f) Fits and Clearances

Not affected.

## (6) Supplemental Information

- (a) The Post-Service Bulletin configuration requires new assembly/disassembly procedures of ACC support assemblies on to/from the LPT cooling air duct assy.
- (b) The cleaning procedure for the Post-Service Bulletin configuration requires same standard practices to be used but support and half loop clamp will be cleaned in preassembled configuration.
- (c) The Post-Service Bulletin configuration requires inspection of the riveted connection.
- (d) The Post-Service Bulletin configuration requires a new repair scheme for replacement of rivets and riveted details.

## D. <u>Description</u>

The changes introduced by this Service Bulletin are as follows:

The supports A/O and half loop clamps are preassembled with rivets at the front and rear ends.

Clip nuts are attached to the half loop clamps.

The supports have clip nuts at the front LP Turbine case attaching location.

# E. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

# F. Approval

The part number changes and/or part modification described in Section 2 and 3 of this Service Bulletin has been shown to comply with the applicable Federal Aviation Regulations and is FAA-APPROVED for the engine model listed.

Apr.13/90 Nov.17/11 Revision 4



## G. Manpower

(1) In Service

Not applicable

(2) At Overhaul

The modified LPT ACC support assembly will take 20 minutes less to install.

<u>NOTE</u>: The parts affected by this Service Bulletin are accessible at overhaul.

# H. Material Price and Availability

Modification kit not required; parts supplied as single line items.

For prices and availability of future spares refer to the Supplement of this Service Bulletin.

## I. Tooling Price and Availability

Not applicable.

## J. <u>Industry Support Information</u>

Not applicable.

# K. Weight and Balance

(1) Weight Change

None.

(2) Moment Arm

No effect.

(3) Datum

Engine front mount centerline (Power Plant Station (PPS) 100).

## L. Electrical Load Data

This Service Bulletin has no effect on the aircraft electrical load.

# M. <u>Software Accomplishment Summary</u>

Not applicable.

Apr.13/90 Nov.17/11 Revision 4



## N. References

- (1) Internal Reference Nos. EC 87VM010, 88VM038, 87VM010-01 and 87VM010-02.
- (2) Engine Illustrated Parts Catalog, Chapter 75-24-49.
- (3) Aircraft Maintenance Manual, Chapter 75-24-49.
- (4) Engine Manual, Chapter 72-00-50.
- (5) ATA Locator 75-24-49.

## O. Other Publications Affected

- (1) Illustrated Parts Catalogue Chapter/Section 75-24-49, Figures 02, 03 and 04.
- (2) The V2500 Component Maintenance Manual, Tubes, Hoses and Ducts THD-V2500-1IA and THD-V2500-3IA, Chapter/Section 75-24-49 Disassembly/Assembly, will be revised to show the change introduced by this Service Bulletin.
- (3) V2500 Engine Manual, Chapter/Section 72-00-50 Removal O1 and Installation O7, will be revised to show the change introduced by this Service Bulletin.

## P. Interchangeability of Parts

Affected (Refer to paragraph 2.F. Instruction disposition codes).



# 2. <u>Material Information</u>

# A. The kit required consists of the following parts:

Not applicable.

# B. Parts to be reworked

Not applicable.

# C. New production parts:

Refer to the Supplement of this Service Bulletin

## D. Redundant parts

None.

# E. Parts affected by this Service Bulletin:

75-24-49

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	OLD PART NO.	INSTR DISP
02-490 02-590	3A1749 	1 1 1	.Support, AssyClamp, A/O Half Loop	3A0564 3A0948	(A)(S1)(1D) (B)
02-560 02-450	3A1742 -	10	Clamp, A/O Half Loop .Nut, Option	- 776440	(F)
02-497	- 4W0043	10	Nut, A/O Self Locking	770440	(C)
02-080	-	4	.Nut, Option	776440	(F)
02-495	ST1300-14	2	Rivet, Blind	-	(c)
02-460	_	10	.Bolt, Machine Double Hex	MS9696-06	(F)
02-460	4W0101	8	.Bolt, Machine Double Hex Hd	-	(C)
02-720	3A1752	1	.Support, Assy	3A0580	(A)(S1)(1D)
02-750	3A1742	1	Clamp, A/O Half Loop	-	
02-770	-	1	Clamp, A/O Half Loop	3A0948	(B)
02-670	-	10	.Nut, Option	776440	(F)
	4W0043	10	Nut, A/O Self Locking	-	(C)
02-730	ST1300-14	2	Rivet, Blind	_	(C)
02–680	_	10	.Bolt, Machine Double Hex Hd	MS9696-06	(F)
02-680	4W0101	8	.Bolt, Machine Double Hex Hd	-	(C)
03-490	3A1762	1	.Support, Assy	3A0573	(A)(S1)(1D)
03-590		1	Clamp, A/O Half Loop	3A0948	(B)
03-560	3A1742	1	Clamp, A/O Half Loop		
03-450		10	Nut, Option	776440	(F)

Apr.13/90

Nov.17/11 Revision 4



FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	OLD PART NO.	INSTR DISP
03-507	4W0043	10	Nut, A/O Self Locking		(c)
03-080		4	Nut, Option	776440	(F)
03-505	ST1300-14	2	Rivet, Blind		(C)
03-460		10	.Bolt, Machine Double Hex	MS9696-06	(F)
03-460	4W0101	8	.Bolt, Machine Double Hex Hd		(C)
03-720	3A1759	1	.Support, Assy	3A0677	(A)(S1)
03-770		1	.Clamp, A/O Half Loop	3A0948	(B)
03-740	3A1742	1	.Clamp, A/O Half Loop		
03-670		10	.Nut, Option	776440	(F)
03-727	4W0043	10	Nut, A/O Self Locking		(C)
03-080		4	Nut, Option	776440	(F)
03-725		2	Rivet, Blind		(C)
03-680		10	.Bolt, Machine Double Hex	MS9696-06	(F)
05 000		10	Hd	1137070 00	(1)
03-680	4W0101	8	.Bolt, Machine Double Hex Hd		(C)
04-010	3A1745	1	.Support, Assy	3A0568	(A)(C)
					(S1)(1D)
04-280		2	.Clamp, A/O Half Loop	3A0948	(B)
	3A1742	1	.Clamp, A/O Half Loop		
04-215	3A1744	1	.Clamp, A/O Half Loop		(E)
04-230		20	Nut, Option	776440	(F)
	4W0043	18	Nut, A/O Self Locking		(C)
04-070		2	Nut, Option	776440	(F)
04-110	ST1300-14	4	Rivet, Blind		(C)
04-240		20	.Bolt, Machine Double Hex	MS9696-06	(F)
04-240	4W0101	16	Bolt, Machine Double Hex H	d	(C)
04-410	3A1755	1	.Support, Assy	3A0577	(A)(S1)(1D)
04-680		2	.Clamp, A/O Half Loop	3A0948	(B)
04-610	3A1742	1	.Clamp, A/O Half Loop		
04-620	3A1744	1	.Clamp, A/O Half Loop		(E)
04-630		20	Nut, Option	766440	(F)
04-597	4W0043	18	Nut, A/O Self Locking		(C)
04-470		2	Nut, Option	776440	(F)
04-595	ST1300-14	4	Rivet, Blind		(C)
04-640		20	.Bolt, Machine Double Hex	MS9696-06	(F)
04-640	4W0101	16	Hd .Bolt, Machine Double Hex Hd		(C)

# F. <u>Instructions disposition codes:</u>

(A) Old Part is not longer available for sale.

Apr.13/90 Nov.17/11 Revision 4

R



- (B) Part is available for sale until stock is exhausted.
- (C) New Part currently available for sale.
- (E) Old Part is not longer available for sale. New part belongs to the new support assembly, and are available for sale as a single line item.
- (F) Old Part is available for other applications.
- (S1) Parts are interchangeable as a set by Support/Bracket Location.
- (1D) Old Part can not be reworked.



## 3. Accomplishment Instructions

A. Rework Instructions

Not applicable.

B. Assembly Instructions


For assembly instructions refer to the Component Maintenance Manual Pub.Ref.No. THD-V2500-1IA for A1/A5 Engines and Pub.Ref. No.THD-V2500-3IA for D5 Engines.

C. Recording Instructions

A record of accomplishment is required.

Apr.13/90 Nov.17/11 Revision 4






Location of LP Turbine Support Assemblies Fig.1

Apr.13/90 Nov.17/11 Revision 4






Removal and Installation of Support Assemblies Fig.2

Apr.13/90 Nov.17/11 Revision 4






Removal and Installation of Support Assemblies Fig.3 (sheet 1 of 2)

Apr.13/90 Nov.17/11 Revision 4





Removal and Installation of Support Assemblies Fig.3 (sheet 2 of 2)

Apr.13/90 Nov.17/11 Revision 4



## AIR - INTRODUCE A REVISED LPT ACC SUPPORT ASSEMBLY CONFIGURATION

## SUPPLEMENT - PRICES AND AVAILABILITY

The prices shown are for estimating purposes only and as such are given in good faith, without commercial liability for advanced planning purposes only. Refer to IAE spares and/or current price catalogue for current prices.

# 1. Modification Kit:

Not applicable.

# 2. Parts required:

Part No.	Description	Unit Price US Dollars
3A1749	Support, Assy	2,361.00
3A1742	Clamp, A/O Half Loop	1,565.00
4W0043	Nut, A/O Self Locking	5.01
ST1300-14	Rivet, Blind	10.90
4W0101	Bolt, Machine, Dbl Hx Hd	13.60
3A1752	Support, Assy	1,914.00
3A1759	Support, Assy	2,337.00
3A1745	Support, Assy	3,685.00
3A1744	Clamp, A/O Half Loop	931.00
3A1755	Support, Assy	3,270.00
3A1762	Support, Assy	2,642.00
3A0948	Clamp, A/O Half Loop	408.00

Parts are currently available for sale.



# SERVICE BULLETIN FEEDBACK FORM

Please use this form to give feedback on the quality of this Service Bulletin. The input you provide will be used to analyse areas of improvement and to take action to further improve on the quality of our Service Bulletins.

We thank you for the time you spent in completing this form.

Please rate on a scale of 1 to 5, with 5 being the highest score:

General quality rating of this Service BulletinQuality rating of the Accomplishment Instructions

- Quality rating of the Illustration

- Is this Service Bulletin easy to understand?					
If you have had difficulties to description of the issue:	perform this Service Bullet	in please quote below the a	area(s) and give a short		
Planning Information Section:		Material Information Section:	Accomplishment Instruction Section:		
□ 1.A.	□ 1.I.	□ 2.A.	☐ General		
□ 1.B.	☐ 1.J.	□ 2.B.	☐ Get Access		
□ 1.C.	□ 1.K.	□ 2.C.	☐ Removal/Installation		
□ 1.D.	□ 1.L.	□ 2.D.	☐ Inspection		
□ 1.E.	□ 1.M.	□ 2.E.	☐ Test		
□ 1.F.	□ 1.N.	□ 2.F.	☐ Close the Access		
☐ 1.G.	<u> </u>		☐ Log Book Entry		
□ 1.H	☐ 1.P.				
Explanatory notes:					
Operator:		Overhaul Site:			
Name/Title:		Date:			
			<b>,</b>		

Please send the completed Service Bulletin Feedback Form to IAE, Customer Support. Email: GPIAECUSTCOM@IAEV2500.COM

Nov.17/11 Revision 4 IAE PROPRIETARY INFORMATION © IAE International Aero Engines AG. All rights reserved.

V2500-ENG-75-0001 Page 1 of 1

5

5

4

2

3