

SERVICE BULLETIN

AIR - ENGINE - DEDICATED ALTERNATOR - COOLING AIR SUPPLY - CATEGORY CODE 5 -
MOD.ENG-75-0010

1. Planning Information

Effectivity

- (1) Aircraft: Airbus A320
- (2) Engine: V2500-A1 Engine Serial No. prior to V0122

B. Reason

(1) Condition

Potential overheating of the dedicated alternator.

(2) Background

Engine flight and supplier rig testing has shown that the temperatures being reached by the dedicated alternator stator windings are higher than the continuous rated temperature of the bonding material used.

(3) Objective

To maintain the temperature of the dedicated alternator at an acceptable level.

(4) Substantiation

The changes introduced by this modification have been shown by over 500 hours of development testing to achieve the required reduction in temperature.

(5) Effect of bulletin on workshop procedures

Removal/Installation	Affected
Disassembly/Assembly	Not affected
Cleaning	Affected
Inspection/Check	Affected
Repair	Not affected
Testing	Not affected

(6) Supplemental Information

None

V2500-ENG-75-0010

**C. Description**

(1) The changes introduced by this Service Bulletin are as follows:

- (a) A new dedicated alternator is introduced having an integral cooling air manifold.
- (b) A new, 5 piece, cooling air supply tube is introduced to supply air from the number 1 strut diagnostic air tapping point to the manifold.
- (c) A new, double ended, number 1 strut diagnostic air tapping connector is introduced to connect the new cooling air system.

D. Approval

The part number changes described in sections 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model listed.

E. Compliance

Category Code 5

Accomplish when the engine is disassembled sufficiently to afford access to the affected sub-assembly (i.e. modules, accessories, components, build groups) and to all affected spare sub-assemblies.

F. Manpower

Estimated manhours to incorporated the full intent of this bulletin.

Venue	Estimated Manhours
(1) In service	TOTAL 1 hour 7 minutes
(a) To gain access	
(i) Open fan cowl doors ..	7 minutes
(b) To embody	
(i) Refer to Estimated Manhours quoted for Overhaul	52 minutes
(ii) Reworking of EDA to air cooled standard ..	Refer to Dowty Smiths Service Bulletin 1664-73-001
(c) To return engine to flyable status	

V2500-ENG-75-0010



SERVICE BULLETIN

- (i) Close fan cowl doors .. 8 minutes
- (2) At overhaul TOTAL 52 minutes
- (a) To gain access
 - (i) Remove engine dedicated alternator 6 minutes
 - (ii) Remove fan exist pressure boss and prepare fan case flange for new bracketry 11 minutes
 - TOTAL 17 minutes
- (b) To embody - Not applicable (No rework required)
- (c) To return to modular condition
 - (i) Install new pressure boss and cooling air supply tubes 28 minutes
 - (ii) Install engine dedicated alternator 7 minutes
 - TOTAL 35 minutes

G. Material - Price and Availability

- (1) Details of the Modification kit, allowing reworking of an EDA, can be seen in Dowty Smiths Service Bulletin 1664-73-001.
- (2) See 3. 'Material Information' for prices and availability of future spares.

H. Tooling - Price and Availability

Special tools are not required.

I. Weight and Balance

- (1) Weight change Plus 3.5 lb (1,59 kg.)
- (2) Momemt arm 6.300in. (160 mm.) forward of datum
- (3) Datum Engine front mount centre line (Power Plant Station (P.P.S. 100))

V2500-ENG-75-0010



J. Electrical Load Data

This Service Bulletin has no effect on the aircraft electrical load.

K. References

(1) Internal Reference No.

ECM89VR011

ECM89VR011A

(2) Other References

A320 Aircraft Maintenance Manual


IAE V2500 Service Bulletin Number

V2500-ENG-71-0065.


Dowty Smiths Service Bulletin Number 1664-73-001

L. Other Publications Affected

- (1) V2500 Illustrated Parts Catalog, 71-51-41, 71-51-43, 72-32-85, 73-11-47, 73-22-38, 75-22-49, 79-22-49.
- (2) V2500 Engine Manual, 72-00-32, Removal-02, 03 and 05, Installation 01, 03 and 04, 72-00-60, Removal-02 and 05, Installation 03 and 05.
- (3) V2500 Engine Maintenance Manual, 73-22-38, Removal/Installation.
- (4) V2500 Component Maintenance Manual, 72-51-41, 73-11-47, 75-22-49, Cleaning and Inspection/Check.



UNDERSIDE VIEW




REMOVE PMA1664 Mk2 AND
INSTALL PMA1664 Mk3

REMOVE 4P0153 BOLTS (3 off) AND
INSTALL AS32218 BOLTS (3 off)

B3006

Location of dedicated alternator (stator)
Fig.1



V2500-ENG-75-0010



VIEW AT AB
AFTER ALTERATION


View sharing air cooling tubes and clipping points - After alteration
Fig.2

dec0001158




ded0001159

Clipping points - After alteration
Fig.3




View showing air cooling tubes and clipping points - After alteration
Fig.4

V2500-ENG-75-0010




CLIP POINT 1101
AFTER ALTERATION



Clipping points - Before and after alteration
Fig.5

ded0001161



VIEW AT AD



View showing air cooling tube and clipping points - After alteration
Fig.6

V2500-ENG-75-0010



SERVICE BULLETIN

Printed in Great Britain


CLIP POINTS 0849 0851 & 0852
BEFORE AND AFTER ALTERATION

CLIP POINT 0853

Clipping points - Before and after alteration
Fig.7

ded0001163



V2500-ENG-75-0010



VIEW ON ARROW AE


View showing air cooling tubes and clipping points - After alteration
Fig.8

V2500-ENG-75-0010



Clipping points - Before and after alteration
Fig.9

ded0001165



VIEW AT AF


View showing air cooling tube and clipping points - After alteration
Fig.10

V2500-ENG-75-0010




SERVICE BULLETIN

Printed in Great Britain



CLIP POINT 0845
BEFORE AND AFTER ALTERATION




CLIP POINT 0779

Clipping points - Before and after alteration
Fig.11



ded0001471

V2500-ENG-75-0010



View showing the dedicated alternator - Before and after alteration
Fig.12




V2500-ENG-75-0010



ded0001168

Fan exit pressure boss - Before alteration
Fig.13

V2500-ENG-75-0010



Fan exit pressure boss - Before and after alteration
Fig.14

V2500-ENG-75-0010



2. Accomplishment Instructions

A. Prerequisite Instructions

- (1) Open the fan cowls in accordance with the instructions in the A320 Aircraft Maintenance Manual, 71-13-00-010-010.

B. Removal Instructions

- (1) Remove the engine dedicated alternator (E.D.A.) stator 1664 Mk2 as instructed in the Aircraft Maintenance Manual, TASK 73-22-38-000-010.
- (2) Disconnect the nut connecting tube 6A2135 to the fan exit pressure boss 5A9518, remove the bolts 4W0107 (3 off) securing the fan exit pressure boss to the fan case (refer to Figure 13) and remove the fan exit pressure boss.

C. Rework Instructions

- (1) Reworking of an EDA to air cooled standard is described in detail in Dowty Smiths Service Bulletin 1664-73-001.

D. Assembly Instructions

- (1) Install and secure the new fan exit pressure boss 5A0413 and connect the tube 6A2135 (refer to Figure 13).
- (2) Install the tube 6A2164; support at CP1114, CP1115 and CP1100 (refer to Figures 2 and 3) and connect to the exit pressure boss.
- (3) Install the tube 6A2155; support at CP1101 and CP1102 (refer to Figures 2, 4 and 5) and connect to tube 6A2164.
- (4) Install the tube 6A2157; support at CP1103, CP0853, CP0852 and CP0851 (refer to Figures 4, 5, 6 and 7) and connect to tube 6A2155.
- (5) Install the tube 6A2156; support at CP0849, CP0893, CP0847, CP0846, CP0845 and CP0779 (refer to Figures 7, 8, 9, 10 and 11) and connect to tube 6A2157.
- (6) Install the tube 6A2159 (refer to Figure 12) and connect to tube 6A2156.
- (7) Install the engine dedicated alternator stator 1664 Mk3 as instructed in the Aircraft Maintenance Manual, TASK 73-22-38-400-010 and connect tube 6A2159 (refer to Figure 12).

E. Post Requisite Instructions

- (1) Close the fan cowls in accordance with the instructions in the A320 Aircraft Maintenance Manual, 71-13-00-410-010.



International Aero Engines

SERVICE BULLETIN

F. Recording Instructions

- (1) Record in the Engine Log that this Service Bulletin has been incorporated.

Printed in Great Britain

V2500-ENG-75-0010

Jan.31/92

Page 20



SERVICE BULLETIN

3. Material Information

Applicability: For each V2500 Engine to incorporate this Bulletin.


A. Kits associated with this Bulletin:

- (1) Dowty Fuel Systems Modification kit DTV020 (parts detailed in Dowty Smiths Service Bulletin 1664-73-001).

B. Parts affected by this Bulletin:

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
4W0118 (71-51-41)	1	2.19	Bolt, bihex hd (0.190 dia x 1.438) CP0779	4W0116 (01-790)	(A)(D)
4W0104 (71-51-43)	1	3.30	Bolt, bihex hd (0.190 dia x 0.562) CP0845	4W0103 (01-214)	(A)(D)
4W0001 (71-51-43)	1	5.37	Nut, bihex (0.190 dia) CP0845	AS41104 (01-221)	(A)(D)
4W0104 (71-51-43)	1	3.30	Bolt, bihex hd (0.190 dia x 0.562) CP0846	4W0103 (01-222)	(A)(D)
4W0001 (71-51-43)	1	5.37	Nut, bihex (0.190 dia) CP0846	AS41104 (01-229)	(A)(D)
4W0104 (71-51-43)	1	3.30	Bolt, bihex hd (0.190 dia x 0.562) CP0847	4W0103 (01-230)	(A)(D)
4W0001 (71-51-43)	1	5.37	Nut, bihex (0.190 dia) CP0847	AS41104 (01-237)	(A)(D)
4W0104 (71-51-43)	1	3.30	Bolt, bihex hd (0.190 dia x 0.562) CP0849	4W0103 (01-246)	(A)(D)
4W0104 (71-51-43)	1	3.30	Bolt, bihex hd (0.190 dia x 0.562) CP0851	4W0103 (01-262)	(A)(D)
4W0104 (71-51-43)	1	3.30	Bolt, bihex hd (0.190 dia x 0.562) CP0852	4W0103 (01-270)	(A)(D)
4W0001 (71-51-43)	1	5.37	Nut, bihex (0.190 dia) CP0852	AS41104 (01-277)	(A)(D)
4W0117 (71-51-43)	1	7.16	Bolt, bihex hd (0.190 dia x 1.375)	AS21420 (01-278)	(A)(D)

V2500-ENG-75-0010



SERVICE BULLETIN

UP10481 (71-51-43	1	-	CP0853 Spacer (20 mm.)	-	(A)(C)(E)
4W0001 (71-51-43)	1	5.37	CP0853 Nut, bihex (0.190 dia)	(01-283) AS41104 (01-285)	(A)(D)
4W0104 (71-51-43)	1	3.30	CP0853 Bolt, bihex hd (0.190 dia x 0.562)	- (01-470)	(A)(C)
SP154D (71-51-43)	1	-	CP0893 Washer	- (01-471)	(A)(C)
JM44LC39H1 03RG (71-51-43)	1	3.03	CP0893 Clip, loop	- (01-473)	(A)(C)
4W0001 (71-51-43)	1	5.37	CP0893 Nut, bihex (0.190 dia)	- (01-477)	(A)(C)
740-5492- 501 (71-51-43)	4	-	CP0893 Bracket	- (05-800)	(A)(C)
AS20625 (71-51-43)	2	1.60	CP0849, CP0851, CP0852, CP0853 Nut, bihex (0.250 dia)	- (05-801)	(F)
AS21510 (71-51-43)	4	3.76	CP0849 Bolt, bihex hd (0.250 dia x 0.625)	- (05-804)	(F)
- (71-51-43)	1	-	CP0849, CP0851 Nut, bihex (0.250 dia)	AS20625 (05-871)	(F)
- (71-51-43)	1	-	CP1103 Washer	SP155E (05-872)	(F)
- (71-51-43)	1	-	CP1103 Bolt, bihex hd (0.250 dia x 0.750)	AS21512 (05-874)	(F)
- (71-51-43)	4	-	CP1103 Bracket	740-5425- 505 (05-970)	(G)
- (71-51-43)	2	-	CP0849, CP0851, CP0852 CP0853 Nut, bihex (0.250 dia)	AS20625 (05-971)	(D)(H)(F)
- (71-51-43)	4	-	CP0849 Bolt, bihex hd (0.250 dia x 0.625)	AS21510 (05-974)	(D)(H)(F)
5A0413 (72-32-85)	1	-	CP0849, CP0851 Boss, pressure cooling air fan exit	5A9518 (02-100)	(D)(A)

Printed in Great Britain

V2500-ENG-75-0010



SERVICE BULLETIN

Printed in Great Britain

6A2158 (73-11-47)	1	7.46	Bracket CP1102	- (01-940)	(A)(C)
1664 Mk.3 (73-22-38)	1		Stator - Dedicated alternator	1664 Mk.2 (01-100)	(B)
AS32218 (73-22-38)	3		Bolt, 'D' head (0.250 dia x 1.125)	4P0153 (01-106)	(A)(D)
6A3126 (75-22-49)	3	5.50	Bracket CP1100, CP1101, CP1114	- (15-070)	(A)(C)
4W0002 (75-22-49)	6	6.63	Nut, bihex (0.250 dia) CP1100, CP1101, CP1114	- (15-071)	(A)(C)
4W0164 (75-22-49)	6	3.76	Bolt, bihex hd (0.250 dia x 0.625) CP1100, CP1101, CP1114	- (15-074)	(A)(C)
6A2165 (75-22-49)	1	6.67	Bracket (0.250 dia) CP1115	- (15-080)	(A)(C)
4W0002 (75-22-49)	2	6.63	Nut, bihex (0.250 dia) CP1115	- (15-081)	(A)(C)
4W0164 (75-22-49)	2	3.76	Bolt, bihex hd (0.250 dia x 0.625) CP1115	- (15-084)	(A)(C)
6A2164 (75-22-49)	1	688.00	Tube a/o, cooling air	- (15-100)	(A)(C)
4W0102 (75-22-49)	1	3.30	Bolt, bihex hd (0.190 dia x 0.438) CP1100	- (15-141)	(A)(C)
K8831 (75-22-49)	1	0.13	Washer CP1100	- (15-142)	(A)(C)
400WSS8 (75-22-49)	1	5.21	Clip, loop type CP1100	- (15-144)	(A)(C)
4W0043 (75-22-49)	1	1.76	Nut, clip (0.190 dia) CP1100	- (15-148)	(A)(C)
4W0102 (75-22-49)	1	3.30	Bolt, bihex hd (0.190 dia x 0.438) CP1114	- (15-149)	(A)(C)
K8831 (75-22-49)	1	0.13	Washer CP1114	- (15-150)	(A)(C)
400WSS8 (75-22-49)	1	5.21	Clip, loop type CP1114	- (15-152)	(A)(C)
4W0043 (75-22-49)	1	1.76	Nut, clip (0.190 dia) CP1114	- 15-156)	(A)(C)
4W0102 (75-22-49)	1	3.30	Bolt, bihex hd (0.190 dia x 0.438) CP1115	- (15-157)	(A)(C)
K8831 (75-22-49)	1	0.13	Washer CP1115	- (15-158)	(A)(C)

V2500-ENG-75-0010



SERVICE BULLETIN

400WSS8 (75-22-49)	1	5.21	Clip, loop type CP1115	- (15-160)	(A)(C)
4W0043 (75-22-49)	1	1.76	Nut, clip (0.190 dia) CP1115	- (15-164)	(A)(C)
6A2155 (75-22-49)	1	459.00	Tube a/o, cooling air	- (15-500)	(A)(C)
4W0102 (75-22-49)	1	3.30	Bolt, bihex hd (0.190 dia x 0.438) CP1101	- (15-525)	(A)(C)
K8831 (75-22-49)	1	0.13	Washer CP1101	- (15-526)	(A)(C)
400WSS8 (75-22-49)	1	5.21	Clip, loop type CP1101	- (15-528)	(A)(C)
4W0043 (75-22-49)	1	1.76	Nut, clip (0.190 dia) CP1101	- (15-532)	(A)(C)
4W0102 (75-22-49)	1	3.30	Bolt, bihex hd (0.190 dia x 0.438) CP1102	- (15-533)	(A)(C)
K8831 (75-22-49)	1	0.13	Washer CP1102	- (15-534)	(A)(C)
400WSS8 (75-22-49)	1	5.21	Clip, loop type CP1102	- (15-536)	(A)(C)
4W0043 (75-22-49)	1	1.76	Nut, clip (0.190 dia) CP1102	- (15-540)	(A)(C)
6A2157 (75-22-49)	1	505.00	Tube a/o, cooling air	- (16-100)	(A)(C)
4W0102 (75-22-49)	1	3.30	Bolt, bihex (0.190 dia x 0.438) CP1103	- (16-125)	(A)(C)
K8831 (75-22-49)	1	0.13	Washer CP1103	- (16-126)	(A)(C)
400WSS8 (75-22-49)	1	5.21	Clip, loop type CP1103	- (16-128)	(A)(C)
4W0001 (75-22-49)	1	5.37	Nut, bihex (0.190 dia) CP1103	- (16-132)	(A)(C)
400WSS8 (75-22-49)	1	5.21	Clip, loop type CP0853	- (16-136)	(A)(C)
400WSS8 (75-22-49)	1	5.21	Clip, loop type CP0852	- (16-144)	(A)(C)
400WSS8 (75-22-49)	1	5.21	Clip, loop type CP0851	- (16-152)	(A)(C)
6A2156 (75-22-49)	1	595.00	Tube a/o, cooling air	- (16-500)	(A)(C)
400WSS8 (75-22-49)	1	5.21	Clip, loop type CP0849	- (16-528)	(A)(C)

Printed in Great Britain

V2500-ENG-75-0010



SERVICE BULLETIN

400WSS8	1	5.21	Clip, loop type	-	(A)(C)
(75-22-49)			CP0847	(16-536)	
400WSS8	1	5.21	Clip, loop type	-	(A)(C)
(75-22-49)			CP0846	(16-544)	
400WSS8	1	5.21	Clip, loop type	-	(A)(C)
(75-22-49)			CP0845	(16-552)	
400WSS8	1	5.21	Clip, loop type	-	(A)(C)
(75-22-49)			CP0779	(16-560)	
6A2159	1	377.00	Tube a/o, cooling air	-	(A)(C)
(75-22-49)				(17-100)	
740-5782	1	-	Bracket	740-5779-	(A)(D)
501			CP1103	501	
(79-22-49)				(13-900)	

C. Instructions/Disposition Code Statements

- (A) New parts coded (A) are currently available for sale.
- (B) Refer to Dowty Smiths Service Bulletin 1664-73-001.
- (C) Additional part.
- (D) Old parts can be used at other applications.
- (E) Added as alternative to ST1698D50 (Refer to SB71-0065).
- (F) Indicates item no. change only.
- (G) Leaves 7 required.
- (H) Leaves 12 required.

NOTE: The estimated 1991 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department information concerning firm prices.

Dowty Fuel Systems

SERVICE BULLETIN

1664-73-001

ENGINE DEDICATED ALTERNATOR-STATOR
UNIT. INTRODUCTION OF AIR COOLING
TO ALTERNATOR STATOR.

(IAE SB V2500-ENG-75-0010)
(DSIC MOD. D.TV.020)

1. Planning Information

A. Effectivity

(1) Airbus - A320

V2500-A1100000. All 1664 Mk2 Units.

(2) Stator Units

This bulletin applies to new manufacture; the point of embodiment is unit serial number 1664200.

B. Reason

(1) Condition

The current standard of Alternator runs with a Stator Unit winding temperature of approximately 245°C. This temperature exceeds the continuous functional capability of the slot liner material which causes material shrinkage. This causes a slow and continuous increase in winding temperature which can result in an electrical failure.

(2) Background

The condition was identified during reliability testing of the unit.

(3) Objective

Incorporation of the changes introduced by this Service Bulletin (Modification), are designed to reduce the initial winding temperature to less than 215°C. This will prevent material degradation and extend stator life.

Dowty Fuel Systems

SERVICE BULLETIN

(4) Substantiation

The changes introduced by this Service Bulletin (Modification), have been shown by extended testing, to alleviate the condition.

C. Description

- (1) This Service Bulletin (Modification) introduces an aluminium shroud over the existing Stator Unit body. Air is supplied tangentially into the shroud, flows over the body and is then vented through a gap between the shroud and the body.
- (2) Control of the air flow is by a choke orifice at the inlet to the shroud. The air flow helps heat movement from the body and causes a winding temperature of less than 215°C.
- (3) This Service Bulletin is in two parts. Part 1 is to accomplish this Service Bulletin on-wing. Part 2 is to accomplish this Service Bulletin by unit replacement.

D. Compliance

Category Code 5.

Accomplish when the engine is disassembled sufficiently to afford access to the affected subassembly (i.e. Module, Accessory, Component, Build Group) and to all affected spare subassemblies.

E. Approval

Service Bulletin No. 1664-73-001 (Mod.DTV.020), (IAE SB V2500-ENG-75-0010), was technically approved by IAE on Sep.4/90. The part number changes and/or part modifications described in this Service Bulletin have been shown to comply with the appropriate Federal Aviation Regulations and are FAA approved for those units listed in this Bulletin.

F. Manpower

0.5 additional man hours are necessary to incorporate this Service Bulletin (Modification), at Engine Maintenance level (on-wing).

1664-73-001

Dec. 21/90

Page 2 of 8

Rev. 1 Dec. 1/91

Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).

Dowty Fuel Systems

SERVICE BULLETIN

G. Material - Price and Availability

- (1) See the supplement to this Bulletin.

H. Tooling - Price and Availability

- (1) Additional tools
None.
- (2) Tools made redundant
None.

I. Weight and Balance

- (1) Weight change 257g (9.1oz.)
increase
- (2) Moment arm No effect
- (3) Datum Engine front
mount
centerline.
(Power Plant
Station(PPS)100)

J. References

- (1) Dowty & Smiths Industries Controls Limited, component
maintenance manual 73-22-38.
- (2) IAE Service Bulletin V2500-ENG-75-0010.
- (3) Dowty/Smiths Mod.DTV.020.

K. Other Publications Affected

Nil.

2. Accomplishment Instructions

This Service Bulletin can be accomplished on-wing or by unit replacement. 2.A are the on-wing accomplishment instructions. 2.B are the unit replacement instructions.

1664-73-001

Dec. 21/90

Page 3 of 8

Rev. 1 Dec. 1/91

Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).

Dowty Fuel Systems

SERVICE BULLETIN

A. The on-wing accomplishment instructions (Part 1), of this Service Bulletin are as follows:

- (1) Remove the Engine Dedicated Alternator (EDA), Stator Unit as instructed by IAE Service Bulletin V2500-ENG-75-0010.
- (2) Refer to 73-22-38 and Figure 1 of this Service Bulletin and release the bonding strip (1-70); remove the bonding strip (1-70) and the identification plate (1-80) from the stator unit.
- (3) Discard the bonding strip (1-70) but keep the identification plate (1-80) until the Service Bulletin accomplishment (Part 1), is complete.
- (4) Install the toroidal sealing ring (AS43003-908) onto the smaller threaded end of the stepped union (STD 860-3).
- (5) Assemble the stepped union (STD860-3) to the threaded bore in the shroud and inserts assembly (1664-4003). Hold the shroud and inserts assembly in a soft-jawed vice and torque tighten the stepped union to 40.5 to 49.5 Nm (360 to 440 lbf.in.). Remove the shroud and inserts assembly from the vice.
- (6) Install the toroidal sealing ring (AS43013-154) into the groove inside the shroud and inserts assembly.
- (7) Assemble the shroud and inserts assembly (1664-4003) over the body of the stator unit (1-10). Align the holes in the flange of the shroud and inserts assembly with the holes in the flange of the stator unit body.
- (8) If it has been removed, install the toroidal sealing ring (1-20) to the groove on the stator unit body. Fit the transport cover (1-30) to the stator unit body; assemble the three bolts (STD384-20) and the three nuts (1-40) to keep the components in place.
- (9) Get the new data plate (215-9000) (supplied with the Mod. kit).

1664-73-001


Dec. 21/90

Page 4 of 8

Rev. 1 Dec. 1/91

Dowty Fuel Systems

SERVICE BULLETIN



Assembly of the Cooling Shroud
Figure 1

1664-73-001

Page 5 of 8

Dec. 21/90

Rev. 1 Dec. 1/91

Dowty Fuel Systems

SERVICE BULLETIN

- (10) Refer to the information marked on the first identification plate (1-30) and mark the new identification plate as follows (use 1/16in. (1.6mm), letter/number stamps), with the identification plate held on a flat surface:

TYPE NO. - Mark 1664 Mk3M
SERIAL NO. - Mark as on the original plate
VOCAB NO. - Keep blank
MOD. NO. - Mark DTV020

Note: The M against the Mk3 number shows that the unit has been modified in the field (Part 1), not by unit replacement (Part 2).

- (11) Where possible, fill in the stamped letters/numbers with black paint and wipe away the surplus.
- (12) Destroy the first identification plate.
- (13) Carefully bend the new identification plate to the shape of the shroud and inserts assembly, as shown in Figure 1.
- (15) Line up the holes in the identification plate with the holes in shroud and inserts assembly; install the two panhead screws (A218A10). Torque tighten the panhead screws to 0.72 to 0.88 Nm (6.3 to 7.7 lbf.in.).
- (16) Install the EDA, Stator Unit as instructed by IAE Service Bulletin V2500-ENG-75-0010.
- (17) A record of accomplishment is required.

B. Part 2 of this Service Bulletin is by unit replacement only:

- (1) Remove the Engine Dedicated Alternator (EDA), Stator Unit as instructed by IAE Service Bulletin V2500-ENG-75-0010.

1664-73-001

Dec. 21/90

Page 6 of 8

Rev. 1 Dec. 1/91

Dowty Fuel Systems

SERVICE BULLETIN

Note: Removed stator units should be returned to:

Dowty Fuel Systems
Arle Court
Cheltenham
Glos GL51 OTP,
England.

(For the attention of the Customer Support Engineer).

- (2) Install the replacement EDA Stator Unit as instructed by IAE Service Bulletin V2500-ENG-75-0010.

The part number identification, 1664 Mk3, will show that this Service Bulletin has been incorporated.

- (3) A record of accomplishment is required.

3. Material Information

A. Modification Kit

Modification kit D.TV.020 (comprises the parts given in Para. C.).

B. Parts to be Re-worked

None.

C. New Production Parts

The following new parts will be available as spares:

<u>New Part No.</u>	<u>Qty</u>	<u>Keyword</u>	<u>Old Part No.</u>
1664-4003	1	Shroud & inserts	
		assy of	-
STD860-3	1	Union, stepped	-
AS43013-154	1	Ring, sealing	-
AS43003-908	1	Ring, sealing	-
215-9000	1	Plate, identification	215-386
A218A10	2	Screw, panhead	-
STD384-20	3	Screw, machine	STD384-15

D. Redundant Parts

<u>IPL</u> <u>Fig./Item</u>	<u>New Part No.</u>	<u>Qty</u>	<u>Keyword</u>	<u>Old Part No.</u>
1-50	STD384-20	3	Bolt	STD384-15
1-70	-	1	Strip, bonding	215-410
1-80	215-9000	1	Plate, identification	215-386

1664-73-001

Dec. 21/90

Page 7 of 8

Rev. 1 Dec. 1/91

Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).

Dowty Fuel Systems

SERVICE BULLETIN

E. Identification of Units

The type of equipment affected by this Modification is:

Unit

Type No.

Stator Unit 1664 Mk2 (Becomes 1664 Mk3).

1664-73-001

Page 8 of 8

Dec. 21/90

Dowty Fuel Systems

SERVICE BULLETIN

1664-73-001 (SUPPLEMENT)

ENGINE DEDICATED ALTERNATOR - STATOR
UNIT. INTRODUCTION OF AIR COOLING
TO ALTERNATOR STATOR

(IAE SB V2500-ENG-75-0010)
(DSIC MOD.DTV.020)

1. Modification Kit

Modification kit D.TV.020 comprises the parts given in Para. 2.

2. New Production Parts

<u>Part No.</u>	<u>Qty per unit</u>	<u>Keyword</u>	<u>Gross World List Price (Dollars)</u>	<u>Availability on Receipt of Order</u>
1664-4003	1	Shroud & inserts		
		assy. of	\$591.65	90 days
STD860-3	1	Union, stepped	\$ 62.92	90 days
AS43013-154	1	Ring, sealing	\$ 36.32	90 days
AS43003-908	1	Ring, sealing	\$ 6.15	90 days
215-9000	1	Plate,		
		identification	\$ 26.50	90 days
A218A10	2	Screw, panhead	\$ 0.70 ea.	90 days
STD384-20	3	Screw, machine	\$ 18.07 ea.	90 days

3. New Tooling

None.

SUPPLEMENT
1664-73-001

Page 1 of 1

Dec. 21/90

Rev. 1 Dec. 1/91

Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).