

## SERVICE BULLETIN

ENGINE - AIR - REVISED HPT ACC MANIFOLD SUPPORT BRACKET - CATEGORY CODE 8 -  
MOD.ENG-75-0026

1. Planning InformationA. Effectivity

- (1) Aircraft: Airbus A320
- (2) Engine: V2500-A1 Engines Prior to Serial V0227 except V0225

B. Reason

## (1) Condition

Cracking has occurred on the side support pin of some Turbine Cooling Manifolds.

## (2) Background

New Pin and Support are provided to increase strength of the side support pin of Turbine Cooling Manifold. New Support has an increased thickness and a full circular shape joint instead of existing a semicircular shape. Also new Pin has an increased length. Jointing of the pin and support is improved by the aforesaid changes.

## (3) Objective

To improve strength of side support pin on the Turbine Cooling Manifold.

## (4) Substantiation

The changes introduced by this Bulletin were analytically substantiated.

## (5) Effects of Bulletin on the following shop functions:

Removal/Installation	Not affected
Disassembly/Assembly	Not affected
Cleaning	Not affected
Inspection/Check	Not affected
Repair	Affected (See Supplemental Information)
Testing	Not affected

## (6) Supplemental Information

- (a) The Post-Service Bulletin configuration requires different procedure of Pin Replacement Repair, VRS1530, to IAE V2500 Engine Manual, 75-24-48.

V2500-ENG-75-0026



## SERVICE BULLETIN

C. Description

- (1) The changes introduced by this Service Bulletin are as follows:
- (a) 2A1569 Turbine Cooling Manifold supercedes 2A1540 Turbine Cooling Manifold and 2A3665 Turbine Colling Manifold supercedes 2A0202 Turbine Cooling Manifold. Following composing parts of the Turbine Cooling Manifold are changed.
    - (i) 2A1564 Hollow Pin supercedes 2A0241 Hollow Pin.
    - (ii) 2A1563 TCC Manifold Support supercedes 2A0238 TCC Manifold Support.
  - (2) 2A1540 Turbine Cooling Manifold can be modified and re-identified to 2A1569 Turbine Cooling Manifold.
  - (3) 2A0202 Turbine Cooling Manifold can be modified and re-identified to 2A3665 Turbine Cooling Manifold.

D. Approval

The part number changes and/or part modification described in Section 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Compliance

Category Code 8

Accomplish based upon experience with the prior configuration.

F. Manpower


Estimated Manhours to incorporate the full intent of this Bulletin:

Venue	Est'd Manhours
(1) In service	Not applicable
(2) At overhaul (Note: The parts affected by this Service Bulletin are accessible at overhaul)	
(a) To rework Turbine Cooling Manifold .....	60 minutes

G. Material – Price and Availability

- (1) Modification Kit is not required.

V2500–ENG–75–0026



# SERVICE BULLETIN

- (2) See "Material Information" section for prices and availability of future spares.

## H. Tooling - Price and Availability

Special tools are not required.

## I. Weight and Balance

- (1) Weight change .....None
- (2) Moment arm .....No effect
- (3) Datum .....Engine front mount  
centerline (Powerplant  
Section (P.P.S.) 100)

## J. Electrical Load Data

This Service Bulletin has no effect on the aircraft electrical load.

## K. References

- (1) Internal Reference No.

90VJ048

92VJ083

- (2) Other References

IAE V2500 Engine Illustrated Part Catalog, 75-24-48.

IAE V2500 Standard Practices/Processes Manual, 70-09-00 Marking of Parts, 70-23-05 Penetrant Inspection and 70-31-02 Argonarc Welding Repairs.

IAE V2500 Component Maintenance Manual, 75-24-48 Cleaning and Inspection/Check.

## L. Other Publications Affected

- (1) IAE V2500 Engine Illustrated Parts Catalog, 75-24-48.
- (2) IAE V2500 Powerplant Illustrated Parts Catalog, 75-24-48.

V2500-ENG-75-0026



## 2. Accomplishment Instructions

### A. Rework Instructions


- (1) Do a modification of 2A1540 and/or 2A0202 Turbine Cooling Manifold (See Reference (1), 75-24-48, Fig/Item No. 02-500) and identify as follows:

NOTE: All 2A1540 and 2A0202 Turbine Cooling Manifold must be examined in accordance with Reference (3), 75-24-48, Inspection/Check before application of this modification.

NOTE: Pins and Supports on both sides of 2A1540 and/or 2A0202 Turbine Cooling Manifold must be changed to new configuration at once.

Procedure	Supplementary Information
(a) Cut out the support at 2 points, each point is as close as the manifold	Refer to Figure 1 requirements Use a wire cutter
(b) Remove the residual support from the manifold body, keeping the original thickness of the manifold body	Use a hand held pneumatic grinder Refer to Figure 1 requirements
(c) Remove the all oxides, hydrocarbon, grit and scale from the surface to be welded and adjacent area by local cleaning	Refer to Reference (3), 75-24-48, Cleaning. Use CoMat 01-031 acetone and CoMat 02-099 lint free cloth
(d) Weld the Pin to the Support by tungsten inert gas (TIG) weld	Refer to Reference (2), 70-31-02 Argonarc Welding Repairs-01 and -08, and Figure 1 requirements. Use a tungsten inert gas (TIG) system. Use CoMat 03-204 welding filler wire.
(e) Weld the Support to the manifold by tungsten inert gas (TIG) weld	Refer to Reference (2), 70-31-02 Argonarc Welding Repairs-01 and -08, and Figure 1 requirements. Use a tungsten inert gas (TIG) system. Use CoMat 03-204 welding filler wire.
(f) In contact area, remove excess weld and dress flush with adjacent area	Use a hand held pneumatic grinder

# V2500-ENG-75-0026



# SERVICE BULLETIN


- |   |   |              |              |        |        |        |        |
|---|---|--------------|--------------|--------|--------|--------|--------|
| (g) Examine the repaired area by local application fluorescent penetrant inspection | Refer to Reference (2), 70-23-05<br>Local Application of Fluorescent Penetrant Inspection   |              |              |        |        |        |        |
| (h) Visually examine the repaired area  | Use a 8X magnifying glass.<br>Refer to Reference (3), 75-24-48<br>Inspection/Check  |              |              |        |        |        |        |
| (i) Re-identfy modified Turbine Cooling Manifold by the vibration peen method       | <table border="0"> <tbody> <tr> <td>Old Part No.</td> <td>New Part No.</td> </tr> <tr> <td>2A1540</td> <td>2A1569</td> </tr> <tr> <td>2A0202</td> <td>2A3665</td> </tr> </tbody> </table> <p>Refer to Figure 1 requirements and Reference (2), 70-09-00, Marking of Parts</p> | Old Part No. | New Part No. | 2A1540 | 2A1569 | 2A0202 | 2A3665 |
| Old Part No.  | New Part No.  |              |              |        |        |        |        |
| 2A1540  | 2A1569  |              |              |        |        |        |        |
| 2A0202  | 2A3665  |              |              |        |        |        |        |

## B. Recording Instructions

- (1) A record of accomplishment is necessary.




# SERVICE BULLETIN




ded0001203

Sheets) Modification of 2A1450 and 2A0202 Turbine Cooling Manifold  
Fig.1 (Sheet 1 of 3

## V2500-ENG-75-0026




NOTE : MARK NEW PART NUMBER NEAR BY  
OLD PART NUMBER PER SPM TASK 70-09-00




ded0001204



Sheets) Modification of 2A1540 and 2A0202 Turbine Cooling Manifold  
Fig.1 (Sheet 2 of 3



THIS ILLUSTRATION APPLIES TO PART NUMBER 2A0202




NOTE : MARK NEW PART NUMBER NEAR BY  
OLD PART NUMBER PER SPM TASK 70-09-00



Sheets) Modification of 2A1540 and 2A0202 Turbine Cooling Manifold  
Fig.1 (Sheet 3 of 3

ded0001205





## SERVICE BULLETIN

3. Material Information

Applicability: For each V2500 Engine to incorporate this Bulletin.

A. Kits associated with the Bulletin:

None

B. Parts Affected by this Bulletin:

NEW PART NO. (ATA NO.)	QTY	EST'D UNIT PRICE (\$)	KEYWORD	OLD PART NO. (IPC NO.)	INSTRUCTIONS DISPOSITION
2A3665 (75-24-48)	1		.Manifold, A/O Turbine Colling	2A0202 (02-500)	(S1)(1D)(A) (B)
2A1569 (75-24-48)	1		.Manifold, A/O Turbine Cooling	2A1540 (02-500)	(S1)(1D)(A) (B)
2A1564 (75-24-48)	2		..Pin, Hollow	2A0241 (02-530)	(S2)(C)
2A1563 (75-24-48)	2		..Support, TCC Manifold	2A0238 (02-535)	(S2)(B)

C. Instruction/Disposition Code Statements:

- (A) New part is currently available for sale.
- (B) Old part will no longer be available for sale.
- (C) Old part will continue to be available for sale.
- (S1) New and Old parts are freely and fully interchangeable, both physically and functionally.
- (S2) New parts must be used as a set for higher level assembly. Mixing of old and new parts is not permissible. New and Old parts are not interchangeable.
- (1D) Old part number can be reworked and re-identified as a new part number.

D. Consumables required to incorporate this bulletin:

CoMat 01-031	acetone
CoMat 02-099	lint free cloth
CoMat 03-204	welding filler wire

NOTE: The estimated 1993 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

V2500-ENG-75-0026

