

# **SERVICE BULLETIN**

STARTING — STARTER, PNEUMATIC — INSPECTION OF THE PNEUMATIC STARTER FOR AN INCORRECT FAA-PMA LABEL

<u>MODEL APPLICATION</u> V2500-A1, V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, V2533-A5

**BULLETIN ISSUE SEQUENCE** 

V2500 Series 80-0026

ATA NUMBER 80-13-41

#### IAE PROPRIETARY INFORMATION

This document is the property of International Aero Engines (IAE). You may not possess, use, copy or disclose this document or any information in it, for any purpose, including without limitation to design, manufacture, or repair parts, or obtain FAA or other government approval to do so, without IAE's express written permission. Neither receipt nor possession of this document alone, from any source, constitutes such permission. Possession, use, copying or disclosure by anyone without IAE's express written permission is not authorized and may result in criminal and/or civil liability.

WARNING – This document contains technical data the export of which is or may be restricted by the Export Administration Act and the Export Administration Regulations (EAR), 15 C.F.R. parts 730-774. Diversion contrary to U.S. law is prohibited. The export, re-export, transfer or re-transfer of this technical data to any other company, entity, person, or destination, or for any use or purpose other than that for which the technical data was originally provided by IAE, is prohibited without prior written approval from IAE and authorization under applicable export control laws.

Export Classification: Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).

Supplier Service Bulletin

Sumitomo Precision USA, INC., Service Bulletin 80-001

Compliance Category

6

IAE Distribution Code

V2500

September 17/20

V2500-ENG-80-0026



#### Summary

The purpose of this Service Bulletin is to do an inspection of the pneumatic starter for an incorrect FAA-PMA label.

# Planning Information

#### **Effectivity Data**

#### **Engine Models Applicable**

V2500-A1

Engine Serial Nos. — All Engines.

V2522-A5, V2524-A5, V2527M-A5, V2527-A5, V2527E-A5, V2530-A5, V2533-A5 Engine Serial Nos. — All Engines.

#### Concurrent Requirements

There are no concurrent requirements.

#### Reason

- Condition: Pneumatic starters with an incorrect FAA-PMA label were released in the field.
- Background: The FAA-PMA label is incorrect on Pneumatic Starters, PN 790425A9 manufactured and shipped by Sumitomo Precision USA, Inc. between October 31, 2013 and January 30, 2020. The serial number range affected is from PS4-1001 through PS4-1610.
- 3. Objective: To examine all applicable pneumatic starters and remove the incorrect FAA-PMA label, and attach the correct label.
- 4. Substantiation: Per direction/approval of FAA.
- 5. Effects of Bulletin on:

Removal/Installation: Not Affected.

Disassembly/Assembly: Not Affected.

Cleaning: Not Affected.

Inspection/Check: Not Affected.

Repair: Not Affected.
Testing: Not Affected.

6. Supplemental Information

None.

## Description

Do Reference 4, Sumitomo SB 80-001 to examine and replace (if necessary) the FAA-PMA label on the pneumatic starter.

#### Compliance

Category 6

September 17/20

V2500-ENG-80-0026



Accomplish when the subassembly (i.e. modules, accessories, components, build groups) is disassembled sufficiently to afford access to the affected part and to all affected spare parts.

#### Approval Data

The part number changes and/or part modifications specified in the Accomplishment Instructions and Material Information sections of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model(s) given.

This SB does not contain any change information that revises the equipment definition covered by Airbus approved modifications.

#### Manpower

1.	At	Overhau	ıl
	, ,,	Overnac	41

............ See Reference 4, Sumitomo Precision USA, Inc., Service Bulletin 80-001.

#### Weight and Balance

Weight Change

None.

2. Moment Arm

No Effect.

3. Datum

Engine Front Mount Centerline (Power Plant Station (PPS) 100)

#### Electrical Load Data

This Service Bulletin has no effect on the aircraft electrical load.

# Software Accomplishment Summary

Not Applicable.

#### References

NOTE:

In 2014 IAE converted the V2500 Technical Publications to a new system. As a result of the conversion, some manuals were consolidated. All manuals received new P&W part numbers. To facilitate the use of this Service Bulletin, a Technical Publications conversion table is provided in the Appendix.

- 1. V2500 Standard Practices and Processes, P&W Ref. PN 2A4414
- 2. V2500-A1 Series Illustrated Parts Catalog, P&W Ref. PN 2A4427
- V2500-A5 Series Illustrated Parts Catalog, P&W Ref. PN 2A4428
- 4. Sumitomo Precision USA, Inc., Service Bulletin 80-001.

#### Other Publications Affected

V2500-A1 Series Illustrated Parts Catalog, P&W Ref. PN 2A4427

Chapter/Section 80-13-41, Figure 1

V2500-A5 Series Illustrated Parts Catalog, P&W Ref. PN 2A4428

September 17/20

V2500-ENG-80-0026



Chapter/Section 80-13-41, Figure 1

# Interchangeability of Parts

Not Applicable.

#### Information in the Appendix

Alternate Accomplishment Instructions (No)

Progression Charts (No)

Added Data (Yes)

Revision to Table of Limits (No)

Inspection Procedures (No)



# **Material Information**

#### Material — Price and Availability

- 1. Part prices were not available at the time of Service Bulletin publication. Contact IAE Spares Management & Logistics for firm quotations.
- 2. There is no kit provided to do this Service Bulletin.
- 3. Part availability information is provided in material data Instructions Disposition.

#### **Industry Support Program**

Not Applicable.

The material data that follows is for each engine.

# For V2500-A1 Engines:

New PN	Qty	Estimate of Unit Price (\$)	Keyword	Old PN	Instructions — Disposition
	1		STARTER — PNEUMATIC	790425A9 (80-13-41-01A-200AK)	(4)(X)

The material data that follows is for each engine.

For V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, V2533-A5 Engines:

New PN	Qty	Estimate of Unit Price (\$)	Keyword	Old PN	Instructions — Disposition
	1		STARTER — PNEUMATIC	790425A9 (80-13-41-01A-200AG)	(4)(X)

#### Modification and Spares Information

Parts Modification Conditions

Estimated part prices are provided when they are available at time of publication. The Estimate of Unit Price is only for planning purposes and does not constitute a firm quotation. An asterisk (\*) is shown where part pricing information was unavailable. In either case, contact IAE Spares for firm quotations.

(4) Do an inspection as specified in the Accomplishment Instructions.

#### Spare Parts Availability

(X) See Reference 2 or 3, IPC for applicable replacement parts.



#### Vendor Services or Special Components/Materials

# Vendor Services or Special Components/Materials

P&W Designation	Vendor Designation	Name	Vendor Name & Address	
	U5001007-1	FAA-PMA Label	Sumitomo Precision USA, Inc.	
	80-001	Service Bulletin	c/o 790425A9 Tracking 1639 Falcon Drive DeSoto, Texas 75115 USA	
Email: 790425a9@spu-usa.com				
Phone: (972) 228-9300				

NOTE:

EXCEPT FOR WORK OR SUPPLIES TO BE PERFORMED OR FURNISHED BY IAE, IT IS UNDERSTOOD THAT IAE DOES NOT ENDORSE THE WORK PERFORMED BY THE COMPANY OR COMPANIES NAMED HEREIN OR ANY OTHER COMPANY AND DOES NOT ACCEPT RESPONSIBILITY TO ANY DEGREE FOR THE SELECTION OF SUCH COMPANY OR COMPANIES FOR THE PERFORMANCE OF ANY WORK OR PROCUREMENT OF SUPPLIES.

#### Tooling — Price and Availability

Special tools are not required to accomplish this Service Bulletin.

#### Reidentified Parts

Not Applicable.

#### Other Material Information Data

Not Applicable.



# Accomplishment Instructions

- 1. Do Reference 4, Sumitomo Precision USA, Inc., Service Bulletin 80-001 to identify and replace an incorrect FAA-PMA label on the pneumatic starter.
- 2. Recording instructions
  - A. A record of accomplishment is not necessary.



# Appendix Added Data

# Internal Reference Information

Revision No.	Reference Document	Origination	
Original	EA20VC285	HB/RCM	

NOTE:

In 2014 IAE converted the V2500 Technical Publications to a new system. As a result of the conversion, some manuals were consolidated. All manuals received new P&W part numbers. To facilitate the use of this Service Bulletin, the following Technical Publications cross reference table is provided.

### Technical Publications Cross Reference Table

Publication	Engine Model(s)	IAE IETM Pub Ref	P&W Part Number
ENGINE MANUAL — A1, A5	All	E-V2500-1IA	2A4407
CMM-EHC — A1, A5	All	EHC-V2500-1IA	2A4409
CMM-FN — A1, A5	All	FN-V2500-1IA	2A4410
CMM-MMC — A1, A5	All	MECH-V2500-1IA	2A4411
CMM-THD — A1, A5	All	THD-V2500-1IA	2A4412
TLM — A1, A5	All	T-V2500-1IA	2A4408
ENGINE MANUAL — D5	All	E-V2500-3IA	2A4416
CMM-EHC — D5	All	EHC-V2500-31A	2A4418
CMM-FN — D5	All	FN-V2500-3IA	2A4419
CMM-MMC — D5	All	MECH-V2500-3IA	2A4420
CMM-THD — D5	All	THD-V2500-3IA	2A4423
TLM — D5	All	T-V2500-3IA	2A4417
SPPM (SPM) — A1, A5, D5	All	SPP-V2500-1IA	2A4414
EIPC — A1	V2500-A1102Q00	S-V2500-1IA	2A4427



Publication	Engine Model(s)	IAE IETM Pub Ref	P&W Part Number
	V2522/V2524/V2527M-AQ02	S-V2500-6IA	
	V2522/V2524/V2527M-AQ03	S-V2500-6IB	
	V2522/V2524/V2527M-SQ02	S-V2500-6SA	
	V2522/V2524/V2527M-SQ03	S-V2500-6SB	
	V2522/V2524/V2527M-SQ04	S-V2500-6NA	
	V2522/V2524/V2527M-SQ05	S-V2500-6NB	
	V2527/V2527E-AQ02	S-V2500-7IA	
	V2527/V2527E-AQ03	S-V2500-7IB	
	V2527/V2527E-SQ02	S-V2500-7SA	
	V2527/V2527E-SQ03	S-V2500-7SB	
	V2527/V2527E-SQ04	S-V2500-7NA	2A4428
EIPC — A5	V2527/V2527E-SQ05	S-V2500-7NB	
EIFC — AS	V2530-AQ02	S-V2500-2IA	
	V2530-AQ03	S-V2500-2IB	
	V2530-SQ02	S-V2500-2SA	
	V2530-SQ03	S-V2500-2SB	
	V2530-SQ04	S-V2500-2NA	
	V2530-SQ05	S-V2500-2NB	
	V2533-AQ02	S-V2500-5IA	
	V2533-AQ03	S-V2500-5IB	
	V2533-SQ02	S-V2500-5SA	
	V2533-SQ03	S-V2500-5SB	
	V2533-SQ04	S-V2500-5NA	
	V2533-SQ05	S-V2500-5NB	<u> </u>
	V2525/V2528-AQ02	S-V2500-3IA	
EIPC — D5	V2525/V2528-AQ03	S-V2500-3IB	2A4426
	V2525/V2528-AQ04	S-V2500-3IC	