Date: February 20, 1997

Subject: Transmittal of Revision 1 to Service Bulletin Number V2500-NAC-78-0038

## Service Bulletin Revision History:

**Event** 

Date

Basic Issue

Oct. 01/95

Revision 1

Feb. 20/97

## Reasons for Issuance of Revision

(1) To replace the illustration in Figure 1..

# Effect on Past Compliance

(1) None.

# List of Effective Pages:

Page No.	Rev. No.	<u>Date</u>
1	1 Pasta	Feb. 20/97
2 thru 7	Basic	Oct. 01/95
8	1	Feb. 20/97
9 and 10	Basic	Oct. 01/95

V2500-NAC-78-0038 Transmittal Page 1 of 1 NACELLE - EXHAUST - THRUST REVERSER No. 4 HINGE WASHERS -REPLACEMENT OF

MODEL APPLICATION

V2500-A1

BULLETIN INDEX LOCATOR

78-32-00

Compliance Category Code

4

Internal Reference No. BC/RJ 89VN094

October 1, 1995 Revision 1 - February 20, 1997 V2500-NAC-78-0038
Page 1 of 10



### NOTE:

This Service Bulletin is issued for part number progression history only. It is not intended to be incorporated or kit parts ordered from the manufacturer. The intent of this modification is accomplished by incorporation of Service Bulletins V2500-NAC-78-0063 and V2500-NAC-78-0082

- 1. Planning Information
  - A. Effectivity
    - (1) Airplane: Airbus A320
    - (2) Nacelle: V2500-A1
      - (a) The intent of this Service Bulletin was incorporated at the manufacturer on Thrust Reverser Units Serial Nos. 106, and on.
      - (b) The following Thrust Reversers were not modified at the manufacturer. They can be modified by incorporating this Service Bulletin using Kit V2578016-551

TR
<u>Serial Number</u>
6 thru 105

V2500-NAC-78-0038

# Aero Engines SERVICE BULLETIN

#### B. Reason

(1) Condition

The existing No. 4 hinge bolt exposed thread length is too short to allow proper installation.

(2) Background

Not applicable.

(3) Objective

To maintain thrust reverser reliability and increase maintainability.

(4) Substantiation

This modification was satisfactorly fitted to a production unit.

(5) Impact of Bulletin on Workshop Procedures:

Removal/Installation Affected
Disassembly/Assembly Affected
Cleaning Not Affected
Inspection/Repair Not Affected
Repair Not Affected
Testing Not Affected

(6) Supplemental Information

None

V2500-NAC-78-0038

October 1, 1995



## V2500 Propulsion System — Nacelle

# Aero Engines SERVICE BULLETIN

#### C. Description

The change introduced by this Bulletin is as follows:

Replace the AN960C1016 washer under the bolt head with VN936NP8C washer and add anouther S700W0131R8L20 washer under the new VN936NP8C washer.

## D. Approval

The part number changes and/or part modifications described in Paragraphs 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA approved for the equipment model(s) listed.

#### Compliance Ε.

## Category 4

Accomplish at the first visit of the Nacelle or Nacelle Component to a maintenance base capable of compliance with the accomplishment instructions regardless of the planned maintenance action for the Nacelle of Nacelle Component.

#### F. Manpower

Estimated Manhours to incorporate the full intent of this Bulletin:

#### VENUE

#### ESTIMATED MANHOURS

### (1) In Service

To gain access Not Applicable (a) (b) To embody 1.0 M/Hrs To return Nacelle to service

Not Applacable

1.0 M/Hrs Total

V2500-NAC-78-0038 October 1, 1995

# Aero Engines SERVICE BULLETIN

G. Material Cost and Availability

The parts to accomplish this Service Bulletin, Kit V2578038-551, are not available from the manufacturer. See Kit and part information in Service Bulletins V2500-NAC-78-0063 and V2500-NAC-78-0082.

H. Tooling Cost and Availability

None Required

- I. Weight and Balance
  - (1) Weight change .... None
  - (2) Moment arm ...... No effect
  - (3) Datum ..... Engine Front Mount Centerline

..... (Powerplant Station PPS 100.00)

J. Electrical Load Data

Not Affected

V2500-NAC-78-0038



# V2500 Propulsion System — Nacelle

# International Aero Engines SERVICE BULLETIN

#### ĸ. References

L.

A320 Aircraft Maintenance Manual Service Bulletin V2500-NAC-78-0063 Service Bulletin V2500-NAC-78-0082	78-32-01
Other Publications Affected	
A320 Power Plant Illustrated Parts Catalog	78-32-01

78-32-02 78-32-03 78-32-04 A320 Engine Illustrated Parts Catalog 78-32-01 78-32-02

78-32-03 78-32-04

V2500-NAC-78-0038 Page 6

# Aero Engines SERVICE BULLETIN

- 2. Accomplishment Instructions
  - A. Prerequisite Instructions

CAUTION: Thrust reverser halves must be properly closed and latched before starting this procedure. Damage to hinges may occure if the thrust reverser is not closed and latched.

- (1) Remove the left and right thrust reverser hinge access panel as specified in the A320 Aircraft Maintenance Manual, Chapter 78-32-00.
- (2) Find the No. 4 hinge at the aft end of the thrust reverser. (Refer to Figure 1).
- B. Rework or Modification Instructions
  - (1) Remove bolt, washers, sleeve, and nut from No. 4 hinge. Discard AN960C1016 washer. (Refer to Figure 1).
  - (2) Lubricate S700B1191 bolt with CoMat 10-058 penetrating oil.
  - (3) Install S700B1191 bolt, VN936NP8C washer, two S700W0131R8L20 washers, and LCN12-820 nut.
  - (4) Torque nut to 480 -690 lb-in. (54.2 -78.0 N.m).
  - (5) Install MS24665-304 cotter pin in bolt.
- C. Post-requisite Instructions
  - (1) Install the hinge access panels as specified in A320 Aircraft Maintenance Manual, Chapter 78-32-00.
- D. Recording Instructions
  - (1) Write on the thrust reverser data plate that this Service Bulletin has been incorporated. A record of accomplishment is required.

V2500-NAC-78-0038


Page 7

October 1, 1995



V2500 Propulsion System - Nacelle

# International Aero Engines SERVICE BULLETIN



VSB266

No. 4 Hinge Modification -After Condition Figure 1

October 1, 1995 Revision 1 - February 20, 1997 V2500-NAC-78-0038



## V2500 Propulsion System - Nacelle

# Aero Engines SERVICE BULLETIN

#### 3. Material Information

NEW PART NO. EST'D UNIT OLD PART NO. INSTR/
(ATA NO) QTY PRICE (\$) KEYWORD (IPC NO.) DISPOS

Applicability: For each V2500 Nacelle to incorporate this Bulletin

A. Kits associated with this Bulletin:

V2578038-551 1 Kit (A)
Consisting of:

VN936NP8C 2 Washer S700W0131R8L20 2 Washer (F)

B. Parts affected by this Bulletin:

VN936NP8C	1	Washer	AN960C1016	(A)(C)
(78-32-01)			(01-045)	(S1)
(78-32-02)			(01-045)	
(78-32-03)			(01-045)	
(78-32-04)			(01-045)	
S700W0131R8L20	2	Washer	S700W0131R8L20	(A)(C)
(78-32-01)			(01-040)	(1D)
(78 - 32 - 02)			(01-040)	
(78-32-03)			(01-040)	
(78-32-04)			(01-040)	

October 1, 1995 V2500-NAC-78-0038



# V2500 Propulsion System — Nacelle

# Aero Engines SERVICE BULLETIN

- C. Instruction/Disposition Code Statements
  - (A) Kit is not available.
  - (C) New part is currently available for sale.
  - (F) New part supplied to replace old part. Old part is not reuseable.
  - (1D) Quantity was 1 now is 2
  - (S1) New parts coded S1 must replace old parts coded S1 as a complete set.
- D. These materials are to be procured by the Operator or obtained from his stock.

Part Number	Keyword	Qty	Source	Code
CoMat 10-058	Lubricant	AN	Rocep-Lusol 24 Reidvale St. Glasgow G31 15W Great Britain	K0680

V2500-NAC-78-0038

October 1, 1995