

SERVICE BULLETIN REVISION NOTICE

NACELLE - EXHAUST - LUG, THRUST REVERSER LOWER OUTBOARD TRACK ASSEMBLY LANYARD ATTACH - MODIFICATION OF

Turbojet Engine Service Bulletin No. V2500-NAC-78-0097 Revision No. 1 dated May 9, 2017

Revision History

Original Issue October 15, 1995 Revision 1 dated May 9, 2017

Reason for the Revision

The information contained in this Service Bulletin has been superseded by Service Bulletin V2500-NAC-78-0225. It is no longer necessary to do this Service Bulletin or Original Issue of this Service Bulletin.

Effect of Revision on Prior Compliance

None.

This is a Complete Revision (Not Applicable to the SGML version)

The format of this Service Bulletin has not been changed from the Original Issue. See Reason for the Revision above.

MODEL APPLICATION V2525-D5, V2528-D5

BULLETIN ISSUE SEQUENCE V2500 Series 78-0097

<u>Page</u>	Revision No.	<u>Date</u>
1 thru 16	1	May 9/17 Page 1 of 1 95VN306
		93711300

A copy of this Revision Notice and any future revision notices must be filed as a permanent record with your copy of the subject bulletin.

NO TECHNICAL DATA SUBJECT TO THE EAR OR ITAR.

TRANSMITTAL



NACELLE - EXHAUST - LUG, THRUST REVERSER LOWER OUTBOARD TRACK ASSEMBLY LANYARD ATTACH -MODIFICATION OF

MODEL APPLICATION

V2500-D5

BULLETIN INDEX LOCATOR

78-32-00

Compliance Category Code

6

Internal Reference No.
LL/AC 95VN306

October 15, 1995 Revision 1 - May 9/17

Planning Information

- Α. Effectivity
 - (1) Airplane: MD-90
 - (2) Nacelle: V2500-D5 thrust reverser serial numbers 0006001,

0007001, 0022001, 0024001, 0026001, 0028001,

-0030001, 0032001, 0034001, 0036001, and 0038001.

- В. Reason
 - (1) Condition

The lower thrust reverser outboard track assembly lanyard attach lug may exhibit cracking in service.

(2) Background

Inadequate lug thickness of lower thrust reverser outboard track assembly at lanyard attach location.

(3) Objective

> To provide additional support for lower thrust reverser outboard track assembly lanyard attach location.

(4)Substantiation

> Structural analysis of improved lanyard attach lug was successful.

October 15, 1995 Revision 1 - May 9/17 V2500-NAC-78-0097 Page 2



SERVICE BULLETIN

(5) Impact of Bulletin on Workshop Procedures:

Removal/Installation Not Affected Disassembly/Assembly Not Affected Cleaning Not Affected Inspection/Repair Not Affected Repair Not Affected Testing Not Affected

(6) Supplemental Information

None.

C. Description

The change introduced by this Bulletin is to remove the existing lug on lower outboard track assembly and install a fitting in its place.

D. Approval

Incorporation of this Service Bulletin must be accomplished only in conjunction with Douglas Aircraft Company Service Bulletin MD90 78-005 which has received exclusive FAA approval for MD-90 Series aircraft.

E. Compliance

Category 6

Accomplish when the Nacelle subassembly (i. e., accessories, components) is disassembled sufficiently to afford access to the affected part and to all affected spare parts.

October 15, 1995

Revision 1 - May 9/17

V2500-NAC-78-0097



Aero Engines SERVICE BULLETIN

F. Manpower

Estimated manhours to incorporate the full intent of this Bulletin:

VENUE

ESTIMATED MANHOURS

(1) In Service

Not Applicable

(2) In shop

(a) To rework

4.0 M/Hrs.

Total

4.0 M/Hrs.

G. Material Cost and Availability

The parts to accomplish this Service Bulletin are available from the supplier as kits V2578097-551 and V2578097-553 at no cost to the operator.

Operators with units listed in Paragraph 1.A should submit a no-charge purchase order for the applicable quantity of kits. The purchase order must specify this service bulletin number and only the parts listed herein. Operators will have one year from the issue date of the Service Bulletin to place an order. After one year, kits will no longer be available and Operators will have to order parts individually at catalog prices, if they desire to incorporate the change.

Direct Purchase order to: Rohr Inc. P.O. Box 878 Chula Vista, CA 91912 U.S.A.

Attn:

Airline Support Manager - Bldg. 107A (Ref. Service Bulletin No. V2500-NAC-78-0097)

October 15, 1995 Revision 1 - May 9/17

V2500 International Aero Engines

V2500 Propulsion System — Nacelle

Aero Engines SERVICE BULLETIN

H. Tooling Cost and Availability Not applicable.

I. Weight and Balance

(1)	Weight	Change						No	effect
-----	--------	--------	--	--	--	--	--	----	--------

- (2) Moment Arm. No effect
- (3) Datum Engine Front Mount Centerline

. Power Plant Station (PPS) 95.1

J. Electrical Load Data

Not affected.

K. References

Chapter/Section

V2500 Standard Practices/Processes Manual

70-09-00

70-23-05

70-36-02

70-39-03

L. Other Publications Affected

None.

October 15, 1995 Revision 1 - May 9/17

Aero Engines SERVICE BULLETIN

2. Accomplishment Instructions

A. Prerequisite Instructions


None.

- B. Rework or Modification Instructions
 - (1) Carefully pull back insulation blanket on outboard track assembly of left hand lower thrust reverser to get access to rework area. Refer to Figure 1.
 - (2) If installed, remove S700B0116-5C8 or S700B0116-5C16 bushing. Refer to Figure 2. Discard bushing.
 - (3) If installed, remove 94-B043600-M angle bracket. Discard bracket.
 - (4) Remove material from track assembly as shown in Figure 2.
 - (5) Clean away metal chips or other unwanted material with dry air supply.
 - WARNING: 1,1,1 TRICHLOROETHANE VAPORS ARE HARMFUL. USE IN A
 WELL-VENTILATED AREA. AVOID PROLONGED BREATHING OF
 VAPOR AND PROLONGED OR REPEATED CONTACT WITH SKIN.
 OVEREXPOSURE MAY CAUSE HEADACHE, DIZZINESS OR
 DROWSINESS. VAPOR IS HEAVIER THAN AIR AND MAY REPLACE
 OXYGEN IN A CONFINED AREA. SMOKING AND ARC WELDING
 SHOULD BE AVOIDED WHEN USING THIS SOLVENT; VAPORS OF
 DECOMPOSITION MAY CAUSE SERIOUS BODILY HARM.
 PROTECTIVE GLOVES SHOULD BE WORN DURING USE. MAY CAUSE
 DERMATITIS BY REMOVING SKIN OILS. PRIOR TO USE OF THIS
 PRODUCT, CAREFULLY READ THE APPLICABLE 'MATERIAL
 SAFETY DATA SHEET' AND FOLLOW ALL LISTED SAFETY AND
 HEALTH PRECAUTIONS.
 - (6) Clean the area with a lint free cloth (CoMat 02-099) and trichloroethane (CoMat 01-001). Wipe surface dry before solvent becomes dry.

October 15, 1995 Revision 1 - May 9/17



International Aero Engines SERVICE BULLETIN



OUTBOARD TRACK ASSEMBLY LANYARD ATTACH LUG FIGURE 1


October 15, 1995


Revision 1 - May 9/17


V2500-NAC-78-0097



International Aero Engines SERVICE BULLETIN







LANYARD ATTACH LUG REWORK FIGURE 2

October 15, 1995 Revision 1 - May 9/17 V2500-NAC-78-0097 Page 8



Aero Engines SERVICE BULLETIN

- (7) Dye penetrant inspect the rework area. Apply penetrant locally. Refer to the Standard Practices/Processes Manual, Chapter 70-23-05.
- (8) Use a clean (CoMat 02-099) lint-free cloth and (CoMat 01-001) trichcloroethane to clean rework area to remove any remaining dye penetrant.

WARNING: 463-6-27 BASE, X337 CONVERTER, AND TL52-66 THINNER ARE FLAMMABLE AND VAPOR IS HARMFUL. INHALATION OF SPRAY MIST MAY CAUSE SERIOUS BODILY HARM. SOURCES OF IGNITION. USE ONLY IN AREAS WITH ADEQUATE VENTILATION. WORK PERFORMED IN CONFINED AREA REQUIRES THE USE OF ADDITIONAL FORCED MECHANICAL VENTILATION. AVOID BREATHING OF VAPOR AND CONTACT WITH SKIN AND EYES. MAY CAUSE IRRITATION TO SKIN AND EYES. SEVERE OVEREXPOSURE MAY CAUSE FATIGUE, WEAKNESS, CONFUSION, HEADACHE, DIZZINESS, DROWSINESS, AND IMPAIRED JUDGMENT. USE REGULATORY AGENCY APPROVED RESPIRATORY PROTECTION FOR SPRAY APPLICATIONS. THIS PRODUCT CONTAINS LEAD, A CUMULATIVE POISON. WASH HANDS WELL BEFORE EATING, DRINKING, OR SMOKING. PROTECTIVE GLOVES SHOULD BE WORN DURING MIXING APPLICATION. PROLONGED OR REPEATED CONTACT WITH THIS EPOXY PRIMER MAY RESULT IN A PERMANENT SKIN ALLERGY TO 463-6-27 BASE AND X337 CONVERTER. PRIOR TO USE OF THIS PRODUCT, CAFEFULLY READ THE "MATERIAL SAFETY DATA SHEET" AND FOLLOW ALL

- (9) Mix 463-6-27 base (CoMat 07-071), X337 converter (CoMat 07-067), and TL52-66 thinner (CoMat 07-066) with manufacturer's instructions.
- (10) Apply the primer with a brush to the repair surface.

LISTED SAFETY AND HEALTH PRECAUTIONS.

(11) Cure the primer for seven hours at room temperature or for 40 minutes at 140°-180°F (60°-82°C) with an explosion-proof heat lamp.

October 15, 1995 Revision 1 - May 9/17



Aero Engines SERVICE BULLETIN


- (12) Make a mark for hole locations on 290M0003-1. Refer to Figure 3.
- (13) Attach with a clamp 290M0003-1 fitting and two 290M0003-3 radius blocks to lower track assembly. Refer to Figure 4.
- (14) Drill fastener holes through fittings, lower track assemblies, and radius blocks.

NOTE: Select drill size based on HL148-5 diameter fasteners.

- (15) Remove clamps, fittings, and radius blocks from lower track assemblies.
- (16) Remove burrs and clean away metal chips or other unwanted material with dry air supply.
- (17) Apply liquid shim (CoMat 08-021) to radius block and track assembly(s) mating surfaces. Refer to Standard Practices/Processes Manual, Chapter 70-36-02.
- (18) Install 290M0003-1 fitting and two 290M0003-3 radius blocks on LH lower track assembly with HL48DU5-7 pins, HL48DU5-4 pins, and HL78DU5 collars. Refer to Figure 5. Refer to Standard Practices/Processes Manual, Chapter 70-39-03.
- (19) Clean away any unwanted liquid shim with a lint free cloth (CoMat 02-099) and trichloroethane (CoMat 01-001). Wipe surface dry before solvent becomes dry.
- (20) Install insulation blanket to best fit around fittings.
- (21) Remove any loose or unbonded sealant from insulation blanket and track assembly.

October 15, 1995 Revision 1 - May 9/17

M2500 International Aero Engines SERVICE BULLETIN



290M0003-1 FITTING 290M0003-2 OPPOSITE

VSB337

LANYARD FITTING HOLE LOCATIONS FIGURE 3


October 15, 1995

Revision 1 - May 9/17

V2500-NAC-78-0097



International Aero Engines SERVICE BULLETIN




VSB338

FITTING AND RADIUS BLOCK PLACEMENT FIGURE 4

October 15, 1995 Revision 1 - May 9/17 V2500-NAC-78-0097



International Aero Engines SERVICE BULLETIN



FITTING AND RADIUS BLOCK INSTALLATION FIGURE 5

October 15, 1995

Revision 1 - May 9/17

V2500-NAC-78-0097

Aero Engines SERVICE BULLETIN

- WARNING: DOW CORNING 1200 PRIMER IS FLAMMABLE AND VAPOR IS HARMFUL. USE IN A WELL VENTILATED AREA. WORK PERFORMED IN CONFINED AREAS REQUIRES THE USE OF ADDITIONAL FORCED MECHANICAL VENTILATION. AVOID BREATHING OF VAPOR OR PROLONGED OR REPEATED CONTACT WITH SKIN. MAY CAUSE IRRITATION TO SKIN, EYES, NOSE, AND THROAT. HIGH CONCENTRATIONS MAY CAUSE IMPAIRED JUDGMENT. PROTECTIVE GLOVES SHOULD BE WORN DURING USE. MAY CAUSE DERMATITIS BY REMOVING SKIN OILS.
- (22) Apply a thin layer of primer (CoMat 08-032) to outer edge of insulation blanket and fittings where sealant will be applied. Let primer dry a minimum of 30 minutes before sealant is applied.
- WARNING: USE SEALANT ONLY IN AREAS WITH GOOD VENTILATION. TAKE PRECAUTIONS TO PREVENT MATERIAL FROM COMING INTO CONTACT WITH SKIN. PRIOR TO USE OF THIS PRODUCT, CAREFULLY READ THE APPLICABLE 'MATERIAL SAFETY DATA SHEET' AND FOLLOW ALL LISTED SAFETY AND HEALTH PRECAUTIONS.
- (23) Use manufacturer's instructions to mix sealant (CoMat 08-030).
- (24) Fill gaps and seams between track assemblies, fittings, and insulation blankets with sealant.
- (25) Repeat steps (1) through (24) above for right hand thrust reverser.
- C. Postrequisite Instructions

None.

D. Recording Instructions

A record of accomplishment is necessary. Write in engine log and metal stamp, vibroetch, or electroetch on thrust reverser data plate that Service Bulletin V2500-NAC-78-0097 has been done. Refer to IAE V2500 Standard Practices Manual, Chapter 70-09-00.

October 15, 1995 Revision 1 - May 9/17 V2500-NAC-78-0097

Aero Engines SERVICE BULLETIN

3. Material Information

Applicability:

For each V2500-D5 Nacelle Thrust Reverser to

incorporate this Bulletin.

A. Kits associated with this Bulletin:

NEW PART NO (ATA NO)	<u>QTY</u>	EST'D UNIT <u>PRICE</u>	UNIT OLD PART		INSTR/ DISPOS	
V2578097-551 (Left Hand)		\$3520.00	Kit		(A)	
Consisting of: 290M0003-1 290M0003-3 HL48DU5-7 HL48DU5-4 HL78DU5	1 2 4 2 6		Fitting Radius Block Pin Pin Collar			
V2578097-553 (Right Hand) Consisting of: 290M0003-2	1	\$3520.00	Kit		(A)	
290M0003-2 290M0003-3 HL48DU5-7 HL48DU5-4 HL78DU5	1 2 4 2 6		Fitting Radius Block Pin Pin Collar			

B. Parts affected by this Bulletin:

None.

- C. Instructions/Dispositions Code Statements
 - (A) Kit will be available August 1995.

October 15, 1995

Revision 1 - May 9/17

V2500-NAC-78-0097



International Aero Engines SERVICE BULLETIN

The following material is to be procured by the operator or obtained from their stock.

Part Number	Keyword	Oty	Source	<u>Code</u>
Trichloroethane (CoMat 01-001)	Solvent	AR	Commercially Available	
Lint Free Cloth (CoMat 02-099)	Cloth	AR	Commercially Available	
463-6-27 (CoMat 07-071)	Base	AR	Akzo Coatings America Sikkens Aerospace	98502
X337 (CoMat 07-067)	Converter	AR	Finishes Division 20846 S. Normandie	
TL52-66 (CoMat 07-066)	Thinner	AR		
Hysol E.A. 934NA (CoMat 08-021)	Adhesive	AR	Dexter Adhesives & Structural Mat'ls Div 2850 Willow Pass Rd P.O. Box 312 Pittsburgh, CA 94565-3237 USA	33564
DC 1200 (CoMat 08-032	Primer	AR	Dow Corning Corp P.O. Box 1-M Midland, MI	71984
DC 90-006 (CoMat 08-030)	Sealant	AR	48686-0997 USA	

October 15, 1995 Revision 1 - May 9/17 V2500-NAC-78-0097 Page 16