### International Aero Engines

# **INFORMATION BULLETIN**

STANDARD PRACTICES - ENGINE - INFORMATION - TO ANNOUNCE A REDESIGNED IGNITER MOUNT
BRACKET - CATEGORY CODE 7 - MOD.ENG-70-0033

#### 1. Planning information

#### A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1

#### B. Reason

To announce the redesigned igniter mount bracket including alternative parts.

#### C. <u>Compliance</u>

Category Code 7

Accomplish when supply of the superseded parts have been depleted.

#### D. Approval

(1) The part number transactions shown under the MATERIAL INFORMATION paragraph have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

#### E. Reference

(1) Internal Reference No.

EC88VJ659

#### F. General Information

- (1) New configurations of the igniter mount brackets are introduced to improve the productivity. In addition, the bonding leads are rerouted accompanying with the introduction of new brackets.
- (2) The Material Information portion of this Bulletin provides the latest information concerning the availability of new and old brackets.
- (3) Other Publications Affected:
  - (a) The V2500 Power Plant Illustrated Parts catalog will be revised to include the new parts.
  - (b) The V2500 Engine Illustrated Parts Catalog will be revised to include the new parts.

V2500-ENG-70-0033

### International Aero Engines

# **INFORMATION BULLETIN**

- (c) The V2500 Engine Manual, Chapter/Section 72-00-40 Removal and Installation, will be revised to change fixing route of the bonding leads.
- (d) The V2500 Component Maintenance Manual, Chapter/Section 74-11-38 Cleaning, will be revised to add the new parts.
- (e) The V2500 Component Maintenance Manual, Chapter/Section 74-11-38 Inspection/Check, will be revised to add the new parts.

## 2. Accomplishment Instructions

Not applicable.

### International Aero Engines

01d

5T0005

5T0005

(01-750)

(01-750)

(S1) (A) (B)

(S1) (A) (B)

(E)

# INFORMATION BULLETIN

#### 3. Material Information

New

5T0049

5T0050

(74-11-38)

(74-11-38)

Part No.	Qty	Unit Price (\$)	Keyword	Part No. (IPC No.)	Instructions Disposition
Applicabilit	y: For	each V2500	Engine to incorpora	ate this Bull	etin.
5T0047 (74-11-38)	1	490.00	Bracket	5T0023 (01-350)	(S1) (A) (B)
5T0048 (74-11-38)	Ref.	-	Bracket	5T0023 (01-350)	(S1) (A) (B) (C)

### A. Instruction/Disposition Code Statements:

613.00

1

Ref.

Est'd

(S1) Old and new parts are freely and fully interchangeable, both physically and functionally.

Bracket

Bracket

- (A) New parts are currently available.
- (B) Old parts will continue to be available until supply of old parts has been depleted.
- (C) New part is alternative to 5T0047.
- (E) New part is alternative to 5T0049.

NOTE: The estimated 1990 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.