



STANDARD PRACTICES - ENGINE - INFORMATION - TO ANNOUNCE THE AVAILABILITY OF FAN CASE
REPAIR PARTS - CATEGORY CODE 8 - MOD.ENG-70-0066

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1

B. Reason

To announce that the fan case repair parts are introduced for future repair only.

C. Compliance

Category Code 8

Accomplish based upon experience with the prior configuration.

D. Approval

The part number transactions shown under the Material Information portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

(1) Internal Reference No.

EC89VJ113

(3) The V2500 Illustrated Parts Catalog, 72-32-85 FIG 01.

(4) The V2500 Engine Manual, 72-32-85.

Applicable TASK numbers for each repair part are as follows:


(a) TASK 72-32-85-300-007: 5R0078

(b) TASK 72-32-85-300-008: 5R0079

(c) TASK 72-32-85-300-010: 5R0080, 5R0081 and 5R0082

(d) TASK 72-32-85-300-014: 5R0083, 5R0084, 5R0085, 5R0086 and 5R0087

V2500-ENG-70-0066



International Aero Engines
INFORMATION BULLETIN

Printed in Great Britain


F. General Information

- (1) The Material Information portion of this Bulletin provides the latest information concerning the availability of the new repair parts.
- (2) Other publications affected:
- (a) The following Repair Schemes will be incorporated to Engine Manual, 72-32-85.
- (i) VRS1955: 5R0078
- (ii) VRS1956: 5R0079
- (iii) VRS1958: 5R0080, 5R0081 and 5R0082
- (vi) VRS1959: 5R0083, 5R0084, 5R0085, 5R0086 and 5R0087
- (b) The V2500 Power Plant Illustrated Parts Catalog 72-32-85, will be incorporated to add the new repair parts.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
5R0078 (72-32-85)	AR	586.00	..Lining A/O Front - Repair	- (01-930)	(A)
5R0079 (72-32-85)	AR	668.00	..Lining A/O Rear - Repair	- (01-940)	(A)
5R0080 (72-32-85)	AR	610.00	..Lining A/O Acoustic - Repair	- (01-950)	(A)
5R0081 (72-32-85)	1	610.00	..Lining A/O Acoustic - Repair	- (01-955)	(A)
5R0082 (72-32-85)	1	610.00	..Lining A/O Acoustic - Repair	- (01-960)	(A)
5R0083 (72-32-85)	AR	762.00	..Panel A/O Acoustic - Repair	- (01-960)	(A)
5R0084 (72-32-85)	AR	337.00	..Panel A/O Middle - Repair	- (01-905)	(A)
5R0085 (72-32-85)	1	434.00	..Panel A/O Middle - Repair	- (01-910)	(A)
5R0086 (72-32-85)	AR	410.00	..Panel A/O Rear - Repair	- (01-915)	(A)

V2500-ENG-70-0066



International Aero Engines
INFORMATION BULLETIN

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
5R0087 (72-32-85)	1	410.00	..Panel A/O Rear - Repair	- (01-920)	(A)

NOTE: 1. The estimated 1991 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

2. AR: As required

H. Instruction/Disposition Code Statements:

(A) The new part is used for repair only and currently available for sale.

V2500-ENG-70-0066

May.8/92

Page 3

