

### International Aero Engines

**INFORMATION BULLETIN** 

# STANDARD PRACTICES - ENGINE - INFORMATION - TO ANNOUNCE VARIOUS THICKNESS LPT SHAFT ADJUSTING WASHERS - CATEGORY CODE 7 - MOD.ENG-70-0087

#### 1. Planning Information

#### A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1

#### B. Reason

To announce the availability of various thickness LPT Shaft adjusting washers.

#### C. <u>Compliance</u>

Category 7

Accomplish when supply of superseded parts has been depleted.

#### D. Approval

The part number transaction shown under the MATERIAL INFORMATION portion of this bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

#### E. References

(1) Internal Reference No.

EC89VJ005

#### F. General Information

- (1) Six different LPT Shaft adjusting washers which cover a thickness ranges from 0.4823in. (12,250 mm.) up to 0.5069in. (12.875 mm.) are provided to make the LPT Rotor adjusting easier.
- (2) Other Publications Affected:
  - (a) V2500 Engine Illustrated Parts Catalog; Chapter/Section 72-00-50 will be revised to show the new part numbers.
  - (b) V2500 Engine Manual, 72-00-50, Removal, Installation, Cleaning and Inspection/Check will be revised to include the new part numbers.

V2500-ENG-70-0087

# International Aero Engines

# INFORMATION BULLETIN

## G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
5A0371 (72-00-50)	1		.Ring, adjust	5A0371 (01-300)	(B)(1)
5A0344 (72-00-50)	1		.Ring, adjust	- (01-303)	(A)
5A0345 (72-00-50)	1		.Ring, adjust	- (01-304)	(A)
5A0346 (72-00-50)	1		.Ring, adjust	- (01-305)	(A)
5A0414 (72-00-50)	1		.Ring, adjust	- (01-306)	(A)
5A0415 (72-00-50)	1		.Ring, adjust	- (01-307)	(A)
5A0416 (72-00-50)	1		.Ring, adjust	_ (01-308)	(A)

#### H. Instruction/Disposition Code Statements:

- (A) New Part will be available approximately November 1990.
- (B) Old Part will continue to be available for sale.
- (1) Old Part shall only be used and machined to required washer thickness in case that the adjusting washer introduced by this service bulletin is not adequate.

NOTE: The estimated 1991 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult IAE'S Spare Parts Sales Department for information concerning firm prices.