



International Aero Engines

SERVICE BULLETIN

Date: Feb.25/00

**Subject: Transmittal of Revision 1 to Service Bulletin
No.V2500-ENG-70-0168**

Service Bulletin Revision History:

Event	Date
Basic Issue	Feb.24/92
Revision 1	Feb.25/00

Reason for Issuance of Revision:

To add missing statement, "ATA No." "IPC No." "Instruction/Disposition Codes".

Effect on Past Compliance:

None

List of Effective Pages:

	Bulletin Page No.	Rev. No.	Effective Date
R	1	1	Feb.25/00
	2	Basic	Feb.24/92
R	3	1	Feb.25/00

V2500-ENG-70-0168

**Transmittal
Page 1 of 1**



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE
THE AVAILABILITY OF AN INLET CONE REPAIR DETAIL

MODEL APPLICATION

V2500-A1

BULLETIN INDEX LOCATOR

72-38-00

Compliance Category Code

7

Internal Reference No.

EC91VJ037

Feb.24/92

R Revision 1 Feb.25/00

V2500-ENG-70-0168

Page 1 of 3



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE
THE AVAILABILITY OF AN INLET CONE REPAIR DETAIL

A. Effectivity

- (1) Aircraft: Airbus A320
- (2) Engine: V2500-A1

B. Reason

To announce availability of newly released Repair Parts.

C. Compliance

Category Code 7

This Bulletin is introduced for record purposes only.

D. Approval

- (1) The part number transactions are given in the Material Information section of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model listed.
- (2) IAE sanctioned the release of the remainder of the data shown in this Bulletin which have been duly approved by the IAE Authorization Document Numbers that appear under Paragraph E.(2) of this Bulletin.

E. Reference

- (1) IAE Engineering Change No. 91VJ037.
- (2) IAE Authorization Document No. 91VJ718 (for VRS1467).

F. General Information

- (1) New Repair Scheme being introduced into the V2500 Engine Manual which require special repair parts for its accomplishment:

ATA Ref.No.	Repair Scheme No.	Title
72-38-11	VRS1467	Inlet Cone - Replace the Segment

(For special repair part required, see 'Material Information'.)

Feb. 24/92

V2500-ENG-70-0168

Page 2



International Aero Engines INFORMATION BULLETIN

G. Material Information

	New		Est'd		Old	
	Part No.		Unit		Part No.	Instr.
R	(ATA No.)	Qty	Price(\$)	Keyword	(IPC No.)	/Disp.

The following Special Repair Parts is required to accomplish Repair Scheme No.VRS1467:

R	5A1415	6		...Segment, Locating	-	(A)
	(72-38-11)				(01-300)	

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's spare parts sales department.

R H. Instruction/Disposition Codes

(A) New part is currently available.

Feb.24/92
Revision 1 Feb.25/00

V2500-ENG-70-0168
Page 3