

International Aero Engines

INFORMATION BULLETIN

STANDARD PRACTICES - ENGINE - INFORMATION - TO ANNOUNCE THE AVAILABILITY OF WEIGHT REDUCED FAN CASE REPAIR PARTS - CATEGORY CODE 8 - MOD.ENG-70-0198

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1 Engines

B. Reason

To announce that the weight reduced fan case repair parts are introduced for future repair only.

C. <u>Compliance</u>

Category Code 8

Accomplish based upon experience with the prior configuration.

D. <u>Approval</u>

The part number transactions shown under the Material Information portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

(1) Internal Reference No.

EC91VJ048

(2) Other References


The V2500 Illustrated Parts Catalog, 72-32-85 FIG. 01.

IAE Service Bulletin, V2500-ENG-72-0103.

F. General Information

- (1) The Material Information portion of this Bulletin provides the latest information concerning the availability of the new repair parts.
- (2) Other publications affected:
 - (a) The following Repair Schemes will be incorporated to Engine Manual, 72-32-85.

V2500-ENG-70-0198



INFORMATION BULLETIN

(i) VRS1538: 5R0182

(ii) VRS1539: 5R0183, 5R0184

(iii) VRS1540: 5R0185, 5R0186, 5R0187

G. Material Information

| New Part No. (ATA No.) | Qty | Est'd Unit Price (\$) | Keyword | | Instruction/ Disposition |
|------------------------------|-----|-----------------------------|------------------------|----------|-----------------------------|
| | | | | | |
| 5R0182 | AR | | Lining, A/O Attrition | 5R0078 | (A)(B) |
| (72-32-85) | | | - Repair | (01-930) | (1) |
| _ | AR | | Lining, A/O Rear - | 5R0079 | (B) |
| (72-32-85) | | | Repair | (01-940) | |
| 5R0185 | AR | | Lining, A/O Acoustic - | 5R0080 | (A)(B) |
| (72-32-85) | | | Repair | (01-950) | (1) |
| 5R0186 | 1 | | Lining, A/O Acoustic - | 5R0081 | (A)(B) |
| (72-32-85) | | | Repair | (01-955) | (1) |
| 5R0187 | 1 | | Lining, A/O Acoustic - | 5R0082 | (A)(B) |
| (72-32-85) | | | Repair | (01-960) | (1) |
| - | AR | | Panel, A/O Front - | 5R0083 | (B) |
| (72-32-85) | | | Repair | (01-900) | |
| 5R0183 | AR | | Panel, A/O Ice Impact | 5R0084 | (A)(B) |
| (72-32-85) | | | - Repair | (01-905) | (1) |
| 5R0184 | 1 | | Panel, A/O Ice Impact | 5R0085 | (A)(B) |
| (72-32-85) | | | - Repair | (01-910) | (1) |
| - | AR | | Panel, A/O Rear - | 5R0086 | (B) |
| (72-32-85) | | | Repair | (01-915) | |
| - | 1 | | Panel, A/O Rear - | 5R0087 | (B) |
| (72-32-85) | | | Repair | (01-920) | |

NOTE: 1. The estimated 1992 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

2. AR: As required

H. Instruction/Disposition Code Statements:

- (1) Old and new parts are not interchangeable, either physically or functionally.
- (A) The new part is used for repair only and currently available for sale.
- (B) Old part will continue to be available for sale.

V2500-ENG-70-0198