



STANDARD PRACTICES – ENGINE – INFORMATION – ENGINE – PROVIDE REPAIR PARTS FOR REPAIR OF
THE TURBINE EXHAUST CASE GROUND HANDLING/MOUNT BUSHINGS – NOT APPLICABLE –
MOD.ENG-70-0204

1. Planning Information

A. Effectivity

- (1) Aircraft: Airbus A320
- (2) Engine: V2500-A1

B. Reason

To announce the availability of the required repair parts to allow the replacement of the ground handling/mount bushes on the turbine exhaust case.

C. Compliance

For information only

D. Approval

- (1) The part number transaction shown under Material Information in paragraph has been shown to comply with the applicable Federal Aviation Regulation and are FAA-APPROVED for the Engine Model listed.
- (2) IAE sanctioned the release of the remainder of data shown in this Bulletin which have been duly approved by the IAE Authorization Document Numbers that appear under Paragraph E (4)

E. Reference

- (1) Internal Reference No.

EC90VF002

EC93VF030

ECV93F030A

F. General Information

- (1) Part numbers are required to accomplish Repair Schemes VRS5393 and VRS5394 for removal and replacement of the ground handling/ mount bushes on the turbine exhaust case.
- (2) Other Publications Affected:

V2500-ENG-70-0204



International Aero Engines
INFORMATION BULLETIN

(a) The V2500 Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for the ATA locations.

(b) The V2500 Engine Manual will be revised to include the new parts. See "Material Information" section for the ATA locations.

G. Material Information

| New Part No. (ATA No.) | Qty | Est'd Unit Prices (\$) | Keyword | Old Part No. (IPC No.) | Instruction Disposition |
|------------------------------|-----|------------------------------|---------|------------------------------|----------------------------|
|------------------------------|-----|------------------------------|---------|------------------------------|----------------------------|

(1) The following Repair Parts are required to accomplish Repair Scheme VRS5393.


| | | | | | |
|-------------------------|-----|---|--------|---------------|-----|
| 4P8117C01 (72-50-53) | A/R | - | ..Bush | - (02-494) | (A) |
| 4P8117C02 (72-50-53) | A/R | - | ..Bush | - (02-495) | (A) |
| 4P8117C03 (72-50-53) | A/R | - | ..Bush | - (02-496) | (A) |
| 4P8117C04 (72-50-53) | A/R | - | ..Bush | - (02-497) | (A) |
| 4P8117C05 (72-50-53) | A/R | - | ..Bush | - (02-498) | (A) |

(2) The following Repair Parts are required to accomplish Repair Scheme VRS5394.

| | | | | | |
|-------------------------|-----|---|--------|---------------|-----|
| 4P8118C01 (72-50-53) | A/R | - | ..Bush | - (02-484) | (A) |
| 4P8118C02 (72-50-53) | A/R | - | ..Bush | - (02-485) | (A) |
| 4P8118C03 (72-50-53) | A/R | - | ..Bush | - (02-486) | (A) |
| 4P8118C04 (72-50-53) | A/R | - | ..Bush | - (02-487) | (A) |
| 4P8118C05 (72-50-53) | A/R | - | ..Bush | - (02-488) | (A) |

Printed in Great Britain

V2500-ENG-70-0204



H. Instruction/Disposition Code Statements.

(A) New part is currently available.

NOTE: The estimated 1993 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

