



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - LP COMPRESSOR - INTRODUCE PARTS
FOR VARIOUS FAN CASE REPAIRS - CATEGORY CODE 8 - MOD.ENG-70-0208

1. Planning Information

A. Effectivity

- (1) Aircraft: (a) Airbus A321
(b) McDonnell Douglas MD-90
- (2) Engine : (a) V2500 - A5
(b) V2500 - D5

B. Reason

To announce new Fan Case repair parts which are introduced for future repair only.

C. Compliance

Category Code 8

Accomplish based upon experience with the prior configuration.

D. Approval

The part number transactions shown under the Material Information portion of this Bulletin have been FAA-APPROVED for the Engine Model listed.

E. References

- (1) Internal Reference No.

93VJ005

- (2) Other References

V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-32-85.

V2500 Power Plant Illustrated Parts Catalog, Chapter/Section 72-32-85.

F. General Information

- (1) The Material Information portion of this Bulletin provides the latest information concerning the availability of the new repair parts.
- (2) Other Publications affected:

V2500-ENG-70-0208



International Aero Engines
INFORMATION BULLETIN

- (a) The following Repair Schemes will be incorporated into Engine Manual, 72-32-85 for replacement repairs of the linings and panels.

Repair Scheme	Part No.
VRS1840	5R0274
VRS1841	5R0272, 5R0273
VRS1842	5R0185, 5R0186, 5R0187

NOTE: Acoustic Linings P/N 5R0185, 5R0186 and 5R0187 are same as those of V2500-A1 Engines and can be used for V2500-A5 and V2500-D5 Engines.

- (b) V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-32-85 will be revised to incorporate this new part.


- (c) V2500 Power Plant Illustrated Parts Catalog, Chapter/Section 72-32-85 will be revised to incorporate the new part.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
5R0272 (72-32-85)	AR		..Panel, A/O Ice Impact - Repair	- (01-905)	(A)
5R0273 (72-32-85)	1		..Panel, A/O Ice Impact - Repair	- (01-910)	(A)
5R0274 (72-32-85)	AR		..Lining, A/O Attrition - Repair	- (01-930)	(A)
5R0185 (72-32-85)	AR	2501.00	..Lining, A/O Acoustic - Repair	- (01-950)	(A)
5R0186 (72-32-85)	1	2501.00	..Lining, A/O Acoustic - Repair	- (01-955)	(A)
5R0187 (72-32-85)	1	2501.00	..Lining, A/O Acoustic - Repair	- (01-960)	(A)

Printed in Great Britain

V2500-ENG-70-0208



H. Supply Status Code Statements:

(A) The new part is used for repair only and currently available for sale.

- NOTE:
1. The estimated 1994 unit prices shown are provided for planning purposes only and does not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.
 2. AR: As Required

