

International Aero Engines

INFORMATION BULLETIN

STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - HP COMPRESSOR - TO ANNOUNCE THE AVAILABILITY OF REPAIR PARTS FOR THE STAGE 10 COMPRESSOR CASE ASSEMBLY - CATEGORY CODE 8 - MOD.ENG-70-0216

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine : V2500-A1

B. Reason

To announce the availability of newly releases Repair Parts.

C. <u>Compliance</u>

Category Code 8

Accomplish based upon experience with the prior configuration.

D. <u>Approval</u>

The part number transactions shown under the MATERIAL INFORMATION portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

(1) Internal Reference No.

EC92VR753

F. General Information

New Repair Scheme being introduced into the V2500 Engine Manual which requires Special Repair Parts for its accomplishment.

Ala Ret No. Repair Scheme		IITLE
72-41-21	VRS 6331	Compressor Case Assembly - Stage 10 - Replace loose or damaged rivets and/or worn sealing rings.

(For Special Repair Parts required, see 'Material Information'.)

V2500-ENG-70-0216



International Aero Engines

INFORMATION BULLETIN

G. Material Information

New		Est'd		Old	
Part No.		Unit		Part No.	Supply
(ATA No.)	Qty	Price (\$)	Keyword	(IPC No.)	Status

The following Special Repair Parts are required to accomplish Repair Scheme VRS 6331.

AS16247 (72-41-21)	A/R	0.83	Rivet	- (04-402)	(A)
AS16288 (72-41-21)	A/R	0.89	Rivet	- (04-403)	(A)
6A1252 (72-41-21)	A/R	3136.00	Ring, Sealing	- (04-406)	(A)

A/R - As Required

H. Supply Status Code Statement

(A) New part is currently available.

NOTE: The estimated 1994 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.