



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE THE
AVAILABILITY OF REPAIR PARTS TO SUPPORT VARIOUS REPAIR SCHEMES - NOT APPLICABLE -
MOD.ENG-70-0220

Printed in Great Britain

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1

B. Reason

To announce changes in various spareability codes.

C. Compliance

For information only.

D. Approval

IAE sanctioned the release of data shown in this bulletin which have been duly approved by the IAE Authorization Document Number(s) that appear under paragraph E, of this bulletin.

E. References

(1) Internal Reference No.

EC87VJ075-01

EC87VJ084-02

EC87VJ122-02

EC87VJ182-05

F. General Information


(1) Information in this Bulletin does not effect quantity and installation of parts. Only parts spareability coding.

(2) 72-31-11

(a) The spareability coding for the Pin, part number 5A1116 item number 01-180 changes from not spareable to potential spare for overhaul use only and introduce the new repair scheme (VRS 1010).

(3) 72-32-03

V2500-ENG-70-0220



International Aero Engines
INFORMATION BULLETIN

Printed in Great Britain

- (a) The spareability coding for the Nut, part number 4W0039 item number 02-220 changes from not spareable to potential spare for overhaul use only and introduce the new repair scheme (VRS 1920).

(4) 72-32-93

- (a) The spareability coding for the Seal Rubber, part number 5A3455 item number 01-210 changes from not spareable to potential spare for overhaul use only and introduce the new repair scheme (VRS 1445).
- (b) The spareability coding for the Cushion Rubber, part number 5A3448 item number 01-220 changes from not spareable to potential spare for overhaul use only and introduce the new repair scheme (VRS 1446).

(5) 72-38-11

- (a) The spareability coding for the Inlet Cone Tip, part number 5A0016 item number 01-240 changes from not spareable to potential spare for overhaul use only and introduce the new repair scheme (VRS 1462).


(6) Other publications affected:

- (a) The V2500 Engine Illustrated Parts Catalog will be revised to add the affected parts.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instruction Disposition
5A1116 (72-31-11)	1	42.40	...Pin, locating	5A1116 (01-180)	(A)(B)
4W0039 (72-32-03)	4	8.31	..Nut, self locating plate	4W0039 (02-220)	(A)(B)
5A3455 (72-32-93)	1	20.10	..Seal rubber	5A3455 (01-210)	(A)(B)
5A3448 (72-32-93)	3	41.30	..Cushion rubber	5A3448 (01-220)	(A)(B)
5A0016 (72-38-11)	1	62.00	..Tip, Inlet cone	5A0016 (01-240)	(A)(B)

V2500-ENG-70-0220



International Aero Engines

INFORMATION BULLETIN

H. Instruction Disposition Code Statement

(A) New part is currently available

(B) Changes the spareability code from not spareable to overhaul use only.

NOTE: The estimated 1993 unit prices shown are provided for planning purposes and do not constitute a firm quotation. Consult the IAE Prices Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain

V2500-ENG-70-0220

Nov. 8/93

Page 3

