



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - TO ANNOUNCE THE AVAILABILITY OF A
STEEL BUSHING TO SUPPORT REPAIR OF THE FAN CASE ASSEMBLY - NOT APPLICABLE -
MOD.ENG-70-0232

1. Planning Information

A. Effectivity

- (1) Aircraft: (a) Airbus A320
- (2) Engine : (a) V2500-A1

B. Reason

To announce the availability of a newly released repair part.

C. Compliance

Not applicable

D. Approval

The part number transaction shown under the Material Information in paragraph G, has been shown to comply with the applicable Federal Aviation Regulation and are FAA-APPROVED for the Engine Model listed.

E. References

- (1) Internal Reference No.

92VJ062
92VJ062A

F. General Information

- (1) The Repair Scheme has been introduced into the V2500-A1 Engine Manual which requires Special Repair Parts for its accomplishment:

ATA No. -----	Repair Scheme -----	Title -----
72-32-85	VRS1413	Bushing Repair

(For Special Repair Part required, See 'Material Information')

- (2) V2500 Engine Illustrated Parts Catalog (S-V2500-1IA), Chapter/Section 72-32-85, Figure 01.

V2500-ENG-70-0232



International Aero Engines
INFORMATION BULLETIN

(3) V2500 Engine Manual (E-V2500-1IA), Chapter/Section 72-32-85,
Inspection/Check.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
------------------------------	-----	-----------------------------	---------	------------------------------	------------------

(1) The following Repair Part is required to accomplish
Repair No. VRS1413.

5A1482 (72-32-85)	1	169.00	..Bush	--- (01-990)	(A)
----------------------	---	--------	--------	-----------------	-----

H. Supply Status Code Statement:

(A) New part is currently available.

NOTE: The estimated 1995 unit price shown is provided
for planning purpose only and does not constitute
a firm quotation. Contact IAE's Spare Parts
Sales Department for information concerning firm
price.

Printed in Great Britain

V2500-ENG-70-0232