



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - TO ANNOUNCE THE AVAILABILITY OF
VARIOUS AIR TUBE REPAIR PARTS - NOT APPLICABLE - MOD.ENG-70-0268

1. Planning Information

A. Effectivity

- (1) Aircraft: Airbus A320
(2) Engine : V2500-A1

B. Reason

To announce the availability of newly released Repair Parts.

C. Compliance

For information only.

D. Approval

The part number transactions shown under the MATERIAL INFORMATION portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

- (1) Internal Reference No.

EC90VR738

EC90VR740


F. General Information

New Repair Schemes being introduced into the V2500 Engine Manual which require Special Repair Parts for their accomplishment.

ATA Ref No. -----	Repair Scheme -----	Title -----
36-11-47	VRS 6400	Air tubes - Engine - Replace Welded Connectors or adaptors.
36-11-47	VRS 6402	Air tubes - Engine - replace the brazed on clip.

(For Special Repair Parts required, see 'Material Information'.)

V2500-ENG-70-0268



International Aero Engines
INFORMATION BULLETIN

G. Material Information


New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
------------------------------	-----	-----------------------------	---------	------------------------------	------------------

(1) The following Special Repair Parts are required to accomplish Repair Scheme VRS 6400.

AS15777 (36-11-47)	A/R	3.15	Wire, thrust	- (01-200)	(A)
AS15701 (36-11-47)	A/R	11.00	Nut, tube coupling	- (01-201)	(A)
LK56511 (36-11-47)	A/R	-	Ferrule assy	- (01-202)	(A)
AS15777 (36-11-47)	A/R	3.15	Wire, thrust	- (01-240)	(A)
AS15701 (36-11-47)	A/R	11.00	Nut, tube coupling	- (01-241)	(A)
AS15768 (36-11-47)	A/R	15.70	Ferrule Assy	- (01-242)	(A)
UP11028 (36-11-47)	A/R	-	Adaptor	- (01-602)	(A)
AS15802 (36-11-47)	A/R	-	Adaptor	- (01-642)	(A)
AS15777 (36-11-47)	A/R	3.15	Wire, thrust	- (02-200)	(A)
AS15701 (36-11-47)	A/R	11.00	Nut, tube coupling	- (02-201)	(A)
AS15768 (36-11-47)	A/R	15.70	Ferrule Assy	- (02-202)	(A)
AS15802 (36-11-47)	A/R	-	Adaptor	- (02-242)	(A)
AS15777 (36-11-47)	A/R	3.15	Wire, thrust	- (02-600)	(A)
AS15701 (36-11-47)	A/R	11.00	Nut, tube coupling	- (02-601)	(A)

Printed in Great Britain

V2500-ENG-70-0268



International Aero Engines
INFORMATION BULLETIN

Printed in Great Britain

AS15768 (36-11-47)	A/R 15.70	Ferrule assy	- (02-602)	(A)
AS15802 (36-11-47)	A/R -	Adaptor	- (03-202)	(A)
JR16546 (36-11-47)	A/R 62.20	Reducer	- (03-218)	(A)
AS15778 (36-11-47)	A/R 3.15	Wire, thrust	- (03-240)	(A)
AS15702 (36-11-47)	A/R 17.20	Nut, tube coupling	- (03-241)	(A)
LK40971 (36-11-47)	A/R 205.00	Adaptor	- (03-242)	(A)

(2) The following Special Repair Parts are required to accomplish Repair Scheme VRS 6402.

LK39602 (36-11-47)	A/R 2.70	Clip	- (01-214)	(A)
LK39602 (36-11-47)	A/R 2.70	Clip	- (01-614)	(A)
LK39602 (36-11-47)	A/R 2.70	Clip	- (02-214)	(A)

A/R = As required

H. Supply Status Code Statement

(A) New part number is currently available.

NOTE: The estimated 1994 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

V2500-ENG-70-0268

Jan.14/94

Page 3

