



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: Aug. 8/05

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

V2500-A1/A5 SERIES PROPULSION SYSTEMS INFORMATION SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin EV2500-70-0274 and the Initial Issue of the Supplement

Bulletin Initial Issue

Remove	Incorporate	Reason for change
	Pages 1 to 4 of the	Initial issue
	Service Bulletin	

Supplement Initial Issue

Remove	Incorporate	Reason for change
	Page 1	Initial issue

V2500-ENG-70-0274
Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		Aug.8/05
2		Aug.8/05
3		Aug.8/05
4		Aug.8/05

Supplement		
------------	--	--

1		Aug.8/05
---	--	----------

Printed in Great Britain

INFORMATION – ENGINE – TO ANNOUNCE THE AVAILABILITY OF ALTERNATIVE PART FOR THE AIR
COOLED OIL COOLER INLET DUCT

1. Planning Information

A. Effectivity

(1) Aircraft:

- (a) Airbus A319
- (b) Airbus A320
- (c) Airbus A321

(2) Engine:

- (a) V2500-A1
- (b) V2522-A5
- (c) V2524-A5
- (d) V2527-A5
- (e) V2527E-A5
- (f) V2527M-A5
- (g) V2530-A5
- (h) V2533-A5

B. Reason

To announce the availability of alternative part for the Air Cooled Oil Cooler (ACOC) Inlet Duct.

C. Compliance

For information only.

D. Approval

The part number transactions shown under the MATERIAL INFORMATION section of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model(s) listed.

E. References

- (1) Engine Manual, Chapter/Section 72-00-32, Removal and Installation.
- (2) Internal Reference No. 01VJ002.
- (3) ATA Locator - 79-21-42.

F. Other Publications Affected

- (1) Component Maintenance Manual (CMM), Tubes, Hoses and Ducts (THD), Chapter/Section 79-21-42, Cleaning, Inspection and Repair.

G. General Information

The Material Information section of this Bulletin provides the latest information concerning the availability of the affected parts.

2. Material Information

A. Parts required to accomplish this Service Bulletin:

Applicability: For each V2500 engine to incorporate this Bulletin.

79-21-42

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	OLD PART NO.	INSTR DISP
01-400	5T0170	1	.Duct, A/O Inlet	-	(A)(B)

B. Instruction Disposition Codes

(A) New part will be available from March 2001.

(B) Alternative to 5T0067.

3. Accomplishment Instructions

A. Rework Instructions

None.

B. Assembly Instructions

For the correct assembly instructions refer to Engine Manual, Chapter/Section 72-00-32, Removal and Installation.

INFORMATION – ENGINE – TO ANNOUNCE THE AVAILABILITY OF ALTERNATIVE PART FOR THE AIR
COOLED OIL COOLER INLET DUCT

SUPPLEMENT – PRICES AND AVAILABILITY

The prices (if shown) are for estimating purposes only and as such as are given in good faith, without commercial liability for advanced planning purposes only. Refer to IAE Spare and/or current price catalogue for current prices.

1. Modification Kit:

Not applicable.

2. Parts Required:

Part No.	Description	Unit Price US Dollars
5T0170	Duct, A/O Inlet	22,680.00

3. Tools

None

Aug. 8/05
Aug. 8/05

V2500–ENG–70–0274
Supplement Page 1 of 1

© Rolls–Royce plc

Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).