



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: Jun.30/05

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

V2500-A1/A5/D5 PROPULSION SYSTEMS SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin EV2500-70-0277

Bulletin Initial Issue

Remove	Incorporate Pages 1 to 3 of the Service Bulletin	Reason for change Initial issue
--------	--	------------------------------------

V2500-ENG-70-0277
Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		
---	--	--

		Jun.30/05
--	--	-----------

2		
---	--	--

		Jun.30/05
--	--	-----------

3		
---	--	--

		Jun.30/05
--	--	-----------

Printed in Great Britain

INFORMATION – INTRODUCTION OF ALTERNATIVE SPAREABLE PART NUMBERS FOR BULK STOCK ITEMS

Printed in Great Britain

1. Planning Information**A. Effectivity**

- (1) Airbus A319
V2522-A5, V2524-A5, V2527M-A5 Engines.
- (2) Airbus A320
V2500-A1 Engines.
V2527-A5, V2527E-A5 Engines.
- (3) Airbus A321
V2530-A5, V2533-A5 Engines.
- (4) Boeing – Longbeach Division MD-90
V2525-D5, V2528-D5 Engines.

B. Reason

The current bulk stock part numbers are of an indefinite length and may cause procurement problems.

This information bulletin is raised to announce the availability of a spareable reel, of a defined length, to facilitate procurement of the associated bulk stock items.

C. Compliance

For Information Only.

D. Approval

The part number transactions shown in section 2. Material Information of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA approved for the engine models listed.

E. References

- (1) IAE Engineering Change Number – 01VR001.
- (2) ATA Locator – 71-52-43 and 71-52-51.

F. General Information

- (1) The Material Information section of this Service Bulletin provides the latest information concerning the availability of the affected parts.

2. Material Information

A. Affected Parts

(1) V2500-A1 and A5 Engines

71-52-43

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
03743	U440344	1	..Tubing (Bulk Stock U322766)	-	-	(A)(B)
03743	U322766	REF	..Tubing to RK6014	-	U322766	(B)(D)
03743	U440345	1	..Sleeve (Bulk Stock 1017015)	-	-	(A)(B)
03743	SVT48	REF	..Sleeve Shrink		SVT48	(B)(D)

(2) V2500-D5 Engines

71-52-51

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
03310	U440344	1	..Tubing (Bulk Stock U322766)	-	-	(A)(C)
03310	U322766	REF	..Tubing to RK6014	-	U322766	(C)(D)
03310	U440345	1	..Sleeve (Bulk Stock 1017015)	-	-	(A)(C)
03310	SVT48	REF	..Sleeve Shrink		SVT48	(C)(D)

B. Instructions disposition codes:

(A) New part is currently available.

(B) Parts coded (B) are alternatives.

(C) Parts coded (C) are alternatives.

(D) Part will not be made available as future spare for replenishment purposes.

3. Accomplishment Instructions

None.