400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE:- 860 565 5515 FAX:- 860 565 0600

DATR: May.18/05

P.O. BOX 31, DERBY TELEGRAMS - 'ROYCAR' DERBY TELEX - 37645 TELEPHONE:- 44 (0) 1332 242424 FAX:- 44 (0) 1332 249936

V2500-A1/A5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits Revision 1 to Service Bulletin EV2500-70-0347

<u>Document History</u>

Service Bulletin Revision Status Supplement Revision Status Initial Issue Jun.23/94

Bulletin Revision 1

Remove Incorporate Reason for change
All pages of the Page 1 and 2 of the To revise Effectivity and
Service Bulletin Service Bulletin Material Information.

V2500-ENG-70-0347

Printed in Great Britain

Printed in Great Britai

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin following incorporation of Revision 1 are as follows:

<u>Page</u>	Revision Number	Revision Date
Bulletin		
	_	
R 1	1	May 18/05
R 2	1	May 18/05



SERVICE BULLETIN

STANDARD PRACTICES - ENGINE - MAIN GEARBOX ASSEMBLY - TO ANNOUNCE THE AVAILABILITY OF NEW OIL SCAVENGE TUBE ASSEMBLIES

1. Planning Information

A. Effectivity

Printed in Great Britain

- (1) Airbus A319
- V2522-A5, V2524-A5 Engines prior to Serial No. V10010
- R (2) Airbus A319CJ
- V2527M-A5 Engines prior to Serial No. V10010 R
- R (3) Airbus A320
- R (a) V2500-A1 Engines prior to Serial No. V0362
- R (b) V2527-A5, V2527E-A5 Engines prior to Serial No. V10010
 - (4) Airbus A321
- R V2530-A5 Engines prior to Serial No. V10010

B. Reason

Provide steel oil scavenge tube assemblies.

C. Compliance

Caregory Code 7

Accomplish when supply of superseded parts has been depleted.

D. Approval

The part number changes and/or part modification described in Section 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA APPROVED for the Engine Models listed.

E. References

Internal Reference No. EC92VF003 and EC92VF003A R

F. General Information

The material information Section of this Bulletin provides the current information concerning spare parts availability.

Jun 23/94 R May. 18/05 V2500-ENG-70-0



SERVICE BULLETIN

2. <u>Material Information</u>

A. The kit required consists of the following parts:

None.

B. New production parts:

None.

C. Parts affected by this Bulletin:

V2500-A1 and A5 Engines

79-22-48

R

FIG ITEM	NEW PART	QTY	PART TITLE	OLD PART	INSTR DISP
NO.	NO.			NO.	
01110	4B0306	1	.Tube, A/O Oil	4B0215	(A)(B)(C)
02110	4B0307	1	.Tube, A/O Oil	4B0216	(A)(B)(C)
03100	4B0309	1	.Tube, A/O Oil	4B7248	(A)(B)(C)
05500	4B0308	1	.Tube, A/O Oil	4B2262	(A)(B)(D)
05510	_	3	.Bolt Machine Double Hex	4W0165	(B)(D)
05520	_	3	.Washer Flat	MS9321-10	(B)(D)
05530	4P0125	1	.Packing	AS3209 -217	(A)(B)(D)
05555	4P7253	1	.Collar	-	(A)(B)(D)

D. <u>Instructions disposition codes:</u>

- (A) New part is currently available.
- (B) Old part will be available until the existent stock is depleted.
- (C) Old and new parts are fully interchangeable, both physically and functionally.
- (D) Old and new parts coded (D) are interchangeable in complete sets.

3. Accomplish Instructions

None.

V2500-ENG-70-0347