

# **SERVICE BULLETIN**

Mar. 12/99

Subject: Transmittal of Revision 1 to Service Bulletin V2500-ENG-70-0417.

## Service Bulletin Revision History:

Event Date

Initial Issue Sep. 28/99. Revision 1 Mar. 12/99.

## Reason for Revision:

- (1) Correct SB Number in Footer.
- (2) Layout changes to 2. Material Information.

## Effect on Past Compliance:


None.

## List of Effective Pages:

Page No. Revision No. Effective Date

1 to 4 1 Mar. 12/99.

V2500-ENG-70-0417



# **SERVICE BULLETIN**

INFORMATION - ANNOUNCEMENT OF REPAIR PARTS FOR REPAIR OF THE ACTUATING RINGS FOR THE STAGE-4 AND 5 OF THE HP COMPRESSOR

#### **MODEL APPLICATION**

V2522-A5

V2524-A5

V2527-A5

V2527E-A5

V2530-A5

V2525-D5

V2528-D5

### **BULLETIN INDEX LOCATOR**

72-41-00

Compliance Category Code

Internal Reference No.

N/A


EC89VR836A, 90VR714A

Sep. 25/98

R Revision 1 Mar. 12/99

V2500-ENG-70-0417

Page 1 of 4



# SERVICE BULLETIN

# INFORMATION - ANNOUNCEMENT OF REPAIR PARTS FOR REPAIR OF THE ACTUATING RINGS FOR THE STAGE-4 AND 5 OF THE HP COMPRESSOR

## 1. Planning Information

#### A. Effectivity

- (1) Aircraft
  - (a) Airbus A319
  - (b) Airbus A320
  - (c) Airbus A321
  - (d) Boeing Douglas Product Division MD-90
- (2) Engines
  - (a) V2522-A5 Engines
  - (b) V2524-A5 Engines
  - (c) V2527-A5 Engines
  - (d) V2527E-A5 Engines
  - (e) V2530-A5 Engines
  - (f) V2525-D5 Engines
  - (g) V2528-D5 Engines


#### B. Reason

To announce the availability of new repair parts.

#### C. Compliance

For information only.

Sep. 25/98



## SERVICE BULLETIN

#### D. Approval

The part number transactions are shown in the Material Information section of this Service Bulletin. They obey the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine models listed.

#### E. References


IAE Engineering Change Numbers 89VR836A and 90VR714A.

#### F. General Information

- (1) The Material Information section of this Service Bulletin gives the latest information about the availability of the affected parts.
- (2) The new repair schemes introduced to the V2500 Engine Manual which require special spare parts to complete them are as follows:

ATA Ref No.	Repair Scheme	Title
72-41-34	VRS6202	HP Compressor Stage-5 Actuating Ring Connector Assembly - Replace the bushes
72-41-34	VRS6264	HP Compressor Stage-4 Actuating Ring Connector Assembly - Replace the bushes

(a) For the necessary special repair parts, refer to the Material Information section.



#### SERVICE BULLETIN

~		* ^ .·
•	NA atemai	Intormation
۷.	iviaiciiai	Information

- R A. Modification Kits necessary for this Service bulletin:
- R None.
- R B. Parts affected by this Service Bulletin:

NEW	QTY	EST'D	PART TITLE	OLD	INSTR
PART No.		UNIT		PART No.	DISP
(ATA No.)		PRICE (\$)		(IPC No.)	

(1) The special repair part that follows is necessary to do repair VRS6264:

UP10815	A/R	Bush	-	(A)
(72-41-34)			(04-220)	, ,

(2) The special repair part that follows is necessary for repair VRS 6206:

UP10815	A/R	Bush	UP10815	(B)
(72-41-34)			(05-220)	` '

NOTE: The unit prices if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE price catalogue or contact IAE's spare part sales department.

## R C. Instruction/Disposition Codes

- (1) (A) New part is available for repair of the Stage 4 actuator ring of the HP Compressor.
- (2) (B) New part is available for repair of the Stage 4 actuator ring of the HP Compressor.