



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: Apr. 7/09

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

Printed in Great Britain

V2500-A5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits the Revision 1 of Service Bulletin V2500-ENG-70-0487

Document History

Service Bulletin Revision Status
Initial Issue Sep. 1/96

Service Bulletin Revision 1

Remove	Incorporate	Reason for change
All pages of the Service Bulletin	Pages 1 to 4 of the Service Bulletin	To update the Material Information section.

V2500-ENG-70-0487
Transmittal - Page 1 of 1

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

INFORMATION – ENGINE – TO ANNOUNCE THE AVAILABILITY OF A NEW CORE SERVICE AND FIRE
DETECTION HARNESS

1. Planning Information

A. Effectivity

- (1) Airbus A319
 - (a) V2522-A5, V2524-A5, V2527M-A5 Engines.
- (2) Airbus A320
 - (a) V2524-A5, V2527-A5, V2527E-A5 Engines.
- (3) Airbus A321
 - (a) V2530-A5, V2533-A5 Engines.

B. Reason

- (1) To announce the availability of a new core service and fire detection harness.

C. Compliance

- (1) Category Code 7.
 - Accomplish when supply of superseded parts has been depleted.

D. Approval

- (1) The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organization Approval No. EASA.21J.031.

The authorizing IAE document is EC 93VN077.

E. References

- (1) Internal Reference No.:
 - IAE Engineering Change No. 93VN077.
- (2) ATA Locators – 71-52-41 and 71-52-42.

F. General Information

- (1) Part numbers changed due to the introduction of an angled Backshell to the Core Services and Fire Detection Harnesses.
- (2) The Material Information portion of this General Service Bulletin provides the latest information concerning the availability of the new Harnesses and Backshell.
- (3) Publications affected.

- R (a) The IAE V2500-A5 Engine Illustrated Parts Catalogues will be revised to include the new parts. See "Material Information" section for ATA Locations.
- R (b) The IAE V2500-A5 Engine Manual (E-V2500-1IA) will be revised, to add
R the new parts.
- R (c) The Airbus A319/A320/A321 Aircraft Maintenance Manuals will be
R revised, to add the new parts.

2. Material Information

A. Part Prices:

Not applicable.

B. Parts affected by this Service Bulletin:

Applicability: For all V2500-A5 Engines

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
71-52-41						
	01-005 745-5967 -509	1	.Harness, Core Services	-	745-5967 -507	(A) (S1)
R	02-010 745-5861 -503	REF	..Harness, Fire Detection	-	745-5861 -501	(A) (S1)
	02-015 387AH008 M1204A2	1	..Backshell, angled	-	387AS008 M1204A2	(A) (S1)
R	71-52-42					
R	01-005 745-5862 -501	1	.Harness, Core Services	-	740-5868 -507	(A) (S1)
R	01-100 387AH008 M1204A2	1	..Backshell, angled	-	387AS008 M1204A2	(A) (S1)

C. Instruction/Disposition Codes:

R (A) New part is currently available.

R (S1) Old part number may be used only where old part number was installed. New
R part number is acceptable replacement for the old or new part number.

3. Accomplishment Instructions

None.