



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE THE
AVAILABILITY OF REPAIR PART TO SUPPORT THE REPAIR OF REAR FAIRING ASSEMBLIES -
CATEGORY CODE NA - MOD.ENG-70-0511

A. Effectivity

- (1) Aircraft: (a) Airbus A320
(b) Airbus A321
- (2) Engine: (a) V2500-A1 Engines

B. Reason

To announce the availability of the newly released Repair Part by changing the spareability code from not spareable to potential spare for overhaul uses only.

C. Compliance

For information only.

D. Approval

The part number transactions shown under the Material Information portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

- (1) Internal Reference No.
ECM87VJ076-04

F. General Information

- (1) The Repair Scheme has been introduced on the V2500 Engine Manual which requires the special Repair Part for its accomplishment.

ATA No. -----	Repair Scheme -----	Title -----
72-32-86	VRS1416	Replace the strip seal of the rear fairing assembly

- (2) The spareability coding for the strip seal, part number 5A1255 item number 01-130 changes from not spareable to potential spare for overhaul uses only.

V2500-ENG-70-0511



International Aero Engines
INFORMATION BULLETIN

- (3) The Material Information portion of this Bulletin provides the latest information concerning the availability of the special Repair Part required.
- (4) V2500 Engine Illustrated Parts Catalog (S-V2500-1IA), Chapter/Section 72-32-86 will be revised to incorporate the new part.

G. Material Information

The following special Repair Part are required to accomplish the Repair Scheme VRS1416.

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
5A1255 (72-32-86)	A/R		..Seal,Strip	- (01-130)	(A)(B)

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's Spare Parts Sales Department.

H. Supply Status Code Statements:

- (A) New part is currently available.
- (B) Quantity of part is as required and it must be used by cut.

Printed in Great Britain

V2500-ENG-70-0511