



International Aero Engines INFORMATION BULLETIN

INFORMATION – AIR – TO ANNOUNCE THE AVAILABILITY OF NEW ACTIVE CLEARANCE
CONTROL (ACC) SUPPORTS AND CLAMPS IN X10 MATERIAL

MODEL APPLICATION

V2500-A1
V2522-A5
V2524-A5
V2527-A5
V2530-A5
V2525-D5
V2528-D5

BULLETIN INDEX LOCATOR

75-24-00

Compliance Category Code


7

Internal Reference No.

93VM022

Jul.14/98

V2500-ENG-70-0563
Page 1 of 4



International Aero Engines INFORMATION BULLETIN

INFORMATION – AIR – TO ANNOUNCE THE AVAILABILITY OF NEW ACTIVE CLEARANCE CONTROL (ACC) SUPPORTS AND CLAMPS IN X10 MATERIAL

A. Effectivity

- (1) Aircraft: Airbus A320
Airbus A321
Airbus A319
Mc Donnell Douglas MD90
- (2) Engine: V2500-A1 Engines
V2522-A5 Engines
V2524-A5 Engines
V2527-A5 Engines
V2530-A5 Engines
V2525-D5 Engines
V2528-D5 Engines

B. Reason

- (1) To announce the availability of new ACC supports and clamps manufactured from X10 material

C. Compliance

Category Code 7

Accomplish this Service Bulletin when there are no original parts remaining.

D. Approval

The partnumber transaction are given in the Material Information section of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model listed.

E. Reference

Engineering Change No. 93VM022

F. General Information

The Material Information section of this Service Bulletin gives the latest information about the affected parts.




International Aero Engines INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty.	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
Applicability for D5 engines only affected by this Service Bulletin:					
3A2368 (75-24-49)	1		Support, Assy	3A2007 (01800)	(A) (B) (1)
Applicability for A1, A5 and D5 engines affected by this Service Bulletin:					
3A2350 (75-24-49)	1		Support, Assy (No. 2)	3A1749 (02-490)	(A) (B) (1)
3A2343 (75-24-49)	1		Clamp, A/O half loop	3A1742 (02-560)	(A) (B) (1)
3A2355 (75-24-49)	1		Support, Assy (No. 3)	3A1752 (02-720)	(A) (B) (1)
3A2343 (75-24-49)	1		Clamp, A/O half loop	3A1742 (02-750)	(A) (B) (1)
3A2365 (75-24-49)	1		Support, Assy (No. 6)	3A2320 (03-490)	(A) (B) (1)
3A2343 (75-24-49)	1		Clamp, A/O half loop	3A1742 (03-560)	(A) (B) (1)
3A2362 (75-24-49)	1		Support, Assy (No. 5)	3A1759 (03-720)	(A) (B) (1)
3A2343 (75-24-49)	1		Clamp, A/O half loop	3A1742 (03-740)	(A) (B) (1)
3A2337 (75-24-49)	1		Support, Assy (No. 1)	3A1745 (04-010)	(A) (B) (1)
3A2343 (75-24-49)	1		Clamp, A/O half loop	3A1742 (04-200)	(A) (B) (1)
3A2349 (75-24-49)	1		Clamp, A/O half loop	3A1744 (04-215)	(A) (B) (1)
3A2358 (75-24-49)	1		Support, Assy (No. 4)	3A1755 (04-410)	(A) (B) (1)
3A2343 (75-24-49)	1		Clamp, A/O half loop	3A1742 (04-610)	(A) (B) (1)
3A2349 (75-24-49)	1		Clamp, A/O half loop	3A1744 (04-620)	(A) (B) (1)

Printed in Great Britain



International Aero Engines INFORMATION BULLETIN

H. Instruction/Disposition Code Statement

- (A) New part is available for sale
- (B) Old part will continue to be supplied until the existing stock is exhausted
- (1) Old and new parts are fully interchangeable

NOTE: The estimated 1998 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain