

International Aero Engines
SERVICE BULLETIN

Mar. 5/99

Subject: Transmittal of Revision 2 to Service Bulletin V2500-ENG-70-0573.

Service Bulletin Revision History:

Event	Date
Initial Issue	Nov. 21/97.
Revision 1	Sept. 4/98.
Revision 2	Mar. 5/99.

Reason for Revision:

- (1) Correct header on pages 1 and 2.
- (2) Change engine Serial numbers at 1. A. (2) (b) to (g).
- (3) Editorial Changes.

Effect on Past Compliance:


None.

List of Effective Pages:

Page No.	Revision No.	Effective Date
1 to 4	Revision 2	Mar. 5/99.

V2500-ENG-70-0573

Transmittal
Page 1 of 1



International Aero Engines
INFORMATION BULLETIN

INFORMATION - INTRODUCTION OF ALTERNATIVE TCA PIPE BRACKETS

MODEL APPLICATION

V2500-A1
V2522-A5
V2524-A5
V2527-A5
V2527E-A5
V2530-A5
V2533-A5

BULLETIN INDEX LOCATOR

R


73-13-00

Compliance Category Code

N/A

Internal reference No.

EC97VR007



International Aero Engines
INFORMATION BULLETIN

INFORMATION - INTRODUCTION OF ALTERNATIVE TCA PIPE BRACKETS

1. Planning Information

A. Effectivity

(1) Aircraft:

(a) Airbus A319.

(b) Airbus A320.

(c) Airbus A321.

(2) Engines:

(a) V2500-A1 Engines prior to Serial No. V0362.

R (b) V2522-A5 Engines prior to Serial No. V10425.

R (c) V2524-A5 Engines prior to Serial No. V10425.

R (d) V2527-A5 Engines prior to Serial No. V10425.

R (e) V2527E-A5 Engines prior to Serial No. V10425.

R (f) V2530-A5 Engines prior to Serial No. V10425.

R (g) V2533-A5 Engines prior to Serial No. V10425.

B. Reason


To announce the introduction of alternative support brackets for the Turbine Cooling Air (TCA) Pipe.

C. Compliance

For information only.

D. Approval

The part number transactions are given in the Material Information section of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine models listed.



International Aero Engines
INFORMATION BULLETIN

E. References


IAE Engineering Change No. 97VR007.

F. General Information

The Material Information section gives the latest information about the availability of the affected parts.

R G. Other Publications Affected.

R (1) Illustrated Parts Catalogue (IPC), Chapter/Section 73-13-41.



International Aero Engines
INFORMATION BULLETIN

R 2. Material Information

R A. Kits necessary for this Service Bulletin:

None.

R B. Parts affected by this Service Bulletin:

NEW PART No. (ATA No.)	QTY	EST'D UNIT PRICE (\$)	PART TITLE	OLD PART No. (IPC No.)	INSTR DISP
6A6559 (73-13-41)	1		Bracket - TCA No. 1	- (01-120)	(A) (B)
6A6558 (73-13-41)	1		Bracket - TCA No. 2	- (01-180)	(A) (C)
6A6557 (73-13-41)	1		Bracket - TCA No. 3	- (01-340)	(A) (E)
R 6A6556 (73-13-41)	1		Bracket - TCA No. 4	- (01-400)	(A) (F)

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only.
For actual prices, refer to IAE Price Catalog or contact IAE's spare parts sales department.

C. Instruction Disposition Codes:

- (1) (A) Additional.
- (2) (B) Alternative to 2A1466.
- (3) (C) Alternative to 2A1436.
- (4) (E) Alternative to 2A1479.
- (5) (F) Alternative to 2A1488.