

International Aero Engines
INFORMATION BULLETIN

Mar. 5/99

Subject: Transmittal of Revision 1 to Service Bulletin V2500-ENG-70-0574.

Service Bulletin Revision History:

Event	Date
Initial Issue	Dec. 19/97.
Revision 1	Mar. 5/99.

Reason for Revision:

- (1) Change charts in Section 1 to illustrations.
- (2) Editorial changes

Effect on Past Compliance:


None.

List of Effective Pages:

Page No.	Revision No.	Effective Date
1 to 5	Revision 1	Mar. 5/99.

V2500-ENG-70-0574

Transmittal
Page 1 of 1



International Aero Engines

INFORMATION BULLETIN

INFORMATION - INTRODUCTION OF ALTERNATIVE ACC AND ACAC MOUNTING BRACKETS AND CONTROL LINKS

MODEL APPLICATION

V2500-A1
V2522-A5
V2524-A5
V2527-A5
V2527E-A5
V2530-A5
V2533-A5

BULLETIN INDEX LOCATOR

R


72-00-00

Compliance Category Code

N/A

Internal reference No.

EC97VR008



International Aero Engines

INFORMATION BULLETIN

INFORMATION - INTRODUCTION OF ALTERNATIVE ACC AND ACAC MOUNTING BRACKETS AND CONTROL LINKS

1. Planning Information

A. Effectivity

(1) Aircraft:

(a) Airbus A319.

(b) Airbus A320.

(c) Airbus A321.

(2) Engines:

- R (a) V2500-A1 Engines prior to Serial No. V0362.
- R (b) V2522-A5 Engines prior to Serial No. V10425.
- R (c) V2524-A5 Engines prior to Serial No. V10425.
- R (d) V2527-A5 Engines prior to Serial No. V10425.
- R (e) V2527E-A5 Engines prior to Serial No. V10425.
- R (f) V2530-A5 Engines prior to Serial No. V10425.
- R (g) V2533-A5 Engines prior to Serial No. V10425.

B. Reason


To announce the introduction of alternative ACC and ACAC mounting brackets.

C. Compliance

For information only.

D. Approval

The part number transactions are given in the Material Information section of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine models listed.



International Aero Engines
INFORMATION BULLETIN

E. References


IAE Engineering Change No. 97VR008.

F. General Information

The Material Information section gives the latest information about the availability of the affected parts.

R G. Other Publications Affected.

R (1) Illustrated Parts Catalogue (IPC), Chapter/Sections 72-00-50, 72-40-00, 75-24-47 and 75-24-51.



International Aero Engines
INFORMATION BULLETIN

R 2. Material Information

R A. Kits necessary for this Service Bulletin:

None.

R B. Parts affected by this Service Bulletin:

NEW PART No. (ATA No.)	QTY	EST'D UNIT PRICE (\$)	PART TITLE	OLD PART No. (IPC No.)	INSTR DISP
6A6594 (72-00-50)	1		Bracket - Rear, ACAC	- (01-330)	(A) (B)
6A6589 (72-40-00)	1		Bracket - Front (RH), ACAC	- (05-300)	(A) (C)
6A6590 (72-40-00)	1		Bracket - Front (LH), ACAC	- (05-340)	(A) (E)
6A6591 (72-40-00)	1		Bracket assembly - ACC, LPT Valve	- (05-500)	(A) (F)
6A6592 (72-40-00)	1		Bracket - ACC HPT Valve	- (05-550)	(A) (G)
6A6593 (72-40-00)	1		Bracket - ACC HPT Valve	- (05-570)	(A) (H)
6A6587 (75-24-47)	1		Bracket assembly - ACC LPT Valve	- (01-500)	(A) (J)
6A6588 (75-24-47)	1		Link - ACC, LPT Valve	- (01-550)	(A) (K)
6A6585 (75-24-51)	1		Link Assembly - ACC HPT Valve	- (02-100)	(A) (L)
6A6586 (75-24-51)	1		Link Assembly - ACC HPT Valve	- (02-250)	(A) (M)

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only.
For actual prices, refer to IAE Price Catalog or contact IAE's spare parts sales department.



International Aero Engines

INFORMATION BULLETIN

C. Instruction Disposition Codes:

- R (1) (A) Additional.
- R (2) (B) Alternative to 5T8123 and 5T8100.
- R (3) (C) Alternative to 5T8121 and 5T8098.
- R (4) (E) Alternative to 5T8122 and 5T8099.
- R (5) (F) Alternative to 6A6487.
- R (6) (G) Alternative to 5W2241.
- R (7) (H) Alternative to 6A6489.
- R (8) (J) Alternative to 6A6486.
- R (9) (K) Alternative to 5W2058.
- R (10) (L) Alternative to 6A6490.
- R (11) (M) Alternative to 6A6488.