



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - MAIN GEARBOX ASSEMBLY GEAR
ASSEMBLY DRIVE PMA MODIFICATION - CATEGORY CODE 6 - MOD.ENG-70-0585

1. Planning Information

A. Effectivity

- (1) Aircraft: Airbus A319 - A320 - A321
McDonnell Douglas MD-90
- (2) Engine: V2500-A1
V2522-A5
V2524-A5
V2527-A5
V2530-A5
V2525-D5
V2528-D5

B. Reason

To change the part number of the PMA Drive Gear Assembly to reflect the revised bolt introduced by SB ENG-73-0093 (EC96VR005).

C. Compliance

For information only

D. Approval

The part number transactions given in the material information section obeys the applicable Federal Aviation Regulation and are FAA-APPROVED for the engine model listed.

E. Reference

- (1) Internal Reference No.


EC95VR005B.

F. General Information

- (1) The Material Information section of this Service Bulletin gives the latest information about the Gear Assembly Drive PMA Modification.
- (2) Other Publications Affected

V2500 Engine Illustrated Parts Catalog (IPC) (S-V2500-1IA, S-V2500-2IA, S-V2500-3IA) Chapter/Section 72-60-33.

V2500-ENG-70-0585



International Aero Engines
INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
4A0322 (72-60-33)	1		Gear, Assembly Drive PMA	4A0295 (01-001)	(A)(1)
4A2176 (72-60-33)	1		Gear, Assembly Drive PMA	4A2175 (01-001)	(A)(1)

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's Spare Parts Sales Department.

H. Instructions Disposition Codes

- (A) Old part to be re-identified with new part number
- (1) Old and new parts are not interchangeable.

Printed in Great Britain

V2500-ENG-70-0585