



International Aero Engines SERVICE BULLETIN

Date: Jan.08/00

Subject: Transmittal of Revision 1 to Service Bulletin
No.V2500-ENG-70-0605

Service Bulletin Revision History:

Event	Date
Basic Issue	Oct.19/98
Revision 1	Jan.08/00

Reason for Issuance of Revision:

- (1) To delete engine model, V2500-A1, in Effectivity.
- (2) To add information about Cleaning, Inspection and Repair in General Information.

Effect on Past Compliance:


None

List of Effective Pages:

Bulletin Page No.	Rev. No.	Effective Date
R 1 to 3	1	Jan.08/00

V2500-ENG-70-0605

Transmittal
Page 1 of 1



International Aero Engines INFORMATION BULLETIN

INFORMATION - LP TURBINE - TO DELETE THE TRIM BALANCE SLOT
OF THE LP TURBINE SHAFT

MODEL APPLICATION

V2522-A5
V2524-A5
V2527-A5
V2527E4-A5
V2530-A5
V2533-A5
V2525-D5
V2528-D5

BULLETIN INDEX LOCATOR

72-50-00

Compliance Category Code

7

Internal Reference No.

EC97VJ017

Oct.19/98

R Revision 1 Jan.08/00

V2500-ENG-70-0605

Page 1 of 3



International Aero Engines INFORMATION BULLETIN

INFORMATION - LP TURBINE - TO DELETE THE TRIM BALANCE SLOT
OF THE LP TURBINE SHAFT

A. Effectivity

(1) Aircraft:

- (a) Airbus A319
- (b) Airbus A320
- (c) Airbus A321
- (d) Boeing-Douglas Product Division MD-90

R

(2) Engine:

- (a) V2522-A5 Engines
- (b) V2524-A5 Engines
- (c) V2527-A5 Engines
- (d) V2527E-A5 Engines
- (e) V2530-A5 Engines
- (f) V2533-A5 Engines
- (g) V2525-D5 Engines
- (h) V2528-D5 Engines

B. Reason

To announce the availability of a new LP Turbine Shaft.

C. Compliance

Category Code 7

Accomplish when there are no original parts remaining.

D. Approval

The part number transaction are given in the Material Information section of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine models listed.

E. Reference


IAE Engineering Change No. 97VJ017

Oct.19/98

Revision 1 Jan.08/00

V2500-ENG-70-0605

Page 2



International Aero Engines INFORMATION BULLETIN

F. General Information

- (1) The Material Information section of this Service Bulletin gives the latest information about the availability of the new LP Turbine shaft.
- (2) V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-50-41 will be revised to incorporate new part number.
- R (3) V2500 Engine Manual (E-V2500-1IA and E-V2500-3IA), Chapter/Section
R 72-50-41, Cleaning-03, Config-01, Inspection/Check-03, Config-01,
R Repair 001(VRS1492), Repair 002(VRS1493), Repair 003(VRS1491),
R Repair 004(VRS1498), Repair 005(VRS1499), Repair 006(VRS1496),
R Repair 007(VRS1497), Repair 008(VRS1502), Repair 011(VRS1495) and
R Repair 012(VRS1494) will be revised to incorporate new part
R number.
- (4) For effect on declared life, see V2500 Time Limits Manuals
(T-V2500-1IA and T-V2500-3IA), Chapter/Section 5-10-01, Group A
Parts Lives

G. Material Information

New	Est'd		Old	
Part No.	Unit		Part No.	Instr.
(ATA No.)	Qty	Price(\$)	Keyword	(IPC No.) /Disp.
5A1762	1		.Shaft, LP	5A1732 (A)(B)(S1)
(72-50-41)			Turbine	(01-200)

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's spare parts sales department.

H. Instruction/Disposition Codes

- (A) New part is available.
(B) Old part is no available.
(S1) Old and New parts are freely and fully interchangeable, both physically and functionally.

