



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE THE AVAILABILITY
OF REPAIR PARTS TO SUPPORT THE REPAIR OF FAN FRAME ASSEMBLIES

MODEL APPLICATION

V2525-D5
V2528-D5

BULLETIN INDEX LOCATOR

72-32-00

Compliance Category Code

Not applicable

Internal Reference No.

ECMD5723203-04

Oct.01/98

V2500- ENG-70-0632

Page 1 of 3



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE THE AVAILABILITY
OF REPAIR PARTS TO SUPPORT THE REPAIR OF FAN FRAME ASSEMBLIES

A. Effectivity

(1) Aircraft:

(a) Boeing-Douglas Product Division MD-90

(2) Engine:

(a) V2525-D5 Engines

(b) V2528-D5 Engines

B. Reason

To announce the availability of the newly released Repair Parts by changing the spareability code from "not spareable" to "potential spare for overhaul uses only".

C. Compliance

For information only.

D. Approval

The part number transactions are given in the Material Information section of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model listed.

E. Reference

IAE Engineering Change No.D5723203-04

F. General Information

- (1) New Repair Schemes will be introduced, in November 1998, into the V2500 Engine Manual which requires the special Repair Parts for its accomplishment.



International Aero Engines INFORMATION BULLETIN

<u>ATA No.</u>	<u>Repair Scheme</u>	<u>Title</u>
72-32-03	VRS1786	Intermediate structure fan frame - Replace the wire thread insert

- (2) The spareability coding for the inserts, part number AGS3732 item number 03-115, changes from "not spareable" to "potential spare for overhaul uses only".
- (3) The Material Information section of this Service Bulletin gives the latest information about the availability of the special Repair Parts necessary.
- (4) V2500 Engine Illustrated Parts Catalogs (S-V2500-3IA), Chapter/Section 72-32-03 will be revised to incorporate the new parts.

G. Material Information

The following special Repair Parts are required to accomplish the Repair Scheme VRS1786.

New Part No. (ATA No.)	Qty	Est'd Unit Price(\$)	Keyword	Old Part No. (IPC No.)	Instr. Disp.
AGS3732 (72-32-03)	18		..Insert, Screw Tread	- (03-115)	(A)

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's spare parts sales department.

H. Instruction/Disposition Codes

(A) New part is currently available.

