



400 MAIN STREET, MAIL STOP 121-10  
EAST HARTFORD, CT 06108, USA.  
TELEPHONE:- 860 565 5515  
FAX:- 860 565 0600

DATE: May.11/04

P.O. BOX 31, DERBY  
TELEGRAMS - 'ROYCAR' DERBY  
TELEX - 37645  
TELEPHONE:- 44 (0) 1332 242424  
FAX:- 44 (0) 1332 249936

## V2500-A1/A5 SERIES PROPULSION SYSTEMS INFORMATION SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin EV2500-70-0742 and the Initial Issue of the Supplement

### Bulletin Initial Issue

Remove	Incorporate	Reason for change
	Pages 1 to 3 of the	Initial issue
	Service Bulletin	

### Supplement Initial Issue

Remove	Incorporate	Reason for change
	Page 1	Initial issue

# V2500-ENG-70-0742

Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED  
If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England  
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
Bulletin		
1		May 11/04
2		May 11/04
3		May 11/04
Supplement		
1		May 11/04

Printed in Great Britain



INFORMATION – ENGINE – TO ANNOUNCE THE AVAILABILITY OF A SHORTER CLAMP STACK BOLT AT  
THE GENERAL SERVICES PYLON INTERFACE HARNESS LIMB

1. Planning Information

A. Effectivity

- (1) Airbus A319
  - (a) V2522-A5, V2524-A5, V2527M-A5 Engines.
- (2) Airbus A320
  - (a) V2500-A1 Engines.
  - (b) V2527-A5, V2527E-A5 Engines.
- (3) Airbus A321
  - (a) V2530-A5, V2533-A5 Engines.

B. Reason

To announce the availability of a shorter clamp stack bolt at Clipping Point CP 0876. This will reduce the possibility of fouling with the general services pylon interface harness limb.

C. Compliance

Category Code 7

Accomplish when the supply of superseded parts has been depleted.

D. Approval

The part number transaction shown under the Material Information section of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and is FAA-APPROVED for the Engine Model listed.

E. References

- (1) IAE Engineering Change No. 03VN765 issue 1.
- (2) Shorts modification No. D1140.
- (3) ATA Locator – 77-32-43.



F. General Information

- (1) The existing bolt, on the clamp stack may foul the limb of the general services pylon interface harness.
- (2) Other publications affected
  - (a) V2500-A1/A5 Engine Illustrated Parts Catalogs will be revised to include the new bolt. See 'Material Information' section for ATA locations.
  - (b) V2500-A1/A5 Component Maintenance Manuals will be revised to include the new bolt. See 'Material Information' section for ATA locations.

Printed in Great Britain



## 2. Material Information

### A. Parts affected by this bulletin:

77-32-43

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
01110	4W0103 (AS21408)	1	.Bolt, 0.190in Dia.	-	4W0105 (AS21410)	(A)

### B. Instructions/Disposition Code Statements:

(A) New parts are available.

## 3. Accomplishment Instructions

A. None.





INFORMATION - ENGINE - TO ANNOUNCE THE AVAILABILITY OF A SHORTER CLAMP STACK BOLT AT  
THE GENERAL SERVICES PYLON INTERFACE HARNESS LIMB

SUPPLEMENT - PRICES AND AVAILABILITY

The prices if shown are for estimating purposes only and as such are given in good faith, without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current price catalogue for current prices.

1. Modification Kit

Not applicable. Parts supplied as single line items

2. New Production Parts

Part No.	Desc.	Unit Price US Dollars
4W0103 (AS21408)	Bolt	5.00

