



International Aero Engines INFORMATION BULLETIN

**INFORMATION - ENGINE - LP COMPRESSOR - INTRODUCTION OF AN INTERMEDIATE
STRUCTURE FRONT FAIRING ASSEMBLY WITH REVISED MATERIAL**

MODEL APPLICATION

V2500-A1

BULLETIN INDEX LOCATOR

72-32-00

Compliance Category Code

7

Internal Reference No.

EC98VJ004

Mar.29/00

V2500-ENG-70-0788

Page 1 of 3



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - LP COMPRESSOR - INTRODUCTION OF AN INTERMEDIATE STRUCTURE FRONT FAIRING ASSEMBLY WITH REVISED MATERIAL

A. Effectivity

(1) Aircraft:

(a) Airbus A320

(2) Engine:

(a) V2500-A1 Engines

B. Reason

To introduce an intermediate structure front fairing assembly with revised material.

C. Compliance

Category Code 7

Accomplish when there are no original parts remaining.

D. Approval

The part number transactions are given in the Material Information section of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model listed.

E. Reference

IAE Engineering Change No. 98VJ004

F. General Information

(1) The Material Information section of this Service Bulletin gives the latest information about the availability of the front fairing assembly.


(2) Other Publications Affected

(a) V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-32-93 will be revised to add the new part number.

Mar.29/00

V2500-ENG-70-0788

Page 2



International Aero Engines INFORMATION BULLETIN

- (b) V2500 Engine Manual(E-V2500-1IA), Chapter/Section 72-32-93, Cleaning-01, Config-01 will be revised to add new part number.
- (c) V2500 Engine Manual(E-V2500-1IA), Chapter/Section 72-32-93, Inspection/Check-01, Config-03 will be introduced to include new procedure.
- (d) Repair Scheme will be revised to add new part number in the V2500 Engine Manual(E-V2500-1IA).

<u>ATA Ref No.</u>	<u>Repair Scheme</u>	<u>Title</u>
72-32-93	VRS1445	INTERMEDIATE STRUCTURE FRONT FAIRING - REPLACE THE RUBBER CUSHION
72-32-93	VRS1446	INTERMEDIATE STRUCTURE FRONT FAIRING - REPLACE THE RUBBER SEAL

- (e) New Repair Scheme will be introduced to include new procedure in the V2500 Engine Manual(E-V2500-1IA).

<u>ATA Ref No.</u>	<u>Repair Scheme</u>	<u>Title</u>
72-32-93	VRS1448	INTERMEDIATE STRUCTURE FRONT FAIRING - REPLACE THE WASHER

G. Material Information

New	Est'd		Old	
Part No.	Unit		Part No.	Instr.
(ATA No.)	Qty	Price(\$)	Keyword	(IPC No.) /Disp.
5A1830 (72-32-93)	4		.FARING A/O FRONT	5A0836 (A) (B) (S1) (01-200)

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's spare parts sales department.

H. Instruction/Disposition Codes

- (A) New part is currently available.
- (B) Old part is no longer available.
- (S1) Old and New parts are freely and fully interchangeable, both physically and functionally.

